

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

VEHICLE NO:SKH 1195S

QTY	PARTICULAR
1 PCS	BONNET <i>862.90</i>
1 PCS	BONNET INNER LOCK
1 PCS	BONNET RUBBER
1 PCS	BONNET INNER INSULATOR
1 SET	BONNET INNER INSULATOR CLIPS
2 PCS	BONNET HINGES @\$105.00
1 PCS	FRONT BUMPER <i>488.01</i>
1 PCS	FRONT BUMPER REINFORCEMENT
1 PCS	FRONT BUMPER LOWER COVER
2 PCS	FRONT BUMPER SIDE RETAINERS @\$65.10
1 PCS	FRONT BUMER CENTRE GRILLE
2 PCS	FRONT BUMPER FOG LAMPS @\$450.00 <i>225 x 2 = 650</i>
2 PCS	FRONT BUMPER FOG LAMP COVERS @\$86.50
1 PCS	FRONT BUMPER TOP RUBBER
1 PCS	FRONT BUMPER SPONGE
2 PCS	HEADLAMPS @\$1500.10 <i>225.10 x 2 = 1650.20</i>
1 PCS	FRONT GRILLE <i>397.10</i>
1 PCS	FRONT GRILLE LOGO
1 PCS	FRONT SUPPORT PANEL <i>845.01</i>
2 PCS	FRONT FENDERS @\$799.10 <i>622.01</i>
2 PCS	FRONT FENDER INNERSHIELDS @\$245.10 <i>188.20</i>
2 PCS	FRONT FENDER VVTI EMBLEMS @\$66.00
1 PCS	FRONT WHEEL HOUSING PANELS N/S
1 PCS	FRONT AIR CON CONDENSER
1 PCS	RADIATOR <i>1984.90</i>
1 PCS	RADIATOR FAN COWLING
1 PCS	RADIATOR FAN BLADE
1 PCS	RADIATOR FAN MOTOR
1 PCS	FUSE BOX
1 PCS	AIR DUCT
1 PCS	FRONT FENDER SIDE COVER N/S
1 PCS	WIPER GARNISH
1 PCS	FRONT WINDSCREEN
1 PCS	FRONT WINDSCREEN MOULDING
1 PCS	INLEF MANIFOLD
1 PCS	TROTTLER BODY AIR FLOW
1 PCS	ALTERNATOR
1 PCS	FRONT CHASSIS MEMBER N/S
1 PCS	ENGINE TOP COVER
1 PCS	FRONT SHOCK ABSORBER
1 PCS	FRONT LOWER ARM
1 PCS	FRONT KNUCKLE ARM
1 PCS	FRONT KNUCKLE ARM BEARING
2 PCS	ENGINE MOUNTINGS @\$395.10
1 PCS	AIR BAG DRIVER
1 PCS	AIR BAG SPIRAL SENSOR

Not Approved
2/11
10/12/19
2/5 @ 12.000
15-dm.

Buc	\$1,499.20	
twi	\$109.50	
ru	\$45.00	
To.1	\$243.67	
ru	\$50.00	
Bul	\$210.00	
7.5	\$523.01	
7.5	\$399.02	
7.5	\$248.20	
Bul	\$130.20	
To.1	\$102.30	
one/ SMO	\$900.00	
MS To.1	\$173.00	<i>120</i>
ru	\$66.50	
NT	\$195.30	<i>2</i>
MS SMO OKEN	\$3,000.20	
SNO	\$399.10	
ru	\$68.50	
twi	\$2,045.10	
MS Buc	\$1,598.20	<i>120</i>
MS To.1	\$490.20	<i>120</i>
MS	\$132.00	
Dis.ore	\$1,021.10	
Bul/Pan	\$1,485.00	
Bul/Pan	\$1,988.10	
one	\$223.45	
Bul	\$105.00	
FM	\$485.00	
one	\$866.01	
11	\$145.00	<i>X</i>
MS	\$85.50	
11	\$266.20	<i>X</i>
one	\$1,288.10	
ru	\$166.50	
one	\$1,025.10	
11	\$855.10	<i>X</i>
11	\$1,899.20	<i>X</i>
11	\$885.10	<i>X</i>
MS	\$315.00	
11	\$399.20	<i>X</i>
11	\$415.50	<i>X</i>
11	\$488.20	<i>X</i>
11	\$250.00	<i>X</i>
11	\$790.10	<i>X</i>
Actual	\$1,880.20	
Actual	\$295.10	

503

1 PCS
1 PCS
2 PCS
1 PCS

PASSENGER AIR BAG 2238.10
DASHBOARD
SEAT BELTS @\$850.00 645.10 x 2 = 1290.20
AIR BAG CONTROL UNIT 850.00

Actual
Total
Actual
Actual
\$2,680.10
\$859.50
\$1,700.00
\$1,029.30
\$36,519.86

P-24092-08
50%
12066.04

Best \$50.00 40 S.W.
M \$50.00 40 "
DD \$200.00 502/100"
M \$20.00 "
M \$50.00 30 "

1 PCS
1 PCS
1 PCS
1 PCS
1 BOL

S.NETT
FRONT LICENCE PLATE W/HOLDER
FRONT WINDSCREEN SEALANT
BATTERY
ERP BRACKET
RADIATOR COOLANT

LABOUR CHARGES

TO CHECK WIRING
TO SPRAY RUST PROOFING
TO CONDUCT WHEEL ALIGNMENT
TO REFILL AIR CON GAS
TO DISMANTLE & REFIX UNDERCARRIAGE
TO MOUNT VEHICLE ON CAR O-LINER
TO DISMANTLE & REPLACING FRONT WINDSCREEN
TO DISMANTLE & REPLACING FRONT AIR BAG SYSTEM
TO DISMANTLE & REPLACING FRONT DASHBOARD
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$80.00 30
\$180.00 100
11 \$120.00 X
\$120.00 100
11 \$180.00 X
11 \$380.00 X
\$150.00 120
\$380.00 200
\$380.00 260
\$2,000.00 1200
\$1,800.00 1100
TOTAL \$42,659.86

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-12066
S.W-230
L-3110
TK386.