



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19021759/Bpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 06-05-2020



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 6286J	Veh. Inspected	SJT 4378K
Policy No.	GA447921	Coverage (\$)	0.00
Claim No.	S9M029KK	Excess (\$)	0.00
Assign From		Assign Date	09/12/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA AXIO 1.5X A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	NZE1416098038	Colour	BLUE
Odometer	289530	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70 R14	DUNLOP	6 mm
L/H Front Tyre	185/70 R14	DUNLOP	6 mm
R/H Rear Tyre	185/70 R14	DUNLOP	6 mm
L/H Rear Tyre	185/70 R14	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	08/12/2019	Inspection Date	10/12/2019
Survey held at	TEAM AUTOPRO PTE LTD 160 Sin Ming Dr #01-14 Sin Ming AutoCity Singapore 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
-------------------------------------	------------------------