

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SH 9045U

DATE: 9. Dec. 2019

MAKE : HYUNDAI

MODEL : i40

DOA: 5. Dec. 2019

QBE

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper <i>X(R)</i>			\$553.00
10	Rear Bumper Clips <i>Xnn</i>		\$2.20	\$22.00
1	Rear Bumper Sponge <i>xnn</i>			\$103.50
1	Rear Bumper Reinforcement <i>xnn</i>			\$428.40
1	Rear Bumper Undercover <i>xnn</i>			\$228.00
<div data-bbox="235 556 673 913"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p> </div>				
SUB TOTAL				\$1,334.90
LESS 25%				\$333.73
DISCOUNTED TOTAL				\$1,001.17
1	Advertisement – Rear Bumper <i>rec</i>			\$50.00
2	Advertisement – Rear Fenders RH/LH <i>rec</i>		\$100.00	\$200.00
				Nett
				Nett
<div data-bbox="649 1155 1218 1533"> <p><i>Ram (LKK)</i> <i>9/12/19 1330 hrs</i> <i>Parasuram LKK auto.com</i> <i>88622778 HP</i> <i>45 aft repair photo</i> <i>2 repairs by</i></p> </div>				
Labour Charge				\$250.00
1	Panel Beating			\$300.00
1	Spray Painting Charge			\$250.00
1	Wiring Charge			\$50.00
1	Remove/refix Reverse Sensor			\$80.00
TOTAL LABOUR				\$680.00
ESTIMATE TOTAL				\$1,931.17
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

Larry Ng

\$286

\$200

xnn

kna