

Our Job Ref No : 305361888

Date : 10. Dec. 2019

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : RAMVehicle Reg No. : SH 9045UDate of Accident: 5. Dec. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: QBE GBA7151Y

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

**Final Lumpsum Repair cost****\$600.00**3. Estimated normal period for repairs: 2 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and  
finalized amountSignature : Name : Larry NgTel : 6214 8316Fax : 6546 8156Signature : Name : RamDate : 11/12/19

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## REPAIR ESTIMATE\*

VEHICLE NO : SH 9045U

**DATE: 9. Dec. 2019**

MAKE : HYUNDAI

DOA: 5. Dec. 2019

**QBE**

MODEL : i40

MODEL : i40		DUA: 31 Decr 2019		
Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper X(R)			\$553.00
10	Rear Bumper Clips X 7mm		\$2.20	\$22.00
1	Rear Bumper Sponge X 4m			\$103.50
1	Rear Bumper Reinforcement X 4m			\$428.40
1	Rear Bumper Undercover X 4m			\$228.00
<div><p>LKK Auto Consultants hereby notify the Repairer of the following:</p><ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul><p>Acknowledged by Repairer Signature: Date:</p></div> <div><p>SUB TOTAL LESS 25% DISCOUNTED TOTAL</p></div>				\$1,334.90
				\$333.73
				\$1,001.17
1	Advertisement – Rear Bumper ra —			\$50.00
2	Advertisement – Rear Fenders RH/LHnc —		\$100.00	\$200.00
<p>Ram (LKK)</p> <p>9/12/19 1330hrs</p> <p>Parasuram Lkkauto.com</p> <p>88622778 KP</p> <p>(L/S) aft repair photo</p> <p>2x repair hrs</p>				\$250.00
				\$300.00
				\$250.00
				\$50.00
				\$20 \$80.00
TOTAL LABOUR				\$680.00
ESTIMATE TOTAL				\$1,931.17
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				