

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : ALISON NG LI YING
932A HOUGANG AVE 9
#15-90
SINGAPORE 531932
TEL: 93671892
ATTN:
Your Ref No: SLP8769L
Claim Type: Third Party
Accident Date: 06/12/2019
TP Veh Reg No: SJN7137B

Claim No: MC1900881
No: MF1900968
Date: 30 Mar 2020
Policy No: PNPV2019-00005768
Veh Reg No: SLP8769L
Make/Model: TOYOTA WISH 1.8 CVT
Chassis No: JTDGG20W00J007079
TP Ins Co: CHINA

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SLP8769L

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 FRONT DOOR PROTECTOR RH	1 PC	160.00	
		160.00	
	Less 25%	40.00	120.00
LABOUR			
2 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR FRONT DOOR RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	200.00	
3 TO SPRAY FRONT DOOR RH,FRONT FENDER RH, SIDE MIRROR RH.	1 PC	400.00	
		600.00	600.00
		Total	S\$ 720.00
		Add GST @ 7%	50.40
		Total Amount Payable	S\$ 770.40

TOTAL: SINGAPORE DOLLAR SEVEN HUNDRED SEVENTY AND CENTS FORTY ONLY

The above vehicle was surveyed by GUO QIANG - LKK on 11/12/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ALISON NG LI YING
932A HOUGANG AVE 9
#15-90
SINGAPORE 531932
TEL: 93671892

ATTN:
Your Ref No: SLP8769L
Claim Type: Third Party
Accident Date: 06/12/2019
TP Veh Reg No: SJN7137B

Estimate No: MC1900881
Date: 10 Dec 2019
Policy No: PNPV2019-00005768
Veh Reg No: SLP8769L
Make/Model: TOYOTA WISH 1.8 CVT

2:30pm

Estimate Repair Cost to Vehicle No :SLP8769L

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 FRONT FENDER RH <i>X repair</i>	1 PC	720.40	
2 FRONT DOOR PROTECTOR RH - CHECK PRICE <i>NEC. 160.00</i>	1 PC	0.00	
		720.40	
	Less 25%	180.10	540.30
LABOUR			
3 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	X
4 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR FRONT DOOR RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	200
5 TO SPRAY FRONT DOOR RH, FRONT FENDER RH, SIDE MIRROR RH.	1 PC	500.00	400
		940.00	940.00
Total			S\$ 1,480.30
Add GST @ 7%			103.62
Total Amount Payable			S\$ 1,583.92

TOTAL: SINGAPORE DOLLAR ONE THOUSAND FIVE HUNDRED EIGHTY THREE AND CENTS NINETY TWO ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

3 Days
part by nt
After repair photos
Gmo Qiang - 82880282
11/12/19

Man photo
18-02-2020

For AH LIM MOTOR COMPANY



AUTHORIZED SIGNATURE

17-02-2020

Kok