

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 16 Dec 2019

Preliminary Advice

Insured Vehicle No : SKV2620B

TP Vehicle No : SLP402Y

Make : TOYOTA PRIUS HYBRID

Date of Inspection : 11/12/2019

Inspection At : Esteem Performance Pte Ltd (HQ)
Blk 5033 Ang Mo Kio Ind Park 2, #01-259
Singapore 569536

Accident Date : 09/12/2019

Assignment Date : 11/12/2019

Est. Duration of Repair : 4-5 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesN/S front... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,242.25
Revised Amount	:S\$	5,388.95
Check Items (Estimated)	:S\$	1,783.62
Total	:S\$	7,172.57

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.