

Estimate

1/2



Vehicle: SPR 9209P

Make & Model: TOYOTA

Year: TRCHIN VIC

Chassis no: _____

MR0ZX696200020760

Qty	Parts / Labour	Cond	Part \$
1	rear bumper del	678 ✓	980
1	_____ clips (set) new	30	100
1	_____ sponge new	+	25
1	_____ reinforcement Bent	+	350
2	_____ side retainers (9) 95 new	✓	190
1	Rear end panel Repis	+	850
1	_____ garnish del	✓	258
2	rear bumper reflectors (9) 110 new	+	210
1	Tail gate Repis	+	1754
1	_____ lock } new	+	357
1	_____ latch } new	+	85
1	_____ weather strip } new	+	280
1	_____ lock } new	✓	89
1	_____ emblem "Toyota" } new	✓	83
1	_____ "Fortuner" } new	✓	86
1	_____ "V" } new	✓	35
1	rear exhaust pipe new	+	620
1	_____ chrome new	+	87
1	spare tyre top board new	+	350
1	rear floor panel new	+	1200
1	rear wip new new moulding new	+	230

PRO-JEX V2D MOTOR PTE LTD

Reg. No.: 201600429G

SYNERGY @ KB

25 KAKI BUKIT ROAD 4 #03-94

SINGAPORE 417800

HOTLINE: 6100 7676

FAX : 6841 9698

22



Make & Model: BYD Year FOR TUNE

For Tuner

[illegible]