


# MBM WHEELPOWER PTE LTD



Your Ref:

Our Ref: SCL89X

To: ALLIED WORLD

CC

Fax

*Not Authorized  
Resurvey After Paim*

Date: 17/12/2019  
 From: Eryx Tan  
 Fax: 64525333  
 Contact: 81387188  
 Make / Model: PORSCHE PANAMERA 4S  
 Chassis No.: WPOZZZ97ZHL123971  
 Engine No.: CSZ005609  
 Year of Make: 2017  
 Accident Date: 9/12/2019

ESTIMATE FOR VEHICLE NO. : SCL89X

	<u>DESCRIPTION</u>	<u>PART NO.</u>	<u>QTY</u>		<u>List Price</u>
1	BOTTOM ENGINE COVER	971 825 311 F	1	\$	Ta 1,200.00 ✓
2	BOTTOM ENGINE COVER LH	971 825 521 C	1	\$	CM 980.00 ✓
3	BOTTOM ENGINE COVER RH	973 825 522 F	1	\$	CM 980.00 ✓
4	BOTTOM COVER LH	971 825 357	1	\$	nd 85.00 ✓
5	BOTTOM COVER RH	971 825 358	1	\$	nd 85.00 ✓
6	FRONT SUB FRAME	971 400 048 AH	1	\$	Ra 11,550.00 ✓
7	FRONT BOTTOM REINFORCEMENT	971 407 129 N	1	\$	nd 1,200.00 ✓
8	REINFORCEMENT FOR CROSS MEMBER	971 407 487 H	1	\$	1,800.00 ?
9	REINFORCEMENT PLATE	971 407 129 J	1	\$	Ra 1,350.00 ?
10	HEAT SHIELD SUB FRAME	971 825 611	1	\$	120.00 ?
13	TRACK CONTROL LOWER ARM LH	971 407 151 H	1	\$	3,280.00 ?
14	TRACK CONTROL LOWER ARM RH	971 407 152 H	1	\$	3,280.00 ?
15	TRACK CONTROL ARM SPOILER LH	971 407 125 A	1	\$	220.00 ?
16	TRACK CONTROL ARM SPOILER RH	971 407 126 A	1	\$	220.00 ?
17	TRACK CONTROL ARM UPPER	971 407 021 C	1	\$	2,350.00 ?
18	BOLT WITH SHOULDER ( S\$15/PC )	N 106 283 01	8	\$	120.00 ?
19	12-PT SOCKET SHOULDERED NUT SELF-LOCKING ( S\$25/PC )	WHT 005 633	8	\$	200.00 ?
20	SELF LEVELING SENSOR ( S\$1200/PC )	971 616 213 A	2	\$	? 2,400.00
21	HYDRO MOUNTING ( S\$1200/PC )	971 407 183 B	2	\$	? 2,400.00
22	SUSPENSION STRUT BEARING ( S\$190/PC )	971 407 516	2	\$	? 380.00
23	STOP WASHER	971 407 441 A	2	\$	? 140.00

24	WHEEL SPORT RIM (FRONT) ( S\$8,400/PC )	971 601 025 AB 0C6	2	\$	<i>nd</i> 16,800.00 ✓
25	WHEEL SPORT RIM (REAR) ( S\$8,800/PC )	971 601 025 AC 0C6	2	\$	<i>nd</i> 17,600.00 ✓
26	BOLT ( S\$10/PC )	N 106 872 01	8	\$	? 80.00
27	ENGINE MOUNT ( S\$1150/PC )	9A7 199 383 10	2	\$	<i>cm</i> 2,300.00 ✓
28	GEAR BOX MOUNT LH	9A7 399 151 04	1	\$	350.00 ?
29	GEAR BOX MOUNT RH	9A7 399 152 04	1	\$	350.00 ?

Parts List Total:	\$	71,820.00
Less 10% :	\$	7,182.00
	\$	<u>64,638.00</u>

38 **LABOUR**

39	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS.	\$	2,500.00 ?
40	TO RESET ENGINE WARNING LIGHT (ABS,SRS,ECU MEMORY & ETC)	\$	250.00 ?
44	TO CHECK ,REMOVE & REFIT CROSS MEMBER	\$	<i>90d</i> { 350.00
46	TO REMOVE,RENEW & REFIT UNDER CARRIAGE X 04	\$	1,000.00
47	TO CONDUCT WHEEL ALIGNMENT	\$	120.00 ✓

Total:	\$	68,858.00
7% GST:	\$	4,820.06
<b>Grand Total:</b>	<b>\$</b>	<b><u>73,678.06</u></b>

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey ~~before/after~~ spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_