

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

First

Owner : Haridass S/O Muniandy

Accident Date : 3-Dec-19

Vehicle No : FBE 4950 G

Vehicle Model : Honda Wave

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Fork inner tubes	\$ set/tub 240.00 ✓
2	Fork outer tubes	\$ set/tub 250.00 ✓
1	Fork under bracket	\$ set 185.00 ✓
1	Front sport rim	\$ 320.00 x
1	Front rim shaft	\$ su 42.00 x
1	Front rim bearing	\$ 38.00 x
1	Front brake disc	\$ su 155.00 x
1	Headlamp	\$ su 95.00 x
1	Side mirror -L/H	\$ set 48.00 —
1	Front signal -L/H	\$ set 50.00 —
1	Handle-bar	\$ set 105.00 —
1	Hand grip (1 set)	\$ 50.00 —
1	Front footrest bracket	\$ set 55.00 —
1	Front footrest rubber R/H L/H	\$ 28.00 —
1	Brake pedal	\$ 42.00 x
1	Rear footrest - R/H L/H	\$ cur 38.00 —
1	Rear footrest bracket	\$ set 65.00 —
1	Rear taillamp	\$ cur 88.00 —
1	Rear fender n13	\$ cur 68.00 —
1	Main stand	\$ 90.00 x
1	Side stand	\$ 75.00 x
1	Fairing assy (1 set)	\$ cur 485.00 —
		\$ 2,612.00
	Less 10%	\$ 261.20
		\$ 2,350.80

not doing

don

12/11/19

Khanchana

4 day

1/3 @ 1200

MV 81300

Khanchana

1753

c/f: \$ 2,350.80

Special Nett Items

- 1 Number plate (1 set)
- 2 Fork oils
- 2 Fork oil seals
- 1 Steering cone bearing (1 set)
- 1 Rear box
- 1 Rear box bracket
- 1 ERP IU
- 1 Helmet

Rear	\$	3rd	28.00	10
	\$	11	30.00	Q
	\$	11	56.00	Q
	\$	11	85.00	✓
	\$	11	250.00	200
	\$	11	100.00	✓
	\$	11	175.00	✓
	\$	11	95.00	X
	\$		819.00	

S/No.

Labour

- 1 To provide towing service.
- 2 To check wiring and reset headlamp focusing
- 3 To provide labour.
- 4 To repair body frame.

\$	50.00	35
\$	80.00	X
\$	380.00	280
\$	400.00	X
\$	910.00	

Grand Total

\$ 4,079.80

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Reparer of the following:

- * To resurvey before/after spray painting
- * To display damaged parts before/after survey
- * Parts prices are subject to confirmation
- * Supplementary items must be resurveyed and
- * Parts prices are subject to confirmation
- * To display damaged parts before/after spray painting
- * To resurvey before/after spray painting

Acknowledged by Reparer:

Signature: _____

Date: _____

LKK Auto Consultants hence notify

2464.5
(9)1