

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg;darren@sngahtee.com;janice@sngahtee.com

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN3014311900	Date of Loss:	08/12/2019
Vehicle Reg. No.:	GBH1712G	Driveable?	
Driver Age/Info:	32 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	GREENLITE ELECTRIC PTE. LTD.		
Driver:	PARAMASIVAM RADHAKRISHNAN		
Make/Model:	TOYOTA DYNA 150, 3.0 D (M)	Vehicle Reg. Date:	06/03/2018
Vehicle Colour:	WHITE		
Engine No:	1KD2774594	Chassis No:	JTFAT35Y80K209803
Odometer:	6 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	REFER TO POLICE REPORT T/20191209/2042		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	1,950.00
Miscellaneous Items	90.00
Labour	680.40
Paintwork Labour	457.80
Towing	0.00
Gross Total (\$)	3,178.20
+ GST 7.00% (\$)	222.47
Nett Amount (\$)	3,400.67

This claim is handled by: **JOYCE TAN LAI CHIN**Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 13 Dec 2019)**Parts:** N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sng Ah Tee Motor & Panel Service Pte Ltd/GBH1712G/13/12/2019 09:20**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TOTAL SPARE PART	0.00	0.00	1456
F=Franchise part.						*1,950.00 F
Total Parts (\$\$)						1,950.00

Sng Ah Tee Motor & Panel Service Pte Ltd/GBH1712G/13/12/2019 09:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount	
<u>Miscellaneous Items</u>				
1	1	FRT CORNER PANEL BRACKET RH	38	40.00
2	1	FRT DOOR ROC STICKER		20.00
3	1	TO CHECK WIRING		30.00
			Sub Total (S\$)	90.00

Estimates on Labour

No	Particulars	Lab.Type		Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINTWORK LABOUR	New	390.60	457.80
<u>Labour Items</u>				
2	TOTAL OF LABOUR	New	239.40	680.40
			Gross Labour Cost (S\$)	1,138.20

Sng Ah Tee Motor & Panel Service Pte Ltd/GBH1712G/13/12/2019 09:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >