

REPAIR ESTIMATE*

VEHICLE NO : SHA 469G

DATE 12/12/2019 10:09

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet <i>BUC</i>			\$ 2,265.90	
	Bonnet Lock <i>xnn</i>			\$ 36.90	
	Radiator Grille <i>cva</i>			\$ 1,110.10	
	Radiator Grille H Emblem <i>nee</i>			\$ 39.50	
	Front Bumper Cover <i>cva</i>			\$ 1,052.20	
	Front Bumper Sponge <i>Br</i>			\$ 99.20	
	Front Bumper Reinforcement ?			\$ 402.10	
	Front Bumper Grille (LH/RH) <i>xnn</i>		\$ 93.60	\$ 187.20	
	Front Bumper Grille Airduct (LH/RH) <i>xnn</i>		\$ 26.20	\$ 52.40	
	Front Bumper Bracket Top (LH/RH) <i>xnn</i>		\$ 22.40	\$ 44.80	
	Front Bumper Bracket (LH/RH) <i>xnn</i>		\$ 24.60	\$ 49.20	
	Headlamp (LH/RH) <i>Br (LH)</i>		\$ 1,388.00	\$ 2,776.00	
	Front Fender (LH/RH) <i>RH BUC - LH x (R)</i>		\$ 663.00	\$ 1,326.00	
	Front Fender Shield (LH/RH) <i>xnn</i>		\$ 174.90	\$ 349.80	
	Front Fender Retainer <i>xnn</i>			\$ 24.60	
	SUB TOTAL			\$ 9,815.90	
	LESS 20%			\$ 1,963.18	
	DISCOUNTED TOTAL			\$ 7,852.72	
	Front Number Plate <i>cva</i>			\$ 25.00	Nett
	Front No Plate Trim Cover <i>Br</i>			\$ 30.00	Nett
	Front Fender Advertisement Logo (LH/RH) <i>Br</i>		\$ 100.00	\$ 200.00	Nett
	Labour Charge				
	Panel Beating			\$ 1,800.00	\$ 966
	Spray Painting Charge			\$ 1,000.00	\$ 800
	Wiring Charge			\$ 50.00	\$ 30
	Tuff Kote			\$ 50.00	
	TOTAL LABOUR			\$ 2,900.00	
	ESTIMATE TOTAL			\$ 11,007.72	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

ALG

LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ram (LKR)
12/12/19 1530hrs
Paraswan @ LKR Auto. Consultants
8862278 hp
Aft repair - flat
(LIS) *(3 repair days)*