

ASS. REC. BY:

REF:

08/GAI19022002/As d302

Special Instruction:

Surveyor:

41847

ASSIGNMENT (Office)

From (Person):

Sharon

of

GAI

Date/Time:

13/12/19 @ 2:59pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 2875J

Insured:

SJP 6601Z

at Workshop in/s

New Hock Teck

Tel:

6747 9241

of

1 Kaki Bukit Ave 6 # 01-43 Autobay

Policy No:

Claim No:

CLMOMVP000001039

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

3:44pm @ 13/12/19

Person Contacted:

Sukyi

Vehicle IN / OUT

Date/Time

Action/Instruction

1-shmull ✓

81J2875J-X

SJP 6601Z - NM / GAI19021951/24

DOA: 12/12/19

7.200/- @ 9 days

INSURANCE

(Policy No.)
 (Client's Name)
 (Policy No.)
 (Sum Insured)
 (Client's Address)
 (Make of Vehicle)
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 (Est. Repair) days: Res: Yes or No
 (Lith. Sath) % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: Person Contacted:

NS	OS

(Policy No.) 5LJ2875J. 2016 Dec
 (Type) ☒ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Private Motor /
 (Truck / Trailer or)
 (Make) Subaru Forester 1998
 (Color) Grey
 (Sp. Reading) 84246.
 (Engine)
 (Cibo) JFISJGK85GG078708.
 (Gen. Cond.) ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 (Steering) ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt
 (Brake) ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt
 (Mod.) Nil / ☒ STD A/Rim or
 (Tyre Size) F: 225/55R18.
 R: 225/55R18.
 (DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or)
 (Front) (Rear)
 (R/Bal) 06 mm (R/Bal) 06 mm
 (L/Bal) 06 mm (L/Bal) 06 mm
 (D.O.A.) (D.O.L) 16/12/19.
 (Survey held at) NHT.
 (Des. of Damages) Frt / ☒ Rear / ☐ OS / ☐ N/S / ☐ U/C / ☐ Rooftop or
 (The U/C / Chassis frame / Body Structure affected due to its location)

Date / Time Action / Instruction
 TP Great American

MV: 80K
 PV: 55.1K
 Nett: 24.9K.

Adrien Confirmed US \$7,300/- @ 9 days with Boss.
 (\$ 9,620.70 Red - 57%)

(Date/Time) 14/02/20
 (Type) ☒ Prel. Report
☒ Final Report

(Days Of Repair) 9
 (Return No. of Trip) 2

(Add. Fee) ☐ Site Ins. 12
☐ Night Ins. 18
☐ Test Ins. 12
☐ Other Ins. 12

(Selling Fee) 490
 (490)

\$ 7,300/- 45

Nivitha (LKK Auto)

From: Motor Claims <motorclaims@sg.gaig.com>
Sent: Friday, 13 December 2019 2:59 PM
To: SUR
Cc: assignments
Subject: FW: Re: SLJ2875J CLAIMING AGAINST SJP6601Z DOA:12.12.19 - Our ref: CLMOMVP000001039
Attachments: SLJ2875J ESTIMATE.pdf; SJP6601Z (OI).pdf

LKK team

Please survey SLJ2875J and obtain TP SAS from workshop.

Regards
Sharon
Great American

From: Admin nht <admin@nhtmotor.com>
Sent: 13 December 2019 1:37 PM
To: Motor Claims <motorclaims@sg.gaig.com>
Cc: Chloe <chloe@nhtmotor.com>
Subject: [External] Re: SLJ2875J CLAIMING AGAINST SJP6601Z DOA:12.12.19

Without Prejudice

Hi Sharon

Enclosed estimate for your reference.

Please kindly assign the assignment to LKK Auto Consultants for the survey, thanks.

Best Regards,
Sukyi Chong
New Hock Teck Motor Pte Ltd
1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)
Tel : 6747 9241 Fax : 6741 7276

On Fri, Dec 13, 2019 at 10:56 AM Admin nht <admin@nhtmotor.com> wrote:
Without Prejudice

Hi Sharon

Thanks for your email.

Please kindly arrange for LKK Auto Consultants

We are in the midst of preparing the estimate , once is available we will pass to surveyor when come over for the survey,thanks.

*** Please kindly take note this claim is under "New Hock Teck Motor Pte Ltd" ***

Best Regards,

Sukyi Chong

New Hock Teck Motor Pte Ltd

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276



On Fri, Dec 13, 2019 at 10:50 AM Motor Claims <motorclaims@sg.gaig.com> wrote:

WITHOUT PREJUDICE

Hi Sukyi

We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. A-PAC Adjusters & Surveyors Pte. Ltd.
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants

Kindly let us know which SJE is selected and **furnish the estimates** for the survey to be carried out.

Thanks and Regards

Sharon Ng, Assistant Manager | Claims, P&C | P. +65 6804 7845 | F. +65 6235 3354 | sharon.ng@sg.galg.com



Claims Division | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Admin nht <admin@nhtmotor.com>

Sent: 12 December 2019 11:32 AM

To: Motor Claims <motorclaims@sg.galg.com>

Cc: Chloe <chloe@nhtmotor.com>

Subject: [External] SLJ2875J CLAIMING AGAINST SJP6601Z DOA:12.12.19

Without Prejudice

Hi Motor Claim Dept

Please send us your surveyor list, thanks.

*** Please kindly take note this claim is under "New Hock Teck Motor Pte Ltd" ***

Best Regards,

Sukyi Chong

New Hock Teck Motor Pte Ltd

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276



The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 977H

Vehicle Details

Vehicle No.: SLJ2875J
Vehicle to be Exported: No
Intended Deregistration Date: 12 Dec 2019
Vehicle Make: SUBARU
Vehicle Model: FORESTER 2.0XT CVT AWD
SR

Primary Colour: Silver
Manufacturing Year: 2016
Engine No.: FA20B828567
Chassis No.: JF15JGK85GG078708
Maximum Power Output: 177.0 kW (237 bhp)
Open Market Value: \$20,851.00
Original Registration Date: 03 Dec 2016
First Registration Date: 03 Dec 2016
Transfer Count: 0
Actual ARF Paid: \$21,192.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 02 Dec 2026
PARF Rebate Amount: \$15,894.00

Intended COE Rebate Details

COE Expiry Date: 02 Dec 2026
COE Category: B - Car above 1600cc or 97kW
(130bhp)
COE Period(Years): 10
QP Paid: \$56,206.00
COE Rebate Amount: \$39,187.00
Total Rebate Amount: \$55,081.00

The information contained herein is correct as at 12 Dec 2019

OK



Subaru Forester 2.0i-L Sunroof \$69,800 | \$9,270 /yr | 19-Aug-2016 | 1,995 cc | 77,933 km | SUV | Available

1 Owner. Meticulously Taken Care! Immaculate Condition Like New Car! One Of The Most Popular SUV Around! High Loan And High Trade In Available. Do Call Our Friendly Salesman Now To Make An Appointment For A Viewing! Don't Miss! 2.28% Interest Rate.

Mayfair Motoring

☆ Posted: 13-Dec-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru

PREMIUM AD



Subaru Forester 2.0XT Sunroof \$79,800 | \$10,280 /yr | 17-Sep-2016 | 1,998 cc | 74,888 km | SUV | Available

Lowest Interest Rates At 2.28%. Full Loan Available! Car In Tip-Top Condition. No Repair Needed! Call Us Now For A Non Obligation Viewing Today!

Autotraders Traders Pte Ltd

☆ Posted: 13-Dec-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru

PREMIUM AD



Subaru Forester 2.0i-L Sunroof \$68,560 | \$8,880 /yr | 26-Sep-2016 | 1,995 cc | 85,738 km | SUV | Available

Offer Loan Interest At 2.28%. Extremely Well Maintained. New Road Tax Until March 2020. This Beast Does Not Just Look Beautiful. It's 100% Accident Free. View To Believe! 80% Financing Of Car Price Possible! Trade In Welcome Call/SMS To Arrange A Viewing Today! V...

☆ Posted: 28-Dec-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru

PREMIUM AD



Insurance renewal at cheaper price!

We'll find you the cheapest car insurance quotes from over 10 insurers. Make your choice on zero excess and own workshop. Everything done at the comfort of your own home. Roadside assistance & claims support completely free.

Find out more!



Subaru Forester 2.0XT Sunroof \$88,800 | \$11,390 /yr | 27-Oct-2016 | 1,998 cc | 38,787 km | SUV | Available

12.12 Promo! FOC 12 Months Insurance And 12 Months Service Shield. Pristine Condition, Under Warranty! Low Mileage Done. Flexible Finance With Lowest Interest Rates! Buy With A Peace Of Mind From Us, With Proven Track Records For The Past 35 Years. 100% Smo...

Hua Yang Credit Pte Ltd

☆ Posted: 21-Oct-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru

PREMIUM AD



Subaru Forester 2.0i-L Sunroof \$76,800 | \$9,940 /yr | 01-Nov-2016 | 1,995 cc | 31,000 km | SUV | Available

1 Owner! AA Trust Certified Quality Vehicle! 2 Years Extended Warranty! The New Forester That Boast A Meaner Look And All Rounder Driving Experience! Comfort And Sporty That Drives Well On Long Distance With Its Generous Cabin Space And Boot Space For Anythin...

AA Trust Automotive

☆ Posted: 25-Dec-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru

PREMIUM AD



Subaru Forester 2.0i-L Sunroof \$72,900 | \$9,260 /yr | 23-Nov-2016 | 1,995 cc | 51,099 km | SUV | Available

Fully Maintained And 5 Year Warranty By Subaru Agent Till Nov 2021 For Peace Of Mind. Bank And In House Full Loan Available. 1 Owner Only. Original Paintwork Since Day 1. 100% Accident Free. No Repair Needed. Trade In Welcome. Kindly Contact Our Sales Advisor For...

Imperium Car Motor Pte Ltd

☆ Posted: 13-Dec-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru

Available



Subaru Forester 2.0XT Sunroof \$82,800 | \$10,380 /yr | 30-Nov-2016 | 1,998 cc | 31,452 km | SUV | Available

In Showroom Condition. Low Mileage Very Well Kept By 1 Owner. Still Under 5 Years Agent Warranty. we Offer High Trade In. Loan Available From 2.28%. Call Now For Viewing.

Mayfair Motoring

☆ Posted: 13-Dec-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru

PREMIUM AD



Subaru Forester 2.0XT Sunroof \$82,999 | \$10,340 /yr | 15-Dec-2016 | 1,998 cc | 55,000 km | SUV | Available

Lowest Depre In The Market! 237Bhp! Pristine Condition, 1 Owner. Low Mileage, Flexible Financing Package And Trade In, Certified Premium Multi-point Check Drive Away. Please Call /sms/ Whatsapp For More Information And Viewing!

Premium Automobiles

☆ Posted: 22-Dec-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru

PREMIUM AD



Subaru Forester 2.0i-L Sunroof \$71,800 | \$9,050 /yr | 16-Dec-2016 | 1,995 cc | 73,818 km | SUV | Available

1 Owner. Meticulously Taken Care! Immaculate Condition Like New Car! One Of The Most Popular SUV Around! High Loan And High Trade In Available. Do Call Our Friendly Salesman Now To Make An Appointment For A Viewing! Don't Miss! 2.28% Interest Rate.

Mayfair Motoring

☆ Posted: 09-Dec-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru

PREMIUM AD



Subaru Forester 2.0XT Sunroof \$82,300 | \$10,300 /yr | 11-Dec-2016 | 1,998 cc | 58,000 km | SUV | Available

Check This Out. Only One Owner And Superbly Maintained Inside Out. Original Pearl White. Still Under Agent's 5 Years Warranty. 100% Accident Free. STA/Viom Complete Evaluation Welcome. High Trade In. Various Loan Schemes Available To Suit Your Budget. Call For...

☆ Posted: 14-Dec-2019 Tags: 2016 Subaru Forester, 2016 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru

Available

SHORTLISTED HISTORY

Compare

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 16 December 2019 1:09 pm
To: 'Ng, Sharon'; 'Motor Claims'
Cc: assignments; SUR
Subject: RE: Re: SLJ2875J CLAIMING AGAINST SJP6601Z DOA:12.12.19 - Our ref: CLMOMVP000001039

Dear Sharon,

Please be informed that we have inspected the vehicle SLJ 2875J on 16/12/2019.

We are pending estimate from repairer.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 13 December 2019 3:47 pm
To: 'Motor Claims' <motorclaims@sg.gaig.com>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; 'Ng, Sharon' <sharon.ng@sg.gaig.com>
Subject: RE: Re: SLJ2875J CLAIMING AGAINST SJP6601Z DOA:12.12.19 - Our ref: CLMOMVP000001039

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.



Wishes you a Merry Christmas & Happy New Year 2020

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2019 13:03
Date Of Accident	12/12/2019 07:40
Exact Location Of Accident	LORNIE RD TWDS THOMSON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ2875J
Insured/Policyholder	
Name Of Registered Owner	CHENG SIEW WENG
NRIC No	S7010977H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96328051
Alternative Phone No	OFFICE-96328051
Vehicle Particulars	
Manufacturer	SUBARU
Model	FORESTER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100492584-03
Cover Note Number	
Driver	
Name of Driver	CHENG SIEW WENG
NRIC No	S7010977H
Date Of Birth	01/04/1970
Occupation	INDOOR
Date Of Driving Pass	12/11/1992
Driving Experience	27 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96328051
Fax Number	
Contact Number	OFFICE-96328051
Email Address	NOEMAIL

Address	17 FERNVALE CLOSE #03-29
Postcode	797478
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING STRAIGHT ALONG LORNIE RD TOWARDS THOMSON RD AT THIRD LANE OF 5 LANES. ALL VEHICLES IN FRONT OF ME SLOWED DOWN AND STOPPED. I FOLLOWED SUIT. SUDDENLY, I FELT AN IMPACT. VEHICLE B COLLIDED ONTO REAR PORTION OF MY VEHICLE AND CAUSED DAMAGES. I ALIGHTED AND REALISED THERE WERE TOTAL OF 3 VEHICLES GOT INVOLVED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJP6601Z
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLM1597C
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

A: 2LJ 2875
B: 2P 66 017
C: 2M 15970

Lorne Rd Towards Thomson Rd

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight along Lorne Rd towards Thomson Rd at 3rd lane of 5 lanes. All vehicles in front of me slowed down & stopped, I followed suite. Suddenly, I felt an impact. Vln "B" collided onto rear portion of my vehicle and caused damages.


I alighted and realised there was total 3 vehicles get involved.

DECLARATION

(We declare the foregoing particulars are true in every respect)


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

26/02/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Great American

Shirley

12/12/2019.

JF1SJGK8566078708

Accident date: 26/02/2019

Estimated repair cost for vehicle no: SJ2875J SUBARU FORESTER 2.0 XT '16

CHASSIS: JF1SJGK85GG078708

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Buckled</i>		\$1,292.30 ✓
2	2	Rear Boot Lid Hinge <i>part</i>	\$55.00	\$110.00 ✓
3	2	Rear Boot Lid Shock Absorber <i>new</i>	\$154.00	\$308.00 ✓
4	1	Rear Boot Lid Emblem Logo <i>?</i>		\$65.00 ✓
5	1	Rear Boot Lid Subaru Logo <i>new</i>		\$68.00 ✓
6	1	Rear Boot Lid Forester Logo		\$68.00 ✓
7	1	Rear Boot Lid AWD Logo		\$65.00 ✓
8	1	Rear Boot Lid XT Logo <i>new</i>		\$65.00 ✓
9	1	Rear Boot Lid Number Plate <i>not new</i>		\$50.00 ✓
10	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$560.30 ✓
11	1	Rear Boot Lid Inner Rubber <i>lot</i>		\$160.30 ✓
12	1	Rear Boot Lid Inner Trim Board <i>Cracked.</i>		\$220.30 ✓
13	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$85.00 ✓
14	2	Rear Boot Lid Windscreen Side Seal	\$75.00	\$150.00 ✓
15	2	Rear Tail Lamp <i>LH cracked.</i>	\$437.00	\$874.00 A37.
16	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 10.
17	2	Rear Tail Lamp Lower Bracket <i>not new</i>	\$28.00	\$56.00 ✓
18	1	Rear Bumper <i>Delined.</i>		\$980.30 784
19	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 30
20	2	Rear Bumper Side Retainer <i>new</i>	\$38.00	\$76.00 ✓
21	2	Rear Bumper Side Reflector <i>new cracked</i>	\$42.00	\$84.00 42
22	1	Rear Bumper Top FORESTER Moulding <i>Delined</i>		\$365.00 ✓
23	1	Rear Bumper Towing Cover <i>Missing.</i>		\$22.00 ✓
24	1	Rear Bumper Reinforcement <i>Bent.</i>		\$320.80 ✓
25	2	Rear Bumper Reinforcement Bracket <i>not new</i>	\$28.60	\$57.20 ✓
26	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$380.00 200(Sm)
27	2	Rear Fender Inner Trim Board <i>LH Delined</i>	\$286.30	\$572.60 486.30
28	16	Rear Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$104.00 30

29	1	Rear End Panel <i>Distorted</i>		\$ 615	✓
30	1	Rear End Panel Top Garnish <i>Detained</i>		\$90.00	✓
31	1	Rear Spare Tyre Panel <i>Buckled</i>		\$832.40	✓
32	1	Rear Spare Tyre Panel Top Cover <i>Detained</i>		\$336.00	✓
33	1	Rear Spare Tyre Panel & End Panel Sealant <i>NH New</i>		\$450.00	x
34	2	Rear Exhaust <i>LH Bent</i>	\$668.00	\$1,336.00	668
35	1	Rear Centre Exhaust <i>NEW</i>		\$1,248.00	x
36	2	Rear Exhaust Chrome Pipe <i>NH New</i>	\$125.90	\$251.80	x
37	2	Rear Exhaust Aluminium Cover <i>NH New</i>	\$68.00	\$136.00	x
38	4	Rear Exhaust Mounting <i>NH New</i>	\$23.10	\$92.40	x

7753-70

620296 S-N 200

Subtotal :- \$12,360.70

Labour charges

To remove & refit cushion	\$280.00	80
To remove & refit reverse sensor	\$100.00	50
To remove & refit rear camera	\$180.00	50
To remove & refit rear & centre exhaust	\$380.00	160
To remove & refit rear windscreen	\$120.00	✓
Gum	\$50.00	✓
To check wiring	\$100.00	30
Tuff kote	\$150.00	60
Panel beating	\$1,600.00	1200
Spray painting	\$1,600.00	1000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged car(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :- \$4,560.00

Total :- \$16,920.70

7.3K

total 9202.96

h/c 7.3K

09 Days

1704.70



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI19022002/Asd3e2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 14-02-2020		
		Code : GAI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJP 6601Z	Veh. Inspected	SLJ 2875J
	Policy No.		Coverage (\$)	0.00
	Claim No.	CLMOMVP000001039	Excess (\$)	0.00
	Assign From	SHARON	Assign Date	13/12/2019
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU FORESTER	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JF1SJGK85GG078708	Colour	GREY
	Odometer	84246	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	12/12/2019	Inspection Date	16/12/2019
	Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 2875J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID	BUCKLED	1,292.30	1,292.30
2	REAR BOOT LID HINGE @\$55.00	NOT NECESSARY	110.00	-
2	REAR BOOT LID SHOCK ABSORBER @\$154.00	NOT NECESSARY	308.00	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	65.00	65.00
1	REAR BOOT LID SUBARU LOGO	NECESSARY	68.00	68.00
1	REAR BOOT LID FORESTER LOGO	NECESSARY	68.00	68.00
1	REAR BOOT LID AWD LOGO	NECESSARY	65.00	65.00
1	REAR BOOT LID XT LOGO	NECESSARY	65.00	65.00
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
1	REAR BOOT LID INNER LOCK	DAMAGED	560.30	560.30
1	REAR BOOT LID INNER RUBBER	CUT	160.30	160.30
1	REAR BOOT LID INNER TRIM BOARD	CRACKED	220.30	220.30
1	REAR BOOT LID WINDSCREEN SEAL	NECESSARY	85.00	85.00
2	REAR BOOT LID WINDSCREEN SIDE SEAL @\$75.00	NECESSARY	150.00	150.00
2	REAR TAIL LAMP @\$437.00	N/S CRACKED	874.00	437.00
4	REAR TAIL LAMP CLIP @\$8.00	NECESSARY	32.00	10.00
2	REAR TAIL LAMP LOWER BRACKET @\$28.00	NOT NECESSARY	56.00	-
1	REAR BUMPER	DEFORMED	980.30	794.00
10	REAR BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
2	REAR BUMPER SIDE RETAINER @\$38.00	NECESSARY	76.00	76.00
2	REAR BUMPER SIDE REFLECTOR @\$42.00	N/S CRACKED	84.00	42.00
1	REAR BUMPER TOP FORESTER MOULDING	DEFORMED	365.00	365.00
1	REAR BUMPER TOWING COVER	MISSING	22.00	22.00
1	REAR BUMPER REINFORCEMENT	BENT	320.80	320.80
2	REAR BUMPER REINFORCEMENT BRACKET @\$28.60	NOT NECESSARY	57.20	-
2	REAR FENDER INNER TRIM BOARD @\$286.30	N/S DEFORMED	572.60	286.30
16	REAR FENDER INNER TRIM BOARD CLIP @\$6.50	NECESSARY	104.00	30.00
1	REAR END PANEL	DISTORTED	615.00	615.00
1	REAR END PANEL TOP GARNISH	DEFORMED	90.00	90.00
1	REAR SPARE TYRE PANEL	BUCKLED	832.40	832.40
1	REAR SPARE TYRE PANEL TOP COVER	DEFORMED	336.00	336.00

Report Ref No. CS/GAI19022002/Asd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE PANEL & END PANEL SEALANT	NOT NECESSARY	450.00	-
2	REAR EXHAUST @\$668.00	N/S BENT	1,336.00	668.00
1	REAR CENTRE EXHAUST	NOT NECESSARY	1,248.00	-
2	REAR EXHAUST CHROME PIPE @\$125.90	NOT NECESSARY	251.80	-
2	REAR EXHAUST ALUMINIUM COVER @\$68.00	NOT NECESSARY	136.00	-
4	REAR EXHAUST MOUNTING @\$23.10	NOT NECESSARY	92.40	-
	LESS 20% DISCOUNT		-	-1,550.74
			12,263.70	6,202.96
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	380.00	200.00
			380.00	200.00
	LABOUR			
	TO REMOVE & REFIT CUSHION.		280.00	80.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	50.00
	TO REMOVE & REFIT REAR CAMERA.		180.00	50.00
	TO REMOVE & REFIT REAR & CENTRE EXHAUST.		380.00	160.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	GUM.		50.00	50.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	60.00
	PANEL BEATING.		1,600.00	1,200.00
	SPRAY PAINTING.		1,600.00	1,000.00
			4,560.00	2,800.00
	GRAND TOTAL		17,203.70	9,202.96
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,300.00

Report Ref No. CS/GAI19022002/Asd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.