

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SLU 8749 T**
 Model : **VOLKSWAGEN TIGUAN**
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Bonnet	1	\$ 1,863.70	\$ 1,120.00 1,863.70	DD ✓
2	Bonnet insulator	1	\$ 237.00	\$ ✓ 237.00	DD ✓
3	Bonnet hinge	2	\$ 185.20	\$ 210.00 370.40	BT ✓
4	Bonnet lock	1	\$ 144.30	\$ ✓ 144.30	JAM ✓
5	Bonnet upper catch	1	\$ 146.30	\$ ✓ 146.30	BT ✓
6	Front grille assy	1	\$ 893.40	\$ 780.50 893.40	MIS ✓
7	Front grille emblem 'Volkswagen'	1	\$ 58.90	\$ ✓ 58.90	NEC ✓
8	Front bumper	1	\$ 1,652.80	\$ 902.00 1,652.80	BR ✓
9	Front bumper side retainer	2	\$ 186.50	\$ 170.00 373.00	NEC ✓
10	Front bumper bracket	2	\$ 126.70	\$ 253.40	NSP X
11	Front bumper tow cover	1	\$ 189.60	\$ 16.00 189.60	MIS ✓
12	Front bumper lower grille	1	\$ 523.10	\$ 325.00 523.10	MIS ✓
13	Front bumper air guide	2	\$ 87.60	\$ 91.40 175.20	MIS ✓
14	Front fog lamp	2	\$ 295.30	\$ 236.00 590.60	MIS ✓
15	Front fog lamp garnish	2	\$ 354.20	\$ 708.40	NSP X
16	Front bumper reinforcement	1	\$ 689.50	\$ 450.00 689.50	BR ✓
17	Front bumper inner sponge	1	\$ 186.40	\$ 160.00 186.40	BR ✓
18	Front support panel	1	\$ 1,769.20	\$ 1,008.00 1,769.20	BR ✓
19	Front fender LH	1	\$ 1,983.50	\$ 899.00 1,983.50	DD ✓
20	Front fender inner cowling LH	1	\$ 358.10	\$ 290.00 358.10	BR ✓

7244.40

21	Air filter box	1	\$	753.40	\$	753.40	BRV
22	Air duct	1	\$	368.20	\$ 266.00	368.20	DIS
23	Battery	1	\$	486.50	\$ 250.00	486.50	BRV
24	Battery bracket	1	\$	328.50	\$ 46.72	328.50	BRV
25	Wiper washer tank	1	\$	623.40	\$ 331.90	623.40	DDV
26	wiper washer tank motor	2	\$	253.80	\$	507.60	? NDX
27	Engine lower caver	1	\$	843.60	\$ 175.45	843.60	BRV
28	engine caver	1	\$	553.10	\$	553.10	NDX
29	Throttlebody	1	\$	583.70	\$ 360.13	583.70	BRV
30	Intake monifold	1	\$	1,653.20	\$	1,653.20	BRV
31	A/c condenser	1	\$	804.00	\$ 615.00	804.00	} BRV \$ DIS \$ BT
32	A/ c condenser high pressure pipe	1	\$	483.10	\$ 216.20	483.10	
33	A/c condenser low pressure pipe	1	\$	452.00	\$ 89.09	452.00	
34	Radiator	1	\$	985.30	\$ 585.00	985.30	
35	Radaitor top hose	1	\$	459.20	\$ 165.08	459.20	
36	Radiator bottom hose	1	\$	587.30	\$ 180.00	587.30	} ? NDX
37	Fuse box assy	1	\$	1,980.00	\$	1,980.00	
38	Inter cooler	1	\$	1,065.90	\$ 647.00	1,065.90	BRV
39	Inter cooler pipe	2	\$	653.80	\$ 453.60	1,307.60	BRV
40	Radiator fan assy	1	\$	986.20	\$ 729.00	986.20	BRV
41	A/con fan assy	1	\$	528.15	\$ 351.00	528.15	BRV
42	Gear box mounting set	1	\$	543.20	\$ 480.00	543.20	BRV
43	Headlamp	2	\$	1,323.60	\$ 2647.20	3,687.00	BRV
44	Headlamp lower bracket	2	\$	128.50	\$	257.00	NSPX

Parts Sub Total : \$ 33,993.95

5% Discount \$ 1,699.70

PARTS TOTAL : \$ 32,294.25

@ 5%

18286.89

914.34

17372.55

4

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Bonnet insulator clip	1	\$ 60.00	\$ 30.00 60.00	} NEC ✓
3	Front grille clip	1	\$ 60.00	\$ 30.00 60.00	
4	Front bumper clip	1	\$ 60.00	\$ 30.00 60.00	
5	Front bumper lower grille clip	1	\$ 60.00	\$ 30.00 60.00	
6	Front bumper sensor	4	\$ 250.00	\$ 260.00 1,000.00	
7	Coolant	1	\$ 80.00	\$ 80.00	NNX
8	Front fender sealant	1	\$ 80.00	\$ 30.00 80.00	NECV
9	Front fender inner cowling clip LH	1	\$ 60.00	\$ 30.00 60.00	NECV
10	A/c condenser fluid	1	\$ 80.00	\$ 40.00 80.00	} NEC
11	Radiator coolant	1	\$ 80.00	\$ 40.00 80.00	
12	Headlamp seal	2	\$ 100.00	\$ 200.00	NNX
SPECIAL NETT TOTAL :				\$ 460.00 1,900.00	

Nos.	LABOUR		S\$	
1	R&R Radiator		\$ 80.00 150.00	✓
2	R&R a/c condenser		\$ 80.00 150.00	✓
3	R&R front bumper sensor		\$ 60.00 100.00	✓
4	R&R fuse box		\$ 50.00 150.00	✓
5	R&R Intake manifold		\$ 50.00 150.00	✓
6	R&R gear box mounting		\$ 50.00 150.00	✓
7	Diagnostic & reset fault codes		\$ 100.00 300.00	✓
8	Panel beat	1,600.00	\$ 120.00 1,800.00	✓
9	Rust proofing		\$ 60.00 100.00	✓
10	Spray painting	1,300.00	\$ 100.00 1,800.00	✓
11	Check wiring		\$ 50.00 150.00	✓
12	Conduct water leakage test		\$ 80.00	NNX
LABOUR TOTAL :			\$ 2780.00 5,080.00	

17/12/19 Survey
TGTim Lim

Resurvey

31/12/19

TGTim Lim

Repair days 10

PARTS TOTAL : \$17372.55 32,294.25
SPECIAL NETT TOTAL : \$ 460.00 1,900.00
LABOUR TOTAL : \$ 2780.00 5,080.00
GRAND TOTAL : \$ 39,274.25

@ 20%

~~20612.55~~
~~4122.51~~
~~16490.04~~

~~L/s 16500/-~~

TGTim
Lim
24/1/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	MIS	✓	
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish	MIS	✓	
1004	991300	Frt Bumper	BR	✓	
1005	992341	Frt Bumper Clips	NEC	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	NEC	✓	
1008	991433	Frt Bumper Reinforcement	BR	✓	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	BR	✓	
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	MIS	✓	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp	MIS	✓	
1020	995080	Frt RH Bumper Fog Lamp	MIS	✓	
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem	NEC	✓	
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BR	✓	
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	BR	✓	
1030	991821	Frt RH Headlamp Assy	BR	✓	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	PD	✓	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock	JM	✓	
1036	990285	Bonnet Insulator	DL	✓	
1037	990273	Bonnet Hinge	BT	✓	
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	BR	✓	
1043	990122	Air Con Fan Assy	BR	✓	
1044	990134	Air Con Suction Pipe (Low Pressure)	BT	✓	
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)	BT	✓	
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator	DD	✓	
1053	992738	Radiator Cowling	BR	✓	
1054	992742	Radiator Fan Assy	BR	✓	
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top	DL	✓	
1057	992757	Radiator Hose Bottom	DL	✓	
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy	BR	✓	
1061	990056	Air Cleaner Hose	DIS	✓	
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery	BR	✓	
1068	990224	Battery Cover			
1069	990223	Battery Bracket	BR	✓	
1070	990229	Battery Tray			

Vehicle No:

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank	DD	✓	
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover	BR	✓	
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting	BR	✓	
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	DD	✓	
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield	BR	✓	
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Inter cooler	BR	✓	
		Inter cooler pipe	DL	✓	