

AE AUTO PTE LTD
 160, Sin Ming Drive
 Sin Ming Auto City #06-01
 Singapore 575722
 Tel: 64535654, 64591630
 Fax: 64591698

Not Notified
1/1 Day @ ?
Recovery After Paint
21 days

Date 16/12/2019

QUOTATION -THIRD PARTY CLAIM

AIG INSURANCE SINGAPORE PTE LD

Attr: Motor Claim Department . Officer In Charge

Accident on : 14/12/2019

Claim : Third Party Claim
 Veh. No : JSB 3294
 Model : TOYOTA VIOS
 Insured Ins: AIG MALAYSIA

QTY	PARTICULARS	AMOUNT	SURVEYOR
Your Insurer Vehicle No : SLA 4391Y			
1 PC	FRONT BONNET ASSY <i>RT</i>	\$ 1,119.40	✓
1 PC	FRONT BOONET HINGES <i>R</i>	\$ 121.10	X
1 PC	FRONT BONNET LOCK <i>R</i>	\$ 167.80	X
1 PC	FRONT BONNET TOP INSULATOR <i>Sum</i>	\$ 46.80	X
2 PCS	FRONT HEADLAMP ASSY R & LH <i>NIS CMA</i>	\$ 1,873.40	✓
1 PC	FRONT GRILLE	\$ CMA 325.00	✓
1 PC	FRONT GRILLE LOGO <i>Me</i>	\$ 38.00	✓
1 PC	FRONT GRILLE CHROME <i>Me</i>	\$ 78.30	✓
1 PC	FRONT BUMPER <i>RT</i>	\$ 737.50	✓
1 PC	FRONT BUMPER BEAM	\$ 562.40	X SVC
2 PCS	FRONT BUMPER SIDE RERTAINER <i>NIS DiY</i>	\$ 222.50	✓
2 PCS	FRONR BUMPER BRACKET	\$ 208.70	X
1 PC	FRONT BUMPER CENTRE GRILLE <i>CMA</i>	\$ 206.60	✓ SVC
2 PCS	FRONT BUMPER SIGNAL LAMP <i>Sum</i>	\$ 84.80	X
2 PCS	FRONT BUMPER SIGNAL LAMP GARNISH <i>Sum</i>	\$ 149.20	X
2 PCS	FRONT BUMPER SPORT LAMPS <i>Sum</i>	\$ 289.30	X
1 PC	FRONT SUPPORT PANEL <i>R</i>	\$ 885.00	X
2 PCS	AIR CONDENSER SIDE AIR GARNISH <i>NIS CMA</i>	\$ 180.00	✓
1 PC	FRONT FENDER		
		REPAIRS	
		\$ 7,385.80	
		LESS 25%	\$ 1,846.45
		SUB-TOTAL (1)	\$ 5,539.35
1 PC	BOOTLID <i>RT</i>	\$ 1,250.00	✓
2 PCS	BOOTLID HINGES <i>NIS RT</i>	\$ 380.00	✓
1 PC	BOOTLID LOCK <i>RT</i>	\$ 220.00	✓
1 PC	BOOTLID OUTER MOULDING <i>WAPP</i>	\$ 180.00	✓
1 PC	BOOTLID WEATHERSTRIP <i>NIS RT</i>	\$ 80.00	✓
1 PC	BOOTLID CENTRE LOGO <i>Me</i>	\$ 68.00	✓
1 PC	BOOTLID VIOS EMBLEM <i>Me</i>	\$ 68.00	✓
1 PC	BOOTLID E EMBLEM <i>Me</i>	\$ 55.00	✓
1 PC	BOOT CABLE <i>Sum</i>	\$ 135.00	X
1 PC	BOOT LID TOP GARNISH <i>DiY</i>	\$ 265.00	✓
2 PCS	TAILLAMP RH & LH <i>CMA</i>	\$ 1,520.00	✓
2 PCS	TAILLAMP INNER PANEL RH & LH <i>RT</i>	\$ 680.00	✓
1 PC	REAR END PANEL		

I, KK Auto Consultants hence notify the Repairer of the following.

- To resurvey before spray painting
- To display damaged part(s) during resurvey

• Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

AE AUTO PTE LTD
 160, Sin Ming Drive
 Sin Ming Auto City #06-01
 Singapore 575722
 Tel: 64535654, 64591630
 Fax: 64591698

JSB 3294

	LABOUR	AMOUNT	SURVEYOR
	Balance b/f		
1 PC	REAR SPARE TRYE SIDE SPONGE <i>Return</i>	\$ 140.00	✓
1 PC	REAR END PANEL TOP GARNISH <i>Remove</i>	\$ 265.00	X
1 PC	REAR SPARE TYRE PANEL <i>Return</i>	\$ 880.00	✓
1 PC	REAR SPARE CARDBOARD <i>CM</i>	\$ 285.00	✓
1 PC	REAR SPARE TYRE CARDBOARD TOP GARNISH <i>CM</i>	\$ 365.00	✓
1 PC	REAR BUMPER <i>R</i>	\$ 1,150.00	✓
2 PCS	REAR BUMPER SIDE RETAINER, <i>CM</i>	\$ 128.00	✓
2 PCS	REAR BUMPER BRACKETS <i>diy</i>	\$ 110.00	✓
2 PCS	REAR BUMPER BEAM <i>M</i>	\$ 325.00	✓
2 PCS	REAR BUMPER REFLECTORS <i>NTS</i>	\$ 680.00	✓
1 SET	REAR BUMPER CLIPS <i>CM</i>	\$ 40.00	✓
1 SET	REAR NO PLATE LAMP <i>new</i>	\$ 285.00	X
1 PC	REAR FENDER -LH <i>Buy</i>	\$ 1,120.00	✓
2 PC	REAR FENDER INNER GARNISH <i>Return</i>	\$ 710.00	✓
1 PC	REAR FENDER -RH	REPAIR	
1 PC	REAR W/SCREEN GLASS MLDG <i>new</i>	\$ 185.00	✓
1 PC	REAR FENDER MUDFLAP <i>CM</i>	\$ 135.00	✓
1 SET	REAR SPARE TYRE OPENER <i>new</i>	\$ 145.00	✓
1 PC	REAR EXHAUST PIPE	\$ 750.00	X
		\$ 12,599.00	
	LESS 25%	\$ 3,149.75	
	SUB-TOTAL (2)	\$ 9,449.25	
	S/NETT		
1 SET	FRONT & REAR NO PLATE <i>new</i>	\$ 120.00	✓
1 SET	REAR BUMPER SENSOR <i>new/short</i>	\$ 380.00	✓
	REAR SPARE TYRE	\$ 250.00	X
	FRONT LABOUR		
	LABOUR CHARGE	\$ 800.00	5000
	SPARY PAINTING ON AFFECTED AREA	\$ 800.00	6000
	ANTI-RUST	\$ 100.00	300
	TO REMOVE AIR CON CONDENSER & TOP UP FEON GAS	\$ 120.00	X
	TO CHECK WIRING SYSTEM FORCUS HEADLAMPS & ETC	\$ 130.00	200
	REAR LABOUR		
	LABOUR CHARGE	\$ 2,000.00	1800
	SPRAY PAINTING WHOLE EXTERIOR AND INTERIOR	\$ 1,500.00	12000

AE AUTO PTE LTD
 160, Sin Ming Drive
 Sin Ming Auto City #06-01
 Singapore 575722
 Tel: 64535654, 64591630
 Fax: 64591698

JSB 3294

TRANSFER OLD BOOT LID TO ANOTHER NEW BOOT	\$ 120.00	60%
ANTI-RUST	\$ 120.00	✓
TO CHECK WIRING & CHECK LEAKING	\$ 90.00	20%
TO REPLACE REAR SENSOR	\$ 90.00	50%
REPLACE REAR EXHAUST PIPE	\$ 180.00	60%
TO REMOVE & REFIT BOOT GARNISH, CARPET & SIDE TRIM	\$ 280.00	100%
TO BODY CHASSIS ALIGNMENT	\$ 300.00	250%
TO REMOVE & REFIT PETROL TANK	\$ 130.00	60%
FRONT & REAR LABOUR	\$ 6,760.00	
SUB-TOTAL (1) *(2)	\$ 14,988.60	
TOTAL ESTIMATE	\$ 21,748.60	