Ling Ting An

From:

Ling Ting An

Sent:

Friday, 15 May 2020 1:12 PM

To:

Kenneth Kong (LKKAuto)

Cc:

Ong Hock Kong; Lily Loi; Sharon Ten

Subject:

RE: SLB2457A Nissan Qashqai

Dear Kenneth,

We confirm finalise lump sum amount at \$4,600.

X 6 days

(Man) Accept

15/5/seso

Thank you.

Best Regards,

Ling Ting An (Mr.)

Motor Claims Department

D: +65 6481 1522 | F: +65 6481 1011 | M: +65 9819 9881

OPT/MA ///ERKZ PTE.LTD.

Head office: 6 Kung Chong Road Singapore 159143 Branch: 9A Serangoon North Ave 5 Singapore 554500 Branch: 452 Tagore Industrial Ave Singapore 787823 Tel: (+65) 6472 1313 Fax: (+65) 6472 2112 Tel: (+65) 6484 9919 Fax: (+65) 6481 1011 Tel: (+65) 6452 6868 Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.

Please notify the sender if you receive this email in error, and delete the email and its content immediately after which

From: Kenneth Kong (LKKAuto) < Kenneth Kong@lkkauto.com>

Sent: Friday, 15 May 2020 11:50 AM
To: Ling Ting An <tingan.ling@ow.sg>
Subject: Re: SLB2457A Nissan Qashqai

L/Sump \$4600.00 as rear bumper \$717.00 and rear end panel \$650.40. Please check and confirmed.

Kenneth

From: Ling Ting An < tingan.ling@ow.sg> Sent: Friday, 15 May 2020 11:10 AM

To: Kenneth Kong (LKKAuto) < Kenneth Kong@lkkauto.com >

Subject: SLB2457A Nissan Qashqai

Dear kenneth,

Attached SLB2457A finalise as per your request.

Thank you.

Best Regards,

Ling Ting An (Mr.)

Motor Claims Department

D: +65 6481 1522 | F: +65 6481 1011 | M: +65 9819 9881



OPTIMA WERKZ PTE LTD Co. Reg. No. 201212455W

www.ow.sq

7 /OptimaWerkz

OptimaWerkz

Date:

14.12.2019

Vehicle No: SLB2457A

Model:

NISSAN OASHOAI 1.2 DIG-T

Chassis:

SJNFEAJ11U1588915 - 2015

Reg.Year:

2016

Third Party Insurer:

Third Party Veh No:

SHD3354T

Date of Accident:

13.12.2019

111

Not Arthorise

ESTIMATE

11 Sing & 7 Merony After Pains 5-6day

NO.	DESCRIPTION		QTY	UNIT S\$	AMOUNT S\$] .
1	REAR TAILGATE		1	1	\$2,867.50	
2	REAR TAILGATE INNER LOCK		1		1101\$203.28	0
3	REAR TAILGATE "QASHQAI" EMBLEM		1	,	Un \$105.75	_
4	REAR WINDSCREEN MOULDING		1		Ma \$128.60	_
5	REAR TAILGATE INNER TRIM CLIPS		8	\$6.50	nn \$52.00	X
6	REAR END PANEL		1	650 40	By \$703.50	-
7	REAR END PANEL UPPER TRIM COVERING		1		017 \$129.25	
8	REAR END PANEL UPPER TRIM COVERING CLIPS		6	\$6.50	Mu \$39.00	-
9	REAR BUMPER		1	717 R	\$1,240.50	
10	REAR BUMPER CLIPS		10	\$5.80	Ma \$58.00	_
11	REAR BUMPER REFLECTOR LH		1		P17 \$87.50	_
12	REAR BUMPER SIDE BRACKET LH		1		p1 \$48.80	
13	REAR SPARE TYRE PANEL				REPAIR	
		5035	20	SUB TOTAL	\$5,663.68	1 \$ 5611.
		1510.5	2	LESS 30%	-\$1,699.10	
		3524.	22	PARTS TOTAL	\$3,964.58	1 3938.

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	REAR WINDSCREEN SEALANT	1		ne \$80.00	4051
2	REAR WINDSCREEN STOPPER	2	\$15.00	m \$30.00	X
3	REAR BUMPER REVERSE SENSOR	1		Not \$350.00	
			S/N TOTAL	\$460.00	\$390

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
 To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



OPTIMA WERKZ PTE LTD Co. Reg. No. 201212455W

www.ow.sq

7 /OptimaWerkz

OptimaWerkz

\$800.00

\$150.00 /201

\$150.00 60

\$900.00

\$200.00

\$120.00 201

Date:

14.12.2019

Vehicle No: SLB2457A

Model:

NISSAN QASHQAI 1.2 DIG-T

Chassis:

SJNFEAJ11U1588915 - 2015

Reg. Year:

2016

Third Party Insurer:

Third Party Veh No:

SHD3354T

Date of Accident:

13.12.2019

ESTIMATE

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST REAR ACCIDENT

AREAS & ETC

LABOUR CHARGES TO REMOVE & REFIX, REPLACE REAR WINDSCREEN GLASS, REAR

WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM

& ETC

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS

AT REAR TAILGATE, REAR END PANEL, REAR BUMPER & ETC

LABOUR CHARGES TO DISCONNECT & RECONNECT REAR WIRING SYSTEMS & ETC

TO TUFF KOTE & UNDERSEAL MATERIALS

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00

\$2,420.00 \$1870

LABOUR TOTAL

\$6,844.58

ONG

TOTAL

Finalise:

Parts: \$3524.55

Nett : \$390

tabour: \$1870

\$ 5784.55 Less 20% = \$4627.6

\$4600

(- \$1327.64) \$ 6188.18 - 20% Long Sun