

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

17-Dec-19

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6418 D

1 pc	Rear bumper o/s side bracket XHV	\$ 29.00
1 pc	Rear bumper X(R)	\$ 696.00
1 pc	Rear o/s wheel cover SCV	\$ 116.00
		\$ 841.00
	Less 10%	\$ 84.10
		\$ 756.90
		\$ 104.4

TO: Chan Jia Le

HS: \$700/=

3 repair days

S/NETT

1 pc	Rear o/s fender sticker rec	\$ 60.00
	Sundry	\$ 50.00 \$30
	To check for rear o/s wheel alignment	\$ 80.00 XHV
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same etc	\$ 550.00 \$360
	To putty and spray painting on rear o/s fender, rear bumper	\$ 400.00 \$360
	To apply rustproofing on the repaired and replaced panels.	\$ 120.00 \$50
		\$ 2,016.90

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Ram (LCC)

19/12/19 10:10 hrs

Parasuram@lkkauto.com

88622728 W

3 repair days

HS

aft repair photo

~~\$700.00~~  
US: \$700.00