

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Dec 2019)
 Parts: 143 OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SMG9846B/18/12/2019 17:43
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Dopr	Amount
1	1		*Front bumper	CM	0.00	0.00 ✓*1,299.00 F ✓
2	1		*Front bumper lower cover	CM	0.00	0.00 ✓*224.00 F ✓
3	1		*Front bumper lower centre grille	DM	0.00	0.00 ✓*120.00 F ✓
4	1		*Front bumper deflector RH	CM	0.00	0.00 ✓*162.00 F ✓
5	8		*Front bumper rivets	mi	0.00	0.00 ✓*16.00 F ✓
6	1		*Front fender splash shield RH	CM	0.00	0.00 ✓*47.00 F ✓
7	1		*LLH air deflector	CM	0.00	0.00 ✓*73.00 F ✓
8	1		*Front bumper sponge	CM	0.00	0.00 ✓*107.00 F ✓
9	1		*Front bumper trim RH *	mi	0.00	0.00 *70.00 F ✓
10	1		*Front bumper fog lamp RH *	mi CM	0.00	0.00 *253.00 F ✓
11	1		*Front bumper fog lamp cover RH *	mi	0.00	0.00 *145.00 F ✓
12	1		*Front bumper fog lamp chrome trim RH *	mi	0.00	0.00 *452.00 F ✓
13	1		*Headlamp RH *	CM	0.00	0.00 *885.00 F ✓
14	1		*Resonator hose *	CM	0.00	0.00 *127.00 F ✓
15	1		*Air guide lower	CM	0.00	0.00 ✓*40.00 F ✓
16	1		*Front bumper bracket RH *	R	0.00	0.00 *44.00 F ✓
17	1		*Front tyre RH (Greenlander - 245 45 R18)	Pu	0	0.00 104- *130.00 FS807.

F=Franchise part. S=SpcNett.

Sub Total (S\$) 4,194.00
 + Margin on L,N Items 10.00% (S\$) 406.40
 Total Parts (S\$) 4,600.40

Lai Huat (Meng Kee) Motor Pte Ltd/SMG9846B/18/12/2019 17:43. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

REPAIR DETAILS

SUPPLEMENTARY

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Jun 2020)
 Parts: 143 OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SMG9846B/16/06/2020 10:15
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Steering rac end RH	0.00	0.00	B1 *254.00 F ✓
2	1		*Steering tie rod RH	0.00	0.00	B1 *261.00 F ✓
3	1		*Front bumper beam RH	0.00	0.00	B1 *14.00 F ✓
4	3		*Front bumper rivets (Original)	0.00	0.00	Mc *3.00 F ✓
5	1		*Pedestrian safety sensor	0.00	0.00	shot *257.00 F ✓
F=Franchise part.						
Sub Total (S\$)						789.00
+ Margin on L,N Items 10.00% (S\$)						78.90
Total Parts (S\$)						867.90

Lai Huat (Meng Kee) Motor Pte Ltd/SMG9846B/16/06/2020 10:15. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray paint (front bumper) <i>reinforcement</i>	New	80.00
<u>Labour Items</u>			
2	To check/erase fault codes	New	100.00
3	To dismantle + renew steering rack + tie rod	New	120.00
4	To knock dents on front bumper reinforcement	New	120.00
Gross Labour Cost (S\$)			420.00

Lai Huat (Meng Kee) Motor Pte Ltd/SMG9846B/16/06/2020 10:15. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

8 6553.30 B4 excess

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

11.00

1 1 OD/TP Case (Insurer)

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

New

300.00

1 To spray paint

New

60.00

Labour Items

2 To check wheel alignment (computerised)

New

20.00

3 To dismantle + renew front tyre RH + wheel balancing

New

300

350.00

4 To dismantle + renew above parts

Gross Labour Cost (S\$)

730.00

Lai Huat (Meng Kee) Motor Pte Ltd/SMG9846B/18/12/2019 17:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

AUTO GERMANY PTE LTD

COMPANY REG NO - 199601763M
7 Ubi Close Singapore 408604 Tel: 69223282 Fax: 69223283



Wir leben Autos.

TAX INVOICE

To : LAI HUAT (MENG KEE) MOTOR PTE LTD
160 SIN MING DRIVE, SIN MING AUTOCITY,
#04-01, #04-02 & #07-03
Singapore 575722

GST Ref No : M289234624
Invoice No : CGI-ASC-19IR11063E
Invoice Date : 20/12/2019
Milage (KM) :
Vehicle Model :
Credit Term : COD

Vehicle No


Parts Charges

S/No	Parts Code	Description	Qty	Unit Price SGD	Discount SGD	Total Price SGD
1	39159652	FRONT BUMPER ASSY	1.00	1,299.00	0.00	✓ 1,299.00 ✓
2	39209137	FRT BUMPER LOWER COVER	1.00	224.00	0.00	✓ 224.00 ✓
3	39108221	RADIATOR GRILLE LOWER	1.00	120.00	0.00	✓ 120.00 ✓
4	39108220	RH FRONT BUMPER DEFLECTOR	1.00	162.00	0.00	✓ 162.00 ✓
5	90450482	RIVET	8.00	2.00	0.00	✓ 16.00 ✓
6	84167103	RH SPLASH SHIELD	1.00	47.00	0.00	✓ 47.00 ✓
7	84167102	LH AIR DEFLECTOR ASSY	1.00	73.00	0.00	✓ 73.00 ✓
8	39098178	ENERGY ABSORBER	1.00	107.00	0.00	✓ 107.00 ✓
9	39138631	PANEL RAD AIR GUIDE LOWER	1.00	40.00	0.00	✓ 40.00 ✓

Remark : SMG9846B INSIGNIA B - Receipt No : 19RC06321E dd 20/12/2019

E & O E

SUB-TOTAL : 2,088.00
ADD 7.00% GST : 146.16
TOTAL WITH GST AMOUNT : 2,234.16



AUTO GERMANY PTE LTD



RAHIM

來發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3
 UEN: 199407592C

TAX INVOICE

EST No. EST0025077
 BIS Motoring P/L

GST Reg No M2-0128609-3
 Page 1 of 1
 Number INV0025283
 Your ref. 999994322
 Job No. 71128
 Our ref AIG191216
 Payment
 Date 16/6/2020

Attn Keif Tan-Hp: 86881311

Vehicle No SMG 9846B
 Vehicle Model : Opel Insignia
 Accident on ... 14/12/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front bumper trim RH	70.00		70.00
1.00	Pc	Front bumper fog lamp RH	253.00		253.00
1.00	Pc	Front bumper fog lamp cover RH	145.00		145.00
1.00	Pc	Front bumper fog lamp chrome trim RH	452.00		452.00
1.00	Pc	Headlamp RH	885.00		885.00
1.00	Pc	Resonator hose	127.00		127.00
1.00	Pc	Front bumper bracket RH	44.00		44.00
1.00	Pc	Front steering rack end RH	254.00		254.00
1.00	Pc	Front steering tie rod RH	261.00		261.00
1.00	Pc	Front bumper beam RH	14.00		14.00
3.00	Pcs	Front bumper rivets (original)	1.00		3.00
1.00	Pc	pedestrian safety sensor	257.00		257.00

Sub-Total 2,765.00
 GST 7.00% 193.55
 Total S\$ 2,958.55

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
 此外，还有先进的 SAICO Deluxe 喷漆烘炉。

Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support ally system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO deluxe oven heater for re-spraying all motor vehicles."