



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS3/INC19019479/Hyf3s2-1

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date : 09-01-2020
189556



ATTN: RAJESWARY

Code : INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 9251S	Veh. Inspected	SJU 2804E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1068828-02	Excess (\$)	0.00
Assign From	MOTOR INCOME INSURANCE	Assign Date	19/12/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053ZEE106150805	Colour	SILVER
Odometer	367709	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	COMFORT MAX	4 mm
L/H Front Tyre	185/65 R15	COMFORT MAX	4 mm
R/H Rear Tyre	195/65 R15	BRIDGESTONE	3 mm
L/H Rear Tyre	195/65 R15	BRIDGESTONE	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/10/2019	Inspection Date	04/11/2019
Survey held at	KENT AUTO SERVICES 2 KAKI BUKIT AVE 2 #01-21 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------