

Ke
Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKZ2124X
TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP-FC

Claim Type: Third Party

Accident Date: 14/12/2019

TP Veh Reg No: SHC7022E

Estimate No: ES2090010/WS

Date: 08 Jan 2020

Policy No: 5105683784-01

Veh Reg No: SKZ2124X

Make/Model: HONDA VEZEL 1.5X
CVT

Chassis No: RU11105764

Engine No: L15B4025767

Reg. Date: 04/12/2015

Estimate Repair Cost to Vehicle No :SKZ2124X

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 RH HEADLAMP	1,820.40	1 PC	1,820.40	
			1,820.40	
		Less 20%	364.08	1,456.32
Labour				
2 REMOVE & REFIX FRT GRILLE,RH HEADLAMP & REALIGN THE SAME	300.00	1 LA	300.00	
3 PUTTY & RESPRAY ON BONNET	320.00	1 LA	320.00	
			620.00	620.00
			Total	S\$ 2,076.32
			Add GST @ 7%	145.34
			Total Amount Payable	S\$ 2,221.66

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: