

Lion City Rentals PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms STG Asia Pacific Insurance Pte Ltd
Attn : MOTOR CLAIMS DEPT
Date: 16/12/2019

ESTIMATE

VEHICLE NO. SLN8931U
CHASSIS NO : JTDKB33FUX03559052
MAKE / MODEL : Toyota Pirus 1.8 Hybrid
DATE OF ACCIDENT : 14/12/2019
YOUR INSURED VEHICLE NUMBER : SLM3385J
MILEAGE : 151784 Km

PARTS DESCRIPTION

QTY	UNIT PRICE	LIST PRICE	PARTS DESCRIPTION
1 PC	\$922.50	\$922.50	Rear back door
1 PC	\$850.00	\$850.00	Rear back door centre garnish cover
1 PC	\$45.80	\$45.80	Rear back door Toyota emblem
1 PC	\$52.30	\$52.30	Rear back door Hybrid emblem
1 PC	\$45.80	\$45.80	Rear back door Pirus emblem
1 PC	\$447.40	\$447.40	Rear back door lock
1 PC	\$24.60	\$24.60	Rear back door lock catch
1 PC	\$356.80	\$423.90	Rear back door weatherstrip
1 PC	\$552.30	\$552.30	Rear bumper
1 PC	\$112.70	\$112.70	Rear bumper center pad
1 PC	\$318.80	\$133.60	Rear bumper LH retainer
1 PC	\$133.60	\$133.60	Rear bumper reinforcement
1 PC	\$303.90	\$148.40	Rear bumper underside LH cover
1 PC	\$356.80	\$356.80	Rear bumper lower cover
1 PC	\$148.40	\$148.40	Rear bumper LH side extension filler
1 PC	\$35.90	\$35.90	Rear bumper RH tow cover
1 PC	\$356.80	\$356.80	Rear end panel
1 PC	\$105.30	\$105.30	Rear end panel top garnish
1 PC	\$433.70	\$433.70	R/L combination lamp
1 PC	\$481.90	\$481.90	R/L lamp len and body
1 PC	\$64.40	\$64.40	R/L fender air vent

1 Bumper and end panel clips / Nec
2 Reverse sensor / short

SPECIAL NETT

1 SET	\$200.00	3	
1 SET	\$260.00	2	
Special Nett Total S\$:			\$460.00
LIST TOTAL S\$:			\$6,216.80
25.00% DISCOUNT S\$:			\$1,554.20
			\$4,662.60

LABOUR CHARGES

- 1 To labour charge for removing rear back door, rear end panel, spare tyre panel, rear bumper and rear bumper reinforcement out to facilitate repairs and replacement of damaged parts. \$1,200.00 ~~800~~ 900
- 2 To respray rear bumper, rear back door, center garnish, rear bumper, end panel, spare tyre panel, R/L side filler \$1,200.00 ~~500~~ 600
- 3 Transfer door mechanism to facilitate repairs and replacement of parts / Remove windscreen \$200.00 ✓
- 4 To conduct a standard of operating procedures post scan test as requirements for hybrid cars upon completion of collision repairs ? \$300.00
- 5 To deactivate and activate high voltage hybrid battery as a requirement for safety precautions \$300.00

LABOUR TOTAL S\$:	<u>\$3,200.00</u>
TOTAL S\$:	\$8,322.60
7% GST	<u>\$582.58</u>
GRAND TOTAL S\$:	<u><u>\$8,905.18</u></u>

Repair days - 6 days

Sun Pin (LKK)

17/12/2019

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: