

辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

A19
18/12/19

15/12/2019

Owner: S.M.H FAMILY FOOD & CATERING PTE LTD

ESTIMATE TO REPAIR TOYOTA C-HR 1.8A - SLT2445P

Not Authorized
11 days 8?
Presumably After Painting
5 days

1pc	front LH fender	R	\$	781.50	X
1pc	front LH fender "HTBRID" emblem	R	\$	85.25	✓
1pc	front LH fender protector	L	\$	374.45	X
1pc	front LH side mirror	CM	\$	781.50	✓
1pc	front LH side mirror cover	Not/CM	\$	281.50	✓
1pc	front LH door	R	\$	1,150.20	✓
2pcs	front LH door hinge @\$121.85	R	\$	243.70	X
2pcs	front LH door frame sticker @\$181.25	R	\$	362.50	✓
1pc	front LH door protector	R	\$	481.50	✓
1pc	front LH door inner rubber		\$	281.50	?
1pc	front LH door inner lock	R	\$	561.25	X
1pc	front LH door glass gear & motor		\$	481.50	?
1pc	rear LH door	R	\$	985.25	✓
2pcs	rear LH door hinge @\$121.85	R	\$	243.70	X
2pcs	rear LH door frame sticker @\$181.25	R	\$	362.50	✓
1pc	rear LH door protector	R	\$	381.50	✓
1pc	rear LH door inner lock	R	\$	561.25	X
1pc	rear LH door inner rubber		\$	182.50	?
1pc	rear LH door glass gear & motor		\$	481.50	?
1pc	rear LH fender protector	R	\$	374.45	✓
1pc	LH side skirt	Not/CM	\$	681.50	✓

less 25%

\$ 10,120.50

\$ 2,530.13

\$ 7,590.38

1pc

LH side skirt (body kit)

R s.nett \$ 780.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

remove & refit LH 2 door glass

\$ 160.00

1201

wiring

\$ 120.00

201

tuffkote

\$ 180.00

601

spray painting

\$ 1,400.00

9001

labour charges

\$ 1,400.00

8001

Total

\$ 11,630.38

