

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CC4/ASM19022472/Hps3q2	
	8 SHENTON WAY AXA TOWERSING		Date:	12/03/2021	
	ATTN:RICHARD		Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMM 6L	Veh. Inspected	SLF 1927X	
	Policy No.	VPA/P2305805	Coverage (\$)	0.00	
	Claim No.	S9M02AFF	Excess (\$)	0.00	
	Assign From		Assign Date	18/12/2019	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	RU31205999	Colour	BLACK	
	Odometer	141842 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16	DOUBLESTAR	5 mm	
	L/H Front Tyre	215/60 R16	DOUBLESTAR	5 mm	
	R/H Rear Tyre	215/60 R16	DOUBLESTAR	5 mm	
	L/H Rear Tyre	215/60 R16	DOUBLESTAR	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	09/12/2019	Inspection Date	18/12/2019	
	Survey held at				
	Repairer	Repairer ASIA MOTORSPORTS SOLUTION PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				