

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS FIRST CAPITAL INSURANCE LTD			Ref : CC4/FCI19022487/Dda3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 25-06-2020 Code: FCI2			
1.	. Policy Particulars :- THIRD PARTY CLAIM				
I	nsured Veh.	SHC 7558B	Veh. Inspected	SHB 6289P	
F	Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
	Claim No.	D19007899MFSH/1	Excess (\$)	0.00	
	Assign From		Assign Date	19/12/2019	
2. Vehicle Particulars & Condition					
ı	Make & Model	MERCEDES BENZ E 220	c.c	2143	
E	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	WDD2120022A724725	Colour	WHITE	
	Odometer	893859	Steering	IN ORDER	
E	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
F	R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L	L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
F	R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L	L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	14/12/2019	Inspection Date	19/12/2019	
	Survey held at	CHUNNI MOTOR WORK PTE LTD			
		BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. 3)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
E	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days				