

INS. CASE OWNER:

CC 6/EQ11902 re ap, A p 23 9

LKK:
IDAC:

Surveyor:

Adnan

DOI:

ASSIGNMENT

18/11/19

Date / Time:

17/11/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBD 2945L

Name of Insured:

ROYAL PETS PRODUCTS

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

10/11/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: MAMBARAN S/O MAMKAM

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

DMPH1219-004104

MSSAN

GUNOS HIGHWAY 2005 PIE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

GBE 7755J

INSRS:
WSP:
Tel:
Liability:
RMKS:

Fatech

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

24/3

GBE 7755J - 5 GBD 2945L - 2
pending acceptance. (offered to TP email).

25/11/2020 - ACC -> MIC - to close

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher: No DV

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / (LOA)

Medical Bill:

PIB:

Reject Instruction:

LOI:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Shi King

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia.:

Repair Cost:

S\$

7169.00

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

600.00 (5 00 x 10 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GLA/LTA Search

S\$

2.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00

Total:

S\$

7771.00

Global Sum S\$:

7,772.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

7,700.00

Name 1:

Fatech Auto Pk Ltd.

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

all
26/3
on

ASSIGNMENT

(Q) TP / WS / TP RES / QO RES / EVA / MV / MV
 To inspect Vehicle No.
 Working No.
 Date
 Location
 Policy No.
 Claim No.
 Sum Insured
 Excess
 (Client's Present)
 Make of Vehicle

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. / Market Value
 IDAC Accident Report Consistent? : Yes or No
 GIA / PR Seen Consistent? : Yes or No
 Est. Repair: 08 days Fee: Yes or No
 Lien Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

BE 7755J 2016 March.
 Type: ☒ M/Cycle / ☒ Car / ☐ Lorry / ☐ Truck / ☐ Trailer or
 Make: Nissan NV200 1597
 Colour: GRY Insured / Std / N / NA
 Sp. Resistor: S2001 Insured / Std / N / NA
 Engine:
 C/Nr: VM20087480
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Mod: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or
 Tyre Size: F: 165R14C
 R: 165R14C
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Fulker.
 Front: R/Bal: 06 mm L/Bal: 06 mm
 Rear: R/Bal: 06 mm L/Bal: 06 mm
 D.O.A.: 18/12/18
 Survey held at: Fastech
 Des. of Damages: Frt ☒ Rear ☐ O/S ☐ N/S ☐ UIC ☐ Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TPEQ.
	US # 6700 Red \$ 12322 / 6570
	MV: 35K
	PV: 2.9K
	Nett: 32.1K

(See Time For Passes) ☐ : Prel. Report
☐ : Final Report

Date/Time For Passes:

Date/Time For Passes:

Reported Party:

Reported Party:

Days Of Repair:

Resurvey No. of Trip:

Survey Pass

Resurvey No.

Resurvey No.

Resurvey No.

Resurvey No.

Resurvey No.

Y/N / End: ☐ Safe / ☐ OK

☐ Insured / ☐ OK

☐ Insured / ☐ OK

☐ Insured / ☐ OK

☐ Insured / ☐ OK

FASTECH AUTO PTE LTD

PAGE 1 OF 2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 21596

Date : 18.12.2019

Vehicle Num : GBE 7755J

Make/Model : NISSAN NV 200 1.6A

Chassis/Engine no :

Accident Date : 16.12.2019

Claim No : 1219-21596

Reference :

Policy No :

TP EQ

Xiao Tony

VM20087480

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Rear boot cover lock catch <i>new</i>	\$ 62.50 +
1 pc	Rear boot cover inner lock <i>Demd</i>	\$ 262.20 562.20
1 pc	Rear boot cover <i>Demd</i>	\$ 1645 2,210.70
1 pc	Rear boot cover centre cover <i>new</i>	\$ 256.30 +
1 pc	Rear boot cover inner board <i>new</i>	\$ 365.50 +
1 pc	Rear logo	\$ 70.00
1 pc	Rear NV 200 emblem <i>new</i>	\$ 76.50
1 pc	Rear vanelt emblem	\$ 68.20
1 pc	Rear taillamp panel RH <i>Demd</i>	\$ 45.70
1 pc	Rear taillamp panel inner RH <i>Regis</i>	\$ 265.50 +
1 pc	Rear bumper <i>Demd</i>	\$ 539 895.20
1 pc	Rear bumper spounge <i>new</i>	\$ 85.30
2 pc	Rear bumper retainer @ 45.70 <i>new</i>	\$ 91.40
1 pc	Rear bumper towing cover <i>new</i>	\$ 39.60 +
1 pc	Rear end panel outer <i>Demd</i>	\$ 572 975.60
1 pc	Rear end panel inner <i>Regis</i>	\$ 1,326.50 +
1 pc	Rear floor panel <i>Regis</i>	\$ 2,265.90 +
1 pc	Rear fender RH <i>Brucked</i>	\$ 204 2,329.00
2 pc	Rear number plate lamp @ 70.70 <i>new</i>	\$ 141.40 +
2 pc	Rear boot cover hinge @ 92.50 <i>new</i>	\$ 185.00 +
1 pc	Rear boot rubber <i>new</i>	\$ 322.00
1 pc	Rear boot rubber top garnish <i>new</i>	\$ 96.00 +
1 pc	Rear spare tyre carrier <i>new + new</i>	\$ 6140.10 410.20 +
1 pc	Rear floor mat	\$ 346.00 +
1 pc	Taillamp RH <i>new</i>	\$ 3526.09 258.70 514.40
1 pc	Rear fender air duct RH <i>new</i>	\$ 77.80 +
1 pc	Rear exhaust pipe	\$ 895.60 +
List item total :		\$ 14,980.00
Discount 10 % :		\$ 1,498.00
		\$ 13,482.00

FASTECH AUTO PTE LTD

PAGE 2 OF 2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 21596

Date : 18.12.2019

Vehicle Num : GBE 7755J

Make/Model : NISSAN NV 200 1.6A

Chassis/Engine no :

Accident Date : 16.12.2019

Claim No : 1219-21596

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

Nett Item :

1 pc	Rear number plate <i>24 m</i>	\$ 45.00 <i>+</i>
1 set	Rear windscreen glass sealant <i>24</i>	\$ 80.00 <i>60</i>
1 set	Rear reversing sensor <i>24</i>	\$ 450.00 <i>200</i>
1 pc	Rear 70 KM sticker <i>3</i>	\$ 15.00 <i>✓</i>
1 pc	Rear 4 pax sticker <i>3</i>	\$ 15.00 <i>✓</i>
Special Nett Total :		\$ 605.00

Labour charge :

To check wiring	\$ 120.00 <i>30</i>
Tuff kote	\$ 200.00 <i>60</i>
To cut rear company lettering	\$ 250.00 <i>+</i>
Remove and refix replace rear windscreen	\$ 250.00 <i>120</i>
Transfer of rear back door mechanism	\$ 160.00 <i>80</i>
Remove and refix upholstery, floor mat etc	\$ 160.00 <i>60</i>
Remove and repalce rear exhaust pipe	\$ 250.00 <i>+</i>
Remove and repalce reverse sensor	\$ 150.00 <i>50</i>
To remove and replace spare part and panel beating	\$ 1,800.00 <i>1200</i>
To spray paint affected portion	\$ 1,600.00 <i>1000</i>
Labour charge total :	\$ 4,940.00

E & O . E

Total Amount \$ 19,027.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No item modification(s) is allowed
- Supplemental claims must be reviewed and is subject to final approval from Insurance Company

FASTECH AUTO PTE LTD Acknowledged by Repairer

Signature:

Date:

Adrian Ling
2/5 12/12/19

08 Payer

Total: 8416.09

4/5 67K

Browse by Category Save Search Print Sort by Date Posted 20 results/page

 ☐ Nissan NV200 1.5M \$36,800 \$6,020 /yr 28-Jan-2016 1,461 cc - Van Available
Fuel Type: Diesel
 Good Condition, Low Mileage Done, Very Well Maintained, In House Loan Available.
[View Details](#) [Contact Seller](#) [Share](#)

 ☐ Nissan NV200 1.5M \$35,688 \$5,760 /yr 26-Feb-2016 1,461 cc - Van Available
Fuel Type: Diesel
 (Cheaper In Town) With Low Depreciation, Ideal For New Business Start Up. 1 Owner Only. New Paintwork. Well Maintain And In Good Condition. Reliable And Low Cost Maintenance. We Offer Various In-house And Bank Loan With Competitive Rate And Ensure You Get T...

 Nissan NV200 1.5M \$38,800 \$5,250 /yr 03-Mar-2016 1,461 cc Van Available

Fuel Type: Diesel

Very Good Condition, Wear/Tear Replaced, Low Mileage. Same Owner, Reloan Case! Used For Stationery Delivery, Front And Reverse Cameras, Floorboard, Solar Film, Performance And Warranty Assured! 100% Fast Loan, Low Interests, Call To Check Availability Before...

SG Motor Link Pte Ltd

Tel: +65 6342 1616 | Email: sgmotorlink@gmail.com

 **Nissan NV200 1.5M** **\$38,800** **\$5,140 /yr** **14-Apr-2016** **1,461 cc** **110,452 km** **Van** **Available**
Fuel Type: Diesel
 Buy Now! Comes With 2 Yrs Free Servicing & 1 Year Free Maintenance In Our In House Workshop! Full Vicom Evaluation Report Provided To Understand The Condition Of The Car, To Give Every Purchase With Assurance & Peace Of Mind.
 Yong Lee Seng Motor
 [Model: L7-Cash/1500](#) [Tags: 2016 Nissan NV200, 2016 Nissan NV200, Nissan NV200, Nissan NV200, Nissan NV200, Nissan NV200, Nissan NV200, Nissan NV200](#)

 **Nissan premieres longer range e-NV200 van**
 Nissan, the world's leading electric vehicle manufacturer, has announced its new longer range e-NV200 van that goes further than ever on a single charge.
[Read this article](#)

 Nissan NV200 1.6A \$39,800 \$6,060 /yr 11-Jul-2016 1,597 cc 89,000 km Van Available
Fuel Type: Petrol
100% Loan Available, Ex-Bankruptcy And Bad Credit Welcome, High Trade In.
Faster Auto Trading
 Product: 15-Dec-2019  Trailer: 2012 Nissan NV200, 2011 Nissan NV200, Nissan NV200, Nissan NV200, Nissan NV200, Nissan NV200, Nissan NV200, Nissan NV200



☐ Nissan NV200 1.5M

\$41,800

\$6,320 /yr

28-Jul-2016

1,461 cc

48,000 km

Van

Available

Fuel Type: Diesel

Fully Tan Chong Service. Buy With A Peace Of Mind. No Repairs Needed, Test Drive To Believe. Loan Available. High Trade In For Your Vehicle. Doorstep Viewing Can Be Arranged. Hurry Call Our Friendly Sales Now.

Net Link Partners Pte Ltd

[View Details](#)
[View Photos](#)
[View Map](#)
[View History](#)

[Compare](#) ☐ Nissan NV200 1.6A \$40,800 \$6,000 /yr 07-Oct-2016 1,597 cc - Van Available

Shu Pei (LKKAUTO)

From: Janice Goh <janice.goh@eqinsurance.com.sg>
Sent: Tuesday, 31 December 2019 9:48 AM
To: Shu Pei (LKKAUTO)
Cc: Admin A; Hsiao Tong (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GBD2955L (OI : EQI - TBA) AND GBE7755J (TP : LKK REF - CC6/EQI19022494/Apb3) on 16.12.2019
Attachments: GBD2955L.PDF

Hi Shu Pei

Attached insured's accident report for your attention.


Thank you.

Janice Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, December 24, 2019 12:06 PM
To: EQI PRS <EQIPRS@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: Direct Settlement - Accident Involving GBD2955L (OI : EQI - TBA) AND GBE7755J (TP : LKK REF - CC6/EQI19022494/Apb3) on 16.12.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle GBE 7755J at M/s Fastech Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:
- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Total Control Panel

[Login](#)

To: eqiprs@eqinsurance.com.sg

[Remove](#) lkkauto.com from my allow list

From: shupeil@lkkauto.com

You received this message because the domain lkkauto.com is on your allow list.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	206R
Vehicle Details	
Vehicle No.:	GBE7755J
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Dec 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.6 A
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	HR16053611D
Chassis No.:	VM20087480
Maximum Power Output:	-
Open Market Value:	\$16,848.00
Original Registration Date:	24 Mar 2016
First Registration Date:	24 Mar 2016
Transfer Count:	2
Actual ARF Paid:	\$843.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Mar 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$4,561.00
COE Rebate Amount:	\$2,859.00
Total Rebate Amount:	\$2,859.00

The information contained herein is correct as at 16 Dec 2019

OK



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 06/04/2020

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBD 2955L (Insd Veh)	Your Ref. No. : DMCPHQ19-004014
	GBE 7755J (TP Veh)	Our Ref. No. : CC6/EQ19022494/Apa3q2
Date of Accident	16/12/2019	

Liability	100%	
Final Repair Cost	: \$ 7,169.00	
Loss of Use	: \$ 600.00	10 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	7,771.00	
Final Settlement Sum	: \$ 7,770.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	FASTECH AUTO PTE LTD	: \$ 7,770.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQ19022494/Apa3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 06-04-2020



Code : EQ1

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 2955L	Veh. Inspected	GBE 7755J
Policy No.	DMCPHQ19-004014	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/12/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VM20087480	Colour	GREY
Odometer	52001	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	165 R14C	FALKEN	6 mm
L/H Front Tyre	165 R14C	FALKEN	6 mm
R/H Rear Tyre	165 R14C	FALKEN	6 mm
L/H Rear Tyre	165 R14C	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/12/2019	Inspection Date	18/12/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 7755J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT COVER LOCK CATCH	NOT NECESSARY	62.50	-
1	REAR BOOT COVER INNER LOCK	DAMAGED	562.20	262.30
1	REAR BOOT COVER	DENTED	2,210.70	1,645.00
1	REAR BOOT COVER CENTRE COVER	NOT NECESSARY	256.30	-
1	REAR BOOT COVER INNER BOARD	NOT NECESSARY	365.50	-
1	REAR LOGO	NECESSARY	70.00	70.00
1	REAR NV 200 EMBLEM	NECESSARY	76.50	76.50
1	REAR VANELT EMBLEM	NECESSARY	68.20	68.20
1	REAR TAILLAMP PANEL RH	DENTED	45.70	45.70
1	REAR TAILLAMP PANEL INNER RH	TO REPAIR SEE LABOUR	265.50	-
1	REAR BUMPER	DEFORMED	895.20	539.00
1	REAR BUMPER SPONGE	CRACKED	85.30	85.30
2	REAR BUMPER RETAINER @\$45.70	NECESSARY	91.40	91.40
1	REAR BUMPER TOWING COVER	NOT NECESSARY	39.60	-
1	REAR END PANEL OUTER	DENTED	975.60	572.00
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	1,326.50	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	2,265.90	-
1	REAR FENDER RH	BUCKLED	2,329.00	2,104.00
2	REAR NUMBER PLATE LAMP @\$70.70	NOT NECESSARY	141.40	-
2	REAR BOOT COVER HINGE @\$92.50	NOT NECESSARY	185.00	-
1	REAR BOOT RUBBER	CUT	322.00	322.00
1	REAR BOOT RUBBER TOP GARNISH	NOT NECESSARY	96.00	-
1	REAR SPARE TYRE CARRIER	NOT NECESSARY	410.20	-
1	REAR FLOOR MAT	NOT NECESSARY	346.00	-
1	TAILLAMP RH	CUT	514.40	258.70
1	REAR FENDER AIR DUCT RH	NOT NECESSARY	77.80	-
1	REAR EXHAUST PIPE	NOT NECESSARY	895.60	-

Report Ref No. CC6/EQ119022494/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,498.00	-814.01
			13,482.00	5,526.09
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
1	SET REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	80.00	60.00
1	SET REAR 70 KM STICKER (SN)	NECESSARY	15.00	15.00
1	REAR 4 PAX STICKER (SN)	NECESSARY	15.00	15.00
1	SET REAR REVERSING SENSOR (SN)	DAMAGED	450.00	200.00
			605.00	290.00
	LABOUR			
	TO CHECK WIRING.		120.00	30.00
	TUFF KOTE.		200.00	60.00
	TO CUT REAR COMPANY LETTERING.	NOT NECESSARY	250.00	-
	REMOVE AND REFIX REPLACE REAR WINDSCREEN.		250.00	120.00
	TRANSFER OF REAR BACK DOOR MECHANISM.		160.00	80.00
	REMOVE AND REFIX UPHOLSTERY ,FLOOR MAT ETC.		160.00	60.00
	REMOVE AND REPLACE REAR EXHAUST PIPE.	NOT NECESSARY	250.00	-
	REMOVE AND REPLACE REVERSE SENSOR .		150.00	50.00
	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TAILLAMP PANEL INNER RH ,REAR END PANEL INNER AND REAR FLOOR PANEL .		1,800.00	1,200.00
	TO SPRAY PAINT AFFECTED PORTION .		1,600.00	1,000.00
			4,940.00	2,600.00
GRAND TOTAL			19,027.00	8,416.09
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,700.00

Report Ref No. CC6/EQ119022494/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.