

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

DATE	TIME	NAME	DATE	TIME
PAY TO		steve	7/2/20	5
PAY NO		KK		
PAY TO				
PAY NO				
PAY TO				
PAY NO				
PAY TO				
PAY NO				
PAY TO				
PAY NO				

Total Labour :	3,793.00
Total Parts :	4,055.40
Total Labour & Parts :	7,848.40
GST @7%:	549.39
Grand Total :	8,397.79

LOSS OF USE = \$120 X 3 DAYS.

NOTE : PLEASE SEEK MANDATE FROM
YOUR PRICIPLE ASAP.

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 53975**
Date Estimated : **02/01/2020**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Ng Chwee Seng
42 Jalan Merlimau

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 308728

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGG9082J	WBAXG12010DX48	30/03/2012	520iA	0
ACCOUNT:				
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper including to make good front left fender and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	1,275.00	0	1,275.00	
To respray front bumper and front left fender	1,730.00	0	1,730.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0	150.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0	150.00	
To replace left B1-Xenon headlight.	408.00	0	408.00	
Sundries.	80.00	0	80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# LH LEVER	6.50	1	0	6.50
FRT BUMPER TRIM PRIMED (PDC)	1,351.15	1	0	1,351.15
HEADLIGHT GASKET SET	34.85	1	0	34.85
LH BI-XENON HEADLIGHT	2,662.90	1	0	2,662.90

SUPPLEMENTARY ITEMS

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 53975**
Date Estimated : **02/01/2020**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Ng Chwee Seng
42 Jalan Merlimau

Singapore 308728

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGG9082J	WBAXG12010DX48	30/03/2012	520iA	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
-------------	----------------------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# LH LEVER	6.50	1	0	6.50

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	6.50
Total Labour & Parts :	6.50