

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 23927

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1506/2019/NS
Date	:	23-Dec-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Anita Boentoro
Address	:	9 Newton Road #12-07 Singapore 307997
Telephone	:	HP +65 98623193
Type of Claim	:	Own Damage Claim
Policy No.	:	2100408855-04
Vehicle No	:	SCW 9208 C
Model Code	:	Audi A6 C7 2.0 TFSI MU 4G
Model / Year	:	Apr-15
Engine No	:	CDN 41705
Chassis No	:	WAUZZZ4G0EN201672
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-Dec-19
Place of Accident	:	9 Newton Road Car Park B1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCW 9208 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To dismantle and renew lhs sill panel trim. To repair lhs sill panel. Re-organise crash management components. Reinstall all parts removed. <i>511 x 1</i>	\$ 1,600.00	<i>500</i>
2	To respray lhs sill panel trim and lhs sill panel. <i>551 x 1</i>	\$ 2,000.00	<i>550</i>
3	To carry out disgnostic check.	S/N \$ 192.00	<i>✓</i>
SUB TOTAL LABOUR CHARGES		: <u>\$ 3,792.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCW 9208 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	SIDE MEMBER - LH / RR	\$	783.00
2	CLIP ATTACHMENT PARTS / MK	4 \$	96.00
3	ADHESIVE TAPE ATTACHMENT PARTS / MK	\$	15.00
4	STONE CHIP / MK	S/N \$	180.00
5	SUNDRIES /	\$	300.00
TOTAL SPARE PARTS		:	\$ 1,374.00
TOTAL LABOUR CHARGES		:	\$ 3,792.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

24/12/19, 10.00 am
Name : Steve (LKK) 00 - Not Author (Cred)
Surveyed Date : Excess - ?
Authorised Date : P/P
Excess Cost : By Bel SJ
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant