Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg GST:201001158E RCB NO:201001158E

AIG ASIA PACIFIC INSURANCE PTE LTD M/S:

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

64193000 TEL:

ATTN: Motor Claim Department

WS Ref:

TP/AIG/AMK

Claim Type: Accident Date:

TP Veh Reg No:

Third Party 19/12/2019

SKN4066E

Nos Asthory

FAX: 64153727

Reany Afa Pains

Estimate No:

ES2090175/AMK

Date:

25 Feb 2020

Policy No:

5110519139 DC

Veh Reg No:

SJJ7811J

Make/Model:

TOYOTA WISH 1.8 A

Chassis No: Engine No:

JTDER12WX03000718

Reg. Date:

1ZZ3135402

25/09/2008

Estimate Repair Cost to Vehicle No: SJJ7811J

	Description	U/Price	Quantity	List Price	Amount
				SS	<u>S\$</u>
	List Price			An sur	
	REAR BUMPER	564.30	1 PC	304.30	
2	REAR BUMPER LH SIDE RETAINER	62.80	1 PC	171 62.80	-
3	REAR BUMPER CLIP	3.89	5 PC	na 19.45	
1	LH TAILLAMP LOWER RETAINER	41.70	1 PC	41.70	
5	TAILGATE LOGO	68.50	1 PC	Na 68.50	-
6	TAILGATE EMBLEM 'AEROTOURER'	51.70	1 PC	Ma 51.70	
			761	0-75 808.45	
			Less 25%	- 202.11	- 17.000000000000000000000000000000000000
	Special Not		(9	1.68	575
20	Special Net	200	1 SET	200.00	7 SHORTE
7	REVERSE SENSOR	200	1361	200.00	-
				200.00	200.00
	Labour				
3	REMOVE & REFIX REAR BUMPER, REVERSE	350.00	1 LA	350.00	2501
	SENSORS, TAILLAMPS; KNOCKING & REPAIR REAR END				
	PANEL & REALIGN TAILGATE THE SAME				0 70
9	PUTTY & RESPRAY REAR BUMPER, REVERSE	600.00	1 LA	600.00	? 50
	SENSORS, TAILGATE, REAR END PANEL & ALL AFFECTED AREAS				
	AREAS			950.00	950.00
		And the second s			
				Total	S\$ 1,756.34
			Add G	ST @ 7%	122.94
			Total Amou	nt Payable	S\$ 1,879.28
				temperary rivers de	THE RESIDENCE OF THE PROPERTY

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey beforelafter spray painting
- To display damaged part(s) during resurvey
- * Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

BORLYN LI

AUTHORISED SIGNATURE

PAPAS: 575.07

00G: 42