



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SJA 637 P
HONDA CIVIC

Guo Qiang @ lkkarito.com

ATTN:	NO	DESCRIPTION - PARTS	QTY	PRICE
	1	REAR WINDSCREEN MOULDING X NN \$406.90.		
	2	BOOTLID X Repair. \$1,329.70		
	3	BOOTLID LOGO (HONDA) / NEC 39.6 \$109.70		
	4	BOOTLID EMBLEM (CIVIC) / NEC 39.6 \$86.40		
	5	BOOTLID EMBLEM (1.6) / NEC 20.9 \$81.90.		
	6	BOOTLID EMBLEM (i.VTEC) / NEC 39.6 \$87.90.		
	7	BOOTLID HANDLE X NN \$418.10		
	8	BOOTLID LOCK SWITCH X NN \$319.70.		
	9	BOOTLID CARPLATE LAMP (L+R) X NN \$226.40		
	10	BOOTLID LAMP (L+R) X NN	2	\$897.40
	11	BOOTLID INNER TRIM X NN	1	\$617.10.
	12	BOOTLID LOCK X NN	1	\$418.40
	13	BOOTLID LOCK COVER X NN	1	\$199.40.
	14	BOOTLID LOCK CATCH X NN	1	\$74.90.
	15	BOOTLID HINGE (L+R) X NN	2	\$242.60.
	16	BOOTLID HINGE COVER (L+R) X NN	2	\$310.40.
	17	BOOTLID STOPPER (L+R) X NN	2	\$79.80.
	18	BOOTLID WEATHERSTRIP R Twi 104.5	1	\$319.60.
	19	TAIL LAMP (L+R) X NN	2	\$1,219.00.
	20	TAIL LAMP PANEL (L+R) X NN	2	\$894.20.
	21	REAR BUMPER / De 638	1	\$1,190.60.
	22	REAR BUMPER RETAINER (L+R) / De 46.2	2	\$296.40
	23	REAR BUMPER REINFORCEMENT BAR X NN	1	NIL.
	24	REAR BUMPER BRACKET (L+R) X NN	2	\$319.20.
	25	REAR BUMPER BEAM X NN	1	NIL.
	26	REAR BUMPER SPONGE X NN	1	NIL.
	27	REAR BUMPER UNDERCOVER X NN	1	\$442.90.
	28	REAR FENDER (L+R) X NN	2	\$2,649.80.
	29	REAR FENDER INNER TRIM (L+R) X NN	2	\$1,294.40
	30	REAR FENDER COWLING (L+R) X NN	2	\$684.60.
	31	REAR FENDER MUDFLAP (L+R) X NN	2	\$219.40.
	32	REAR FENDER AIR VENT (L+R) X NN	2	\$206.20.
	33	REAR QUARTER PANEL (L+R) X NN	2	\$896.40.
	34	END PANEL X Repair. 1	1	\$826.70.
	35	END PANEL TOP GARNISH De 71.5	1	\$294.40
	36	SPAREWHEEL PANEL X NN	1	\$1,071.80
	37	SPAREWHEEL PANEL TOP BOARD X NN	1	\$796.10
	38	SPAREWHEEL PANEL TOP BOARD TOP MAT X NN	1	\$456.70
	39	SPAREWHEEL PANEL TOOLBOX (L+R) X NN	2	\$208.40
	40	EXHAUST PIPE X NN	1	\$1,296.10.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

1

Signature:

1

Date:

1

[illegible]