



JACK CARS

DRIVE WITH ASSURANCE

TAX INVOICE

DATE OF ACCIDENT : 17/12/2019

VEHICLE : SJW4221M

MAKE & MODEL : TOYOTA SIENTA

INSURANCE : FIRST CAPITAL

TAX INVOICE : JC / 20191217 / 4221

PARTS		COST
1.	DOOR – FRONT LEFT	\$ 855
2.	DOOR VISOR – FRONT LEFT	\$ 120
3.	DOOR HINGE – FRONT LEFT (UPPER)	\$ 86
4.	DOOR HINGE – FRONT LEFT (LOWER)	\$ 86
5.	DOOR GARNISH – REAR LEFT	\$105
6.	SIDE MIRROR - LEFT	\$ 665
7.	SIDE MIRROR COVER - LEFT	\$ 76
8.	1/4 GLASS	\$ 120
9.	1/4 GLASS FRAME	\$ 85
10.	1/4 GLASS WEATHER STRIP	\$ 45



JACK CARS

DRIVE WITH ASSURANCE

11.	REAR FENDER - LEFT	\$ 990
12.	REAR FENDER GARNISH - LEFT	\$ 420
13.	REAR FENDER INNER VENT COVER - LEFT	\$ 40
14.	REAR FENDER BRACKET - LEFT	\$ 86
15.	REAR BUMPER	\$ 315
16.	REAR BUMPER GARNISH - LEFT	\$ 115
17.	REAR BUMPER BRACKET - LEFT	\$ 86
18.	FUEL PUMP COVER	\$ 95
19.	MUDGUARD – REAR LEFT	\$ 180
20.	TAIL LAMP – OUTER LEFT	\$ 300
21.	CROSSMEMBER - REAR	\$ 1900
22.	BEARING – REAR LEFT	\$ 475
23.	ABSORBER – REAR LEFT	\$ 200
	SPECIAL NETT	
1.	BUMPER CLIPS	\$ 30
2.	RIM – REAR	\$ 250



JACK CARS

DRIVE WITH ASSURANCE

	LABOUR	
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	\$ 1200
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	\$ 1250
3.	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE	\$ 30
4.	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	\$ 80
5.	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	\$ 60
6.	ANTI RUST TREATMENT	\$ 60
7.	WHEEL BALANCING & ALIGNMENT	\$ 60
	PARTS - 25% :	\$ 5,583.75
	SPECIAL NETT :	\$ 280
	LABOUR :	\$ 2,740
	TOTAL :	\$ 8,603.75
	7% GST :	\$ 602.26
	GRAND TOTAL :	\$ 9,206.01