

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From: PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : CHIN XIAN CHERN Tel : Email :	Customer: GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
---	---

Quotation No. : QO19/12-1236	Quotation Date : 24/12/2019	Terms : 30 DAYS
Vehicle No. : SLR4564B	Chassis No. : JM6BN22A8H0154312	Third Party Insurer : LONPAC
Model : MAZDA 3	Date of Accident : 23/12/2019	
Remarks.:		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>Repair</i>	1	1,175.0000	1,175.00 <i>XR</i>
2	REAR BUMPER TOW COVER <i>X GUC</i>	2	40.0000	80.00 <i>X</i>
3	REAR BUMPER CLIPS <i>40</i>	10	4.0000	40.00 <i>✓</i>
4	REAR BUMPER RIVET <i>206</i>	4	5.0000	20.00 <i>X</i>
5	REAR REINFORCEMENT <i>32</i>	1	545.0000	545.00 <i>X</i>
6	LESS 20%	1	-372.0000	-372.00
7	REAR REVERSE SENSOR <i>X GUC</i>	1	280.0000	280.00 <i>X</i>
8	TO REMOVE&REPLACED REAR REVERSE SENSOR	1	100.0000	100.00 <i>60</i>
9	TO APPLY RUSTPROOFING&TUFFCOATING TREATMENT <i>X m</i>	1	100.0000	100.00 <i>X</i>
10	TO KNOCKING&PANEL BEATING	1	600.0000	600.00 <i>150</i>
11	TO PUTTY&SPRAY PAINT ON THE AFFECTED AREAS	1	600.0000	600.00 <i>200</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total 3,168.00
 GST(7.00%) 221.76
 Total (SGD) 3,389.76

Please conduct the survey at
 Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

410
32
442
2 days