



Your Ref: DM19HO01387-JG

Date: 02nd January 2020

Our Ref: CS1/EQI19022624/Esd3s2

M/s EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: MDB 8193
INSURED VEHICLE: SJT 9048E ACCIDENT DATE: 02/09/2018**

We thank you for your instruction on 02/07/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of MDB 8193 from M/s City Adjuster & Investigators Sdn. Bhd.
- b) Singapore Accident Statement of Vehicle SJT 9048E.
- c) Colour damaged vehicle photographs of MDB 8193.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: MDB 8193
Make & Model	: Subaru Forester
Year of Registration	: 2018
Chassis Number	: PLPSJ5KC5JA837582

2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.