

ASS. REC. BY:

REF: CS/SM019022701 / Ks d3 | n2

Special Instruction:

Sungar: Kenneth

ASSIGNMENT (Office)

From (Person): Grace Teo

of SMO

Date/Time: 26/12/19 @ 3:02pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCW 423G

Insured:

SCA 3228A

at Workshop m/s

Poon Siung SCW

Tel:

6453 7511 / 9616 9634

of

160 Sin Ming Drive #05-13

Policy No:

Claim No:

CMTD1905984 / THE

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/12/2019

CA / REV / REP. / REV 24 HRS 1up

27/12/19

H.O.D. Requirement:

Date/Time: 3:26pm @ 26/12/19

Person Contacted:

Albert

Vehicle IN / OUT

Date/Time

Action/Instruction

SCW 423G - X

SCA 3228A - COG / AKA 1302384A / Koa 303

Ena - 15/12/2013

31/12/19


@ 09:53 am received PA to Henry via email.

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 27/12/19  
 Estimated Cost: \_\_\_\_\_  
 OD  TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SCW 423G  
 at Workshop m/s Poon Siang Seow  
 of 160 Sin Ming Drive # 05-13  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SCW423G Yr Regn: 08 15  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or Wagon  
 Make: Honda Mobile C.C. 1497  
 Colour: M. Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 78518 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MRHDD04870FP000217  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or  
 Brake:  In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD / A/Rim or  
 Tyre Size: F: \_\_\_\_\_ R: 185/65R15  
 BS / DUN / EXNOVA / GY / FS / LIZA /  MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front R/Bal. 8 mm Rear R/Bal. 8 mm  
 L/Bal. 8 mm L/Bal. 8 mm  
 D.O.A. 25/12/19 D.O.I. 27/12/19  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear n/s  
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 03 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS rup  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT



Date / Time	Action / Instruction
3d/12	U/Sing @ 105cl email & confirmed ( \$ 1,130/- Red - 52% )
RECEIVED 31 DEC 2019	

Date/Time, File Page 1 of 7: 31.12.19  
 1) Tyres  
 Date/Time, File Return to? \_\_\_\_\_

: Prel. Report  
 : Final Report

Days Of Repair: 3  
 Resurvey No. of Trip: \_\_\_\_\_

Report Format :  
 Lump Sum / LBJ: (+ \$1,050/- 45)

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Wheel end (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Phone: \_\_\_\_\_  
 Other: \_\_\_\_\_  
 TOTAL: 250



**Auto  
Consultants  
Pte Ltd**

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1905984/THE

Date: 30 December 2019

Our Ref: CS/SMO19022701/Ksd3

The Motor Claims Department  
SOMPO INSURANCE SINGAPORE PL

Dear Sir/Madam,


**PRELIMINARY ADVISE REPORT OF VEHICLE NO. SCW 423G .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/12/2019 at the premises of M/s Poon Siang Seow and have the following to report:-

Workshop Estimate Amount	: <u>SS 2,180.00</u> .
Revised Estimate Amount	: <u>SS 1,072.64</u> .
"Check" Items Amount	: <u>SS -</u> .
Market Value	: <u>SS -</u> .
LTA Reimbursement Value	: <u>SS -</u> .
Nett Value	: <u>SS -</u> .

**Description of Damage:**

The vehicle sustained damages at the rear n/s portion.



**Comments/ Present Status:**

Damages Consistent.

Repair days: 3 days

Yours faithfully

Kenneth Kong  
Automotive Assessor

## Nivitha (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Thursday, 26 December 2019 3:02 PM  
**To:** Albert Poon (sitti1@singnet.com.sg); 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'  
**Cc:** Ye, Yong Kang Melvin; Henry, Irene James  
**Subject:** CMTD1905984/THE - LKK/ SCA3228A & SCW423G ACC ON  
**Attachments:** SCW423G.pdf

### Without Prejudice

Our Reference: CMTD1905984/THE  
Your Reference: SCW423G

Hi Albert,

We acknowledged receipt of your claim documents.

Please be informed that **Ms. Thelma Choo** is the handler of this case who can be contacted at 63224 681/[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg).

As spoken, we have appointed **LKK AUTO** to survey the above vehicle.

-----  
Aside to **LKK AUTO**,

Please make the arrangement to survey for **SCW423G** on a without prejudice basis and revert your report upon completion of survey to my colleague, Ms. Thelma.

Thank you.

Our office will be closed on Christmas, New Year's Eve and New Year Day. Business will resume on 26<sup>th</sup> December 2019 and 2<sup>nd</sup> January 2020 respectively.  
We wish you a Merry Christmas and a Happy New Year!

Best Regards  
**Grace Teo**  
Claims Division  
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)

 **SOMPO**  
INSURANCE

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG**

Download now @



or



<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

-----Original Message-----

From: Albert Poon <[sittil@singnet.com.sg](mailto:sittil@singnet.com.sg)>  
Sent: Thursday, December 26, 2019 2:04 PM  
To: Claims - Motor Survey <[MotorSurvey@sompo.com.sg](mailto:MotorSurvey@sompo.com.sg)>  
Subject: Emailing: SCW423G.pdf

Hi sir  
Please arrange to inspect the vehicle

Thanks

Albert  
M: 96169634, 8458 1169

POON SIANG SEOW  
Sin Ming Autocity  
No.160 Sin Ming Drive, #05-13, S(575722)  
Tel: 6453 7511 Fax:6453 8046  
Email: [sittil@singnet.com.sg](mailto:sittil@singnet.com.sg)

Your message is ready to be sent with the following file or link attachments:

SCW423G.pdf

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto)  
**Sent:** Tuesday, 31 December 2019 9:53 am  
**To:** 'Henry, Irene James'  
**Cc:** SUR; 'Choo, Thelma'; 'Teo, Grace'; assignments  
**Subject:** RE: CMTD1905984/THE - LKK/ SCA3228A & SCW423G ACC ON  
**Attachments:** PRELI ADVISE - SCW 423G .pdf

Dear Henry,

Enclosed preliminary revised of vehicle SCW 423G.

*"Best Wishes for Merry Christmas & Happy New Year 2020"*

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Friday, 27 December 2019 9:56 am  
**To:** 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; 'Choo, Thelma' <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>; 'Teo, Grace' <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>  
**Subject:** RE: CMTD1905984/THE - LKK/ SCA3228A & SCW423G ACC ON

Dear Sir/Mdm,

Noted with thanks.

Wishes you a Merry Christmas & Happy New Year 2020



Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
 Owner ID: 258G

**Vehicle Details**

Vehicle No.: SCW423G  
 Vehicle to be Exported: Yes  
 Intended Deregistration Date: 27 Dec 2019  
 Vehicle Make: HONDA  
 Vehicle Model: MOBILIO SV 1.5 CVT  
 Primary Colour: Black  
 Manufacturing Year: 2015  
 Engine No.: L15Z12100842  
 Chassis No.: MRHDD4870FP000217  
 Maximum Power Output: 88.0 kW (118 bhp)  
 Open Market Value: \$18,935.00  
 Original Registration Date: 05 Aug 2015  
 First Registration Date: 05 Aug 2015  
 Transfer Count: 0  
 Actual ARF Paid: \$18,935.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 04 Aug 2025  
 PARF Rebate Amount: \$14,201.00

**Intended COE Rebate Details**

COE Expiry Date: 04 Aug 2025  
 COE Category: A - Car up to 1600cc & 97kW (130bhp)  
 COE Period(Years): 10  
 QP Paid: \$55,889.00  
 COE Rebate Amount: \$31,324.00  
**Total Rebate Amount: \$45,525.00**

The information contained herein is correct as at 26 Dec 2019

ATTN: - Edmund

rear bumper  
 rear bumper chrome moulding  
 rear bumper edging  
 rear bumper central  
 badge MOBILIO  
 RS  
 VTEC



方商昭噴漆  
**POON SIANG SEOW**  
 Sin Ming Autocity  
 No. 150 Sin Ming Drive  
 #05-13 Singapore 575722  
 Tel: 64537511 Fax: 64538046  
 Email: sitti1@singnet.com.sg

OK

# Enquire Vehicle Transfer Fee

## Vehicle Details

Vehicle No.  
**SCW423G**

Make / Model  
**HONDA / MOBILIO SV 1.5 CVT**

Vehicle Type :  
**P11 - Passenger Station Wagon/Jeep/Land Rover**

Vehicle Attachment 1 :  
**No Attachment**

Vehicle Scheme :  
**Normal**

Chassis No. :  
**MRHDD4870FP000217**

Propellant :  
**Petrol**

Engine No. :  
**L15Z12100842**

Motor No. :  
-

Engine Capacity :  
**1497 cc**

Power Rating :  
-

Maximum Power Output :  
**88.0 kW (118 bhp)**





# 方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.  
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

CHEE CHEE LEONG  
APT BLK 312 SHUNFU ROAD  
#07-243  
SINGAPORE 2057

Dear sir  
Estimate cost of repair to vehicle no. SCW 423G

To supply

1. Rear bumper	<i>Bucler</i>	563.70	✓
2. Rear bumper retainer	<i>in</i>	54.00	X
3. Rear bumper chrome moulding	<i>set</i>	152.70	✓
4. Rear bumper reflector	<i>in</i>	45.00	X
5. Tail gate badge mobilio	<i>in</i>	25.00	—
6. Tail gate badge RS	<i>in</i>	28.40	—
7. Tail gate badge VTEC	<i>in</i>	31.20	—
8. Rear panel	<i>201 in</i>	350.00	X

Labour charges

Rust proofing

Spray painting

Panel beating

	<i>in</i>	80.00	X
		500.00	400/
		600.00	300/

Total *2180/-*

Your faithfully

*[Signature]*  
ALBERT POON

*2430*

*Not Notified  
21 Aug @ 1050h  
Resurvey After Paint  
3 days*

L&K Auto Consultants hence notify the Repairer of the following:

- To ensure below 3 items comply
- To ensure damage report being prepared
- Risk under the vehicle is confirmed
- Third party survey is on a "No Fault Policy" basis
- No slight modification is allowed
- Supplementary report must be submitted and submitted to the relevant insurance company

Approved by Receiver:  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19022701/Ksd3n2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 07-01-2020	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SCA 3228A	Veh. Inspected	SCW 423G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1905984/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	26/12/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA MOBILIO (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MRHDD4870FP000217	Colour	METALLIC BLACK
Odometer	78518	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65 R15	MICHELIN	8 mm
L/H Front Tyre	185/65 R15	MICHELIN	8 mm
R/H Rear Tyre	185/65 R15	MICHELIN	8 mm
L/H Rear Tyre	185/65 R15	MICHELIN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/12/2019	Inspection Date	27/12/2019
Survey held at	POON SIANG SEOW No.160 SIN MING DRIVE #05-13 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCW 423G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	BUCKLED / DENTED	563.70	563.70
1	REAR BUMPER RETAINER	SERVICEABLE	54.00	-
1	REAR BUMPER CHROME MOULDING	SCRATCHED	152.70	152.70
1	REAR BUMPER REFLECTOR	SERVICEABLE	45.00	-
1	TAIL GATE BADGE MOBILIO	NECESSARY	25.00	25.00
1	TAIL GATE BADGE RS	NECESSARY	28.40	28.40
1	TAIL GATE BADGE VTEC	NECESSARY	31.20	31.20
1	REAR PANEL	TO REPAIR SEE LABOUR	350.00	-
	LESS 20% DISCOUNT		-	-160.20
			1,250.00	640.80
<b>LABOUR</b>				
	RUST PROOFING.	NOT NECESSARY	80.00	-
	SPRAY PAINTING.		500.00	400.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR PANEL.		600.00	300.00
			1,180.00	700.00
<b>GRAND TOTAL</b>			<b>2,430.00</b>	<b>1,340.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,050.00</b>

Report Ref No. CS/SMO19022701/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.