

**FW: Finalisation - GBG 6034C / Toyota Dyna**

Jenny Lim <jenny.lim@laihuat.com.sg>

Wed 18/11/2020 5:30 PM

**To:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Dear Denise

For your kind attention.

Thank you.

Kind regards.

Jenny Lim  
for LAI HUAT (MENG KEE) MOTOR PTE LTD  
160 Sin Ming Drive  
#04-01, #04-02 & #07-03  
Sin Ming Autocity  
Singapore 575722  
Tel: 64538110  
Fax: 64596267

---

**From:** Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>

**Sent:** Wednesday, 17 June 2020 3:22 pm

**To:** Jenny Lim <jenny.lim@laihuat.com.sg>

**Subject:** Re: Finalisation - GBG 6034C / Toyota Dyna

Hi Jenny, for labour to repair floor panel I paying 30WU, so is \$126.00. Final repair cost calculated is \$8957.80 B4 excess. Please check and come back to me.

---

**From:** Jenny Lim <jenny.lim@laihuat.com.sg>

**Sent:** Tuesday, 16 June 2020 2:12 PM

**To:** Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>

**Subject:** Finalisation - GBG 6034C / Toyota Dyna

Dear Sir

For your confirmation, please:

- Parts: \$7,249.00 (include supplementary)
- %: -
- SN: \$75.00
- L&M: \$1,675.80
- Sub-total: \$8,999.80
- Less XC: \$350.00
- Total: \$8,649.80

Supporting documents are enclosed for your reference. Photographs will send to you in separate email.

We look forward to hearing from you soon.

Thank you.

Kind regards  
Jenny Lim  
Lai Huat (Meng Kee) Motor Pte Ltd  
Sin Ming Autocity  
160 Sin Ming Drive  
#04-01, #04-02 & #07-03  
Singapore 575722  
Tel: 64538110 Fax: 64596267