

FASTECH AUTO PTE LTD

BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

VEHICLE NO : GBB 6125A

Not Authorized
Hhler
27/12/19
2/5 @ 5100
Hhler

QTY	PARTICULAR	AMOUNT
1 PCS	TAILGATE 1465	\$1,815.00
1 PCS	TAILGATE REAR LOGO 68	\$105.00
1 PCS	TAILGATE 'L200' EMBLEM 82	\$102.00
1 PCS	TAILGATE 'MITSUBISHI' EMBLEM 65	\$85.00
2 PCS	TAILGATE HINGES @\$150.00	\$300.00
1 PCS	TAILGATE LOWER MEMBER 665.00	\$981.00
2 PCS	TAILLAMPS @\$480.00 405x2=810	\$970.00
2 PCS	REAR REFLECTORS @\$205.00 145.00	\$410.00
1 PCS	REAR REVERSE LAMP O/S 366.00	\$395.00
1 PCS	REAR SPARE TYRE CARRIER	\$425.00
2 PCS	REAR STOPPERS @\$60.00 35.00	\$120.00
1 PCS	REAR BODY PANEL O/S	\$2,880.00
1 SET	REAR REVERSE LAMP	\$350.00
		\$8,938.00
	S.NETT	
1 PCS	REAR LOWER SAFETY BAR	\$1,500.00
1 PCS	REAR LICENCE PLATE W/HOLDER	\$50.00
1 SET	REAR REVERSE SENSOR	\$380.00
1 SET	REAR REVERSE CAMERA	\$380.00
1 PCS	REAR 70KM/H STICKER	\$20.00
	TO CHECK WIRING	\$80.00
	TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00
	TO SPRAY RUST PROOFING	\$80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,800.00
	TO PUTTY & SPRAY PAINTING	\$1,500.00
	TOTAL	\$14,808.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3701
6410-9
5128