

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

GBG 1166M

1PC	TAILGATE	1399.70
1PC	TAILGATE ,NISSAN, EMBLEM	141.80
1PC	TAILGATE LOWER MEMBER	
2PCS	TAILGATE LOCK LATCHES @215.00	
2PCS	TAILGATE HINGES \$50.00	
2PCS	TAILGATE 'L' LOWER PANELS @145.00	
2PCS	TAILGATE 'L' LOWER PANEL STOPPERS @121.00	
2PCS	TAILLAMPS @208.00	
2PCS	TAILLAMP BRACKERS @165.00	
2PCS	DROP SIDEGATES @2998.00	
2PCS	DROP SIDEGATE LOWER PANELS @981.00	
1PC	REAR CARGO PANEL FRONT PANEL	
1PC	REAR SPARE TYRE & CHAIN	399.10
1PC	CHASSIS FRAME N/S	

1SET	S.NETT
1SET	70KM/H STICKER & 13 PAX
1SET	REAR REVERSE SENSOR

TO CHECK WIRING
TO DISMANTLE & REPLACING REVERSE SENSOR
TO LIFT UP REAR CARGO DECK FOR REPAIR CHASSIS
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

0.0
1,399.7+
141.8+
416.+
399.1+
=
2,356.6*
2,356.6x
90.0%
2,120.94*

0.0
20.+
200.=
220.*

0.0
20.+
50.+
50.+
680.+
680.=
1,480.*

0.0
2,120.94+
220.+
1,480.=
3,820.94*

4593,050

3,820.94x
80.0%
3,056.752*

1.1 \$880.00 x
\$180.00 50
\$1,800.00 680
\$1,800.00 680
TOTAL \$24,446.00

2356.60
102
2120.94
3820.94