



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676

Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

Page 1 / 2

ESTIMATE

Date	: 23/12/2019	Reg No	: YQ758L
To	: INDIA INTERNATIONAL INSURANCE PTE LTD	Model	: FEB71ER4SDEN C/C MT
Attn.	:	Chassis No	: FEB71EA25158
Office / Mobile	:	Engine No	: 4P10D18750
Email Address	:	Quotation No.	: 102314
		Ref. No.	: GBE/SVC/SALES-4985/191223
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 22/12/2019
Attn.	: ENGKWOKLONG	Policy No.	: 2108926491
Office / Mobile	: +65 6864 0637	Claim Type	: TP CLAIM - III
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

SPECIAL NETT ITEMS

1	J-STRIP	2	250.00
2	BOLT & NUT SET	1	45.00
3	SAFETY LOCK WITH CHAINS	1	65.00

PARTS TOTAL: 360.00

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	300	550.00
2	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	150	300.00

LABOUR TOTAL: 850.00

SUB-TOTAL: 1,210.00

GST @ 7% for \$ 1,210.00 84.70

GRAND TOTAL (S\$): 1,294.70

S/N: 360
L: 450
Total \$ 810

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FUSO

AIRMAN.

bizSAFE
ST & R



ISO 9001



GOLDBELL**ENGINEERING**

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676

Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

Page 2 / 2

ESTIMATE

Date	: 23/12/2019	Reg No	: YQ758L
To	: INDIA INTERNATIONAL INSURANCE PTE LTD	Model	: FEB71ER4SDEN C/C MT
Attn.	:	Chassis No	: FEB71EA25158
Office / Mobile	:	Engine No	: 4P10D18750
Email Address	:	Quotation No.	: 102314
From	: GOLDBELL ENGINEERING PTE LTD	Ref. No.	: GBE/SVC/SALES-4985/191223
Attn.	: ENKWOKLONG	D.O.A.	: 22/12/2019
Office / Mobile	: +65 6864 0637	Policy No.	: 2108926491
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Claim Type	: TP CLAIM - III
		Workshop	: 8 TUAS AVE 18

PREPARED BY : ENKWOKLONGDATE / TIME : 30/12/19 @ 1100SURVEYOR : RameMOBILE NO : 90010068

OFFICE FAX NO : _____

EMAIL ADDRESS : _____

EXCESS AMOUNT : _____

REPAIR TYPE : PART-BY-PART / LUMP SUMAUTHORISATION : AUTHORISED / NOT AUTHORISEDRE-SURVEY : BEFORE PAINT / AFTER PAINTNO. OF DAYS : 1 day

REMARKS : _____

FUSO**AIRMAN.****bizSAFE**
STAR