

ASS. REC. BY:

REF:

08/SMO19022854/Uq d3m2

Special Instructions:

Conveyer: Marcus

## ASSIGNMENT (Office)

From (Person): Grace Teo

of

SMO

Date/Time: 30/12/19 @ 2:19pm

Estimated Cost:

Bill to:

OF / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SKT 7952X

Insured:

FBG 5111 U

at Workshop m/s

Fastech Auto

Tel:

6746 5405

of

1 Kaki Bukit Ave 6 # 01-46 / 48 Autobay

Policy No:

Claim No:

CMTD1906037/GPL

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/12/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3:03pm @ 30/12/19

Person Contacted:

Shi Ying

Vehicle IN / OUT

Date/Time

Action/Instruction

Estimate ✓

SKT 7952 X - X

FBG 5111 U - X

30/12/19 @ 3:31pm informed Grace Teo, we are pending estimate from repairer.  
 06/01/20 @ 4:16pm revised to Grace Teo by email.

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

## ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

KIA 56595

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SK77952X

Yr Regn:

6, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A /

Make:

Toyota harrier

c.c

1986

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

109466

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

25460 0038707

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/55 R 18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/1/20 4/5 # 6500 confirmed with Alan. (Red # 17936. 32, 73%)

RECEIVED 06 JAN 2020

Date/Time, File Pass to?

1) 06/1/2020

Date/Time, File Return to?

2)

☐

Preli. Report

☐

Final Report

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + RS. \$

) Photos

) Others

Report Format :

Lump Sum / I.B.A. (\$

7P

6500

TOTAL

450



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1906037/GPL

Date: 06<sup>th</sup> January 2020

Our Ref: CS/SMO19022854/Uqd3

Without Prejudice

The Motor Claims Department  
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SKT 7952X.**

We thank you for the instruction on 30/12/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/12/2019 at the premises of M/s FASTECH AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>24,436.32</u>
Revised Estimate Amount	: S\$ <u>6,500.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:  
The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:  
Damages consistent.  
We have NOT authorize repair.

Yours faithfully

Marcus Chua  
Licensed Appraiser

**Nivitha (LKK Auto)**

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Monday, 30 December 2019 2:19 PM  
**To:** Ong Shiying; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'  
**Cc:** Jason; Lina Pang; Gnoh, Pau Loong; Ye, Yong Kang Melvin; Henry, Irene James  
**Subject:** CMTD1906037/GPL - LKK/ FBG5111U & SKT7952X DOA: 28.12.2019

Our Reference: CMTD1906037/GPL  
Your Reference: SKT7952X

**Without Prejudice**  
EMAIL ONLY

Date: 30/12/2019

OUR Email: [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)

**Attention:**  
**M/S FASTECH AUTO PTE LTD**

Dear Shi Ying,

**ACCIDENT INVOLVING FBG5111U & SKT7952X ON 28.12.2019**

We refer to your email reply of today.

We will appoint Mr. Marcus Chua of LKK Auto to conduct the survey.

Hi LKK AUTO,

Please make the arrangement to survey for **SKT7952X** on a without prejudice basis and revert your report upon completion of survey to my colleague, Mr. Pau Loong.

Thank you.

Our office will be closed on New Year's Eve (31/12/19) and New Year Day (01/01/20). Business will resume on 2<sup>nd</sup> January 2020.  
We wish you a Happy New Year!

Best Regards  
**Grace Teo**  
Claims Division  
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)



**SOMPO**  
INSURANCE

**A Century of Trust**

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG**

Download now @



or



<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** Ong Shiyong <[shiyong.ong@fastechauto.com.sg](mailto:shiyong.ong@fastechauto.com.sg)>

**Sent:** Monday, December 30, 2019 2:03 PM

**To:** Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>

**Cc:** Jason <[Jason@fastechauto.com.sg](mailto:Jason@fastechauto.com.sg)>; Lina Pang <[Lina.pang@fastechauto.com.sg](mailto:Lina.pang@fastechauto.com.sg)>; Gnoh, Pau Loong <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>; Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>

**Subject:** RE: CMTD1906037/GPL - PRI(NR)/ FBG5111U & SKT7952X DOA: 28.12.2019

*Without Prejudice*

Dear Sir and Madam,

Please arrange (LKK AUTO CONSULTANTS- MARCUS CHUA) to conduct the pre- repair survey.

Thank you.

Regards,

Shiyong

Fastech Auto Pte Ltd

1 Kaki Bukit Avenue 6 #01-46/48/50

Autobay Singapore 417883

Tel: 6746 5405

Fax: 6745 8520

---

**From:** Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

**Sent:** Monday, December 30, 2019 1:55 PM

**To:** Ong Shiyong <[shiyong.ong@fastechauto.com.sg](mailto:shiyong.ong@fastechauto.com.sg)>

**Cc:** Jason <[Jason@fastechauto.com.sg](mailto:Jason@fastechauto.com.sg)>; Lina Pang <[Lina.pang@fastechauto.com.sg](mailto:Lina.pang@fastechauto.com.sg)>; Gnoh, Pau Loong <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>; Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>

**Subject:** CMTD1906037/GPL - PRI(NR)/ FBG5111U & SKT7952X DOA: 28.12.2019

Our Reference: CMTD1906037/GPL

Your Reference: SKT7952X

**Without Prejudice**

EMAIL ONLY

Date: 30/12/2019

OUR Email: [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)

Attention:

M/S FASTECH AUTO PTE LTD

Dear Shi Ying,

**ACCIDENT INVOLVING FBG5111U & SKT7952X ON 28.12.2019**

We refer to your Notice of Accident dated 30/12/2019.

Please be informed that **Mr. Gnoh Pau Loong** is the handler of this case who can be contacted at 63295 217/  
[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg).

Please be informed that we have yet to receive our insured's accident report.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Our office will be closed on New Year's Eve (31/12/19) and New Year Day (01/01/20). Business will resume on 2<sup>nd</sup> January 2020.

We wish you a Happy New Year!

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)



**SOMPO**  
INSURANCE

**A Century of Trust**

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG

Download now @  or 

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** Ong Shiying <[shiyong.ong@fastechauto.com.sg](mailto:shiyong.ong@fastechauto.com.sg)>

**Sent:** Monday, December 30, 2019 12:37 PM

**To:** Claims - Motor Survey <[MotorSurvey@sompo.com.sg](mailto:MotorSurvey@sompo.com.sg)>

**Cc:** Jason <[jason@fastechauto.com.sg](mailto:jason@fastechauto.com.sg)>; Lina Pang <[Lina.pang@fastechauto.com.sg](mailto:Lina.pang@fastechauto.com.sg)>

**Subject:** REQUEST FOR PRE-REPAIR INSPECTION FOR SKT 7952X DOA: 28.12.2019

*Without Prejudice*

Dear Sir/Madam

Your insured's vehicle: FBG 5111U

Date of accident: 28/12/2019

Please arrange Pre-repair Inspection for my client's vehicle no: SKT 7952X.

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS

AMENDMENT NO. 1 OF 2016 paragraph 2.3, please provide a list of at least 10 motor surveyors within 2 days of the notice.

Thank you.

Regards, .

Shiying

Fastech Auto Pte Ltd

1 Kaki Bukit Avenue 6 #01-46/48/50

Autobay Singapore 417883

Tel: 6746 5405

Fax: 6745 8520

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Monday, 6 January 2020 4:16 PM  
**To:** 'Teo, Grace'; assignments  
**Cc:** 'Gnoh, Pau Loong'; 'Ye, Yong Kang Melvin'; 'Henry, Irene James'; SUR  
**Subject:** RE: CMTD1906037/GPL - LKK/ FBG5111U & SKT7952X DOA: 28.12.2019  
**Attachments:** CSSMO1902284Uqd3.pdf

Dear Grace,

Enclosed herewith preliminary advice of SKT 7952X.

**Wishing you a Happiness and Prosperity New Year**

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Monday, 30 December 2019 3:31 PM  
**To:** 'Teo, Grace' <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Gnoh, Pau Loong' <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>; 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CMTD1906037/GPL - LKK/ FBG5111U & SKT7952X DOA: 28.12.2019

Dear Grace,

Please be informed that we have inspected the vehicle SKT 7952X on 30/12/2019.

We are pending for estimate from repairer.

**Best Wishes for Happy New Year 2020**

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Monday, 30 December 2019 3:07 PM  
**To:** 'Teo, Grace' <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Gnoh, Pau Loong' <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>; 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CMTD1906037/GPL - LKK/ FBG5111U & SKT7952X DOA: 28.12.2019

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Monday, 30 December 2019 3:31 PM  
**To:** 'Teo, Grace'; assignments  
**Cc:** 'Gnoh, Pau Loong'; 'Ye, Yong Kang Melvin'; 'Henry, Irene James'; SUR  
**Subject:** RE: CMTD1906037/GPL - LKK/ FBG5111U & SKT7952X DOA: 28.12.2019

Dear Grace,

Please be informed that we have inspected the vehicle SKT 7952X on 30/12/2019.

We are pending for estimate from repairer.

**Best Wishes for Happy New Year 2020**

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Monday, 30 December 2019 3:07 PM  
**To:** 'Teo, Grace' <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Gnoh, Pau Loong' <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>; 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CMTD1906037/GPL - LKK/ FBG5111U & SKT7952X DOA: 28.12.2019

Dear Sir/Mdm,

Thank you for the assignment.

**Wishes you a Merry Christmas & Happy New Year 2020**



Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Teo, Grace [<mailto:grace.teo@sompo.com.sg>]  
**Sent:** Monday, 30 December 2019 2:19 PM  
**To:** Ong Shiying <[shiying.ong@fastechauto.com.sg](mailto:shiying.ong@fastechauto.com.sg)>; 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>;

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Renewal COE Toyota Wish 2.0A



2.88% P.A. \$0 Admin, Monthly  
From \$688, 2 Years Warranty  
Engine And Gearbox.  
GV Credit StarAd

**KA-HUP**

**HOTLINE: 6741 9997**

**VIEW OUR CARS**

**VALUE FOR MONEY**  
**VALUE FOR TIME**  
**A PEACE OF MIND**








Browse by Category

Sort by Date Posted 20 results/page

19 vehicles

harrier

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	harrier		Any	Any	2015	Any	Any	Any	Available
	Toyota	Harrier 2.0A Premium Panoramic	\$87,500	\$12,280 /yr	08-Dec-2015	1,986 cc	-	SUV	Available
Elegant Black SUV, Premium Model With Panoramic Moonroof And Electric Tailgate, This Is Not A Rental/Limousine Unit, One Owner Onl...									
Prime Motor & Leasing									
Posted: 29-Dec-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
	Toyota	Harrier 2.0A Premium Panoramic	\$81,800	\$12,220 /yr	20-Aug-2015	1,986 cc	72,800 km	SUV	Available
1 Owner, Very Well Kept, Regularly Serviced. Beautiful Combination With Leather And Fabric Seat In Diamond Cut Design. In Immaculat...									
Posted: 29-Dec-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
	Toyota	Harrier 2.0A Premium Panoramic	\$83,000	\$11,500 /yr	21-Dec-2015	1,986 cc	59,055 km	SUV	Available
Road Tax Till June 2020. Many Upgraded Accessories. Not PHV Car. Accident Free. No Further Repair Needed. Excellent Condition Very...									
Posted: 28-Dec-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
	Toyota	Harrier 2.0A Premium Panoramic	\$79,800	\$12,500 /yr	25-Jun-2015	1,986 cc	-	SUV	Available
Posted: 27-Dec-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
	Rear LED Bumper Reflector Lamp								
Rear LED Bumper Reflector Lamp (Toyota Harrier 2015 Onwards)									
More info about this product									
	Toyota	Harrier 2.0A Elegance Panoramic	\$76,000	\$12,400 /yr	22-May-2015	1,986 cc	58,000 km	SUV	Available
Direct Owner Selling! Well Taken Care By Careful Owner And Is In Excellent Condition! Very Low Mileage And Underutilize As It Is Seldo...									
Posted: 26-Dec-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
	Toyota	Harrier 2.0A G's Elegance	\$87,000	\$12,550 /yr	24-Jul-2015	1,986 cc	125,000 km	Sedan	Available
The Rare GS Variant Comes With Sportier Outlook, Lowered Suspension, Upgraded Brakes, Reinforced Chassis, Chrome Exhaust Tip, 19" ...									
Posted: 22-Dec-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									

Compare

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	266H
<b>Vehicle Details</b>	
Vehicle No.:	SKT7952X
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER PREMIUM 2.0 A
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	3ZRB516176
Chassis No.:	ZSU600038707
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$29,433.00
Original Registration Date:	23 Jun 2015
First Registration Date:	23 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$23,207.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jun 2025
PARF Rebate Amount:	\$17,405.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	22 Jun 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$71,509.00
COE Rebate Amount:	\$39,190.00
<b>Total Rebate Amount:</b>	<b>\$56,595.00</b>

The information contained herein is correct as at 30 Dec 2019

OK

FASTECH AUTO PTE LTD  
BLK1 KAKI BUKIT AVE 6  
#01-46,48,50 AUTOBAY  
SINGAPORE 417883

Warranty  
This warranty is valid for 12 months or 100,000 km, whichever comes first.  
It covers the cost of parts and labour for any defect in the vehicle.  
Excludes: wear and tear, accident damage, fire, theft, and modifications.  
\* Some warranty items may be excluded and subject to final approval from Insurance Company.

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Not Authorised  
Haha  
30/1/19  
2/5 @ 6500  
5-day.

VEHICLE NO: SKT79524

QTY	PARTICULAR
1 PCS	REAR WINDSCREEN MOULDING 113.10
1 PCS	TAILGATE REAR LOGO
1 PCS	TAILGATE 1712.05
1 PCS	TAILGATE 'HARRIER' EMBLEM 68.10
1 PCS	TAILGATE 'TURBO' EMBLEM
1 PCS	TAILGATE outer garnish 705.10
1 PCS	TAILGATE WEATHERSTRIP
1 PCS	TAILGATE INNER LOCK
1 PCS	TAILGATE INNER TRIM BOARD
2 PCS	TAILGATE DAMPERS @\$580.10
1 PCS	REAR BUMPER DIFUSSER
1 PCS	REAR BUMPER 287.00
1 PCS	REAR BUMPER SPONGE
2 PCS	REAR BUMPER SIDE RETAINERS @\$68.10
1 SET	REAR BUMPER CLIPS
1 PCS	REAR BUMPER SUPPORT BAR
2 PCS	REAR BUMPER SUPPORT BAR BRACKETS @\$165.00
2 PCS	REAR BUMPER SIDE HOLDERS @\$75.50
1 PCS	REAR END PANEL 803.10
1 PCS	REAR END PANEL TOP GARNISH
2 PCS	TAILLAMPS @\$541.10
1 PCS	REAR FLOOR PANEL TOP BOARD
1 PCS	REAR FLOOR PANEL
2 PCS	REAR FENDERS @\$1021.10
2 PCS	REAR FENDER INNER TRIM BOARDS @\$645.20
1 PCS	REAR EXHAUST
4 PCS	REAR BUMPER PDC SENSORS @\$361.10
1 PCS	REAR SMART KEYLESS ANTENNE
1 set	REAR BUMPER reverse sensor
1 SET	S.NETT
1 PCS	REAR FLOOR PANEL INSULATOR
1 PCS	REAR WINDSCREEN SEALANT
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR LICENCE PLATE W/HOLDER

LABOUR CHARGES  
TO CHECK WIRING  
TO DISMANTLE & REPLACING PDC SENSOR  
TO DISMANTLE & REFIX REAR WINDSCREEN  
TO DISMANTLE & REFIX REAR EXHAUST  
TO DISMANTLE & REFIX CUSHION UPHOLSTREY  
TO SPRAY RUST PROOFING  
TO MOUNT VEHICLE ON CAR O-LINER  
TO TRANSFER TAILGATE MECHANISM  
LABOUR FOR PANEL BEATING & REPLACING PARTS  
To putty & spray painting

neu	\$297.54	✓
neu	\$68.10	✓
body	\$1,712.35	✓
neu	\$91.60	✓
NT	\$60.00	X
Cna	\$783.20	✓
neu	\$341.66	✓
shock	\$459.10	✓
neu	\$460.32	✓
11	\$1,160.20	X
11	\$455.00	✓
11	\$955.10	✓
11	\$145.00	✓
NT	\$136.20	IPC
neu	\$50.00	✓
NT	\$1,195.00	X
NT	\$330.00	X
11	\$151.00	X
body	\$831.60	✓
neu	\$360.89	✓
11	\$1,082.20	X
neu	\$820.10	X
11	\$1,166.50	X
11	\$2,042.20	X
NT	\$1,290.40	IPC
11	\$1,185.00	X
11	\$1,444.40	X
11	\$199.20	X
shock	\$250.00	✓
	\$19,226.32	
11	\$180.00	X
neu	\$50.00	40
neu	\$50.00	✓
11	\$50.00	X

(252)  
7659.92  
574494

\$80.00 30  
\$80.00 50  
\$150.00 120  
11 \$100.00 X  
\$150.00 80  
\$120.00 60  
11 \$380.00 X  
\$120.00 80  
\$2,200.00 880  
\$1500.00-1000  
TOTAL @ 24436.32  
24733.86  
8134.94



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19022854/Uqd3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 09-01-2020		
		Code : SMO		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	FBG 5111U	Veh. Inspected	SKT 7952X	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1906037/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	30/12/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HARRIER (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	ZSU600038707	Colour	WHITE	
Odometer	109466	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	235/55 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	235/55 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	235/55 R18	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	28/12/2019	Inspection Date	30/12/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 7952X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR WINDSCREEN MOULDING	NECESSARY	297.54	113.10
1	TAILGATE REAR LOGO	NECESSARY	68.10	68.10
1	TAILGATE	BADLY DENTED	1,712.35	1,712.05
1	TAILGATE "HARRIER" EMBLEM	NECESSARY	91.60	68.10
1	TAILGATE "TURBO" EMBLEM	NOT FITTED	60.00	-
1	TAILGATE OUTER GARNISH	CRACKED	783.20	705.10
1	TAILGATE WEATHERSTRIP	TWISTED	341.66	341.66
1	TAILGATE INNER LOCK	SHORTED	459.10	459.10
1	TAILGATE INNER TRIM BOARD	DEFORMED / TORN	460.32	460.32
2	TAILGATE DAMPERS @\$580.10	NOT NECESSARY	1,160.20	-
1	REAR BUMPER DIFUSSER	DISTORTED	455.00	455.00
1	REAR BUMPER	DISTORTED	955.10	955.10
1	REAR BUMPER SPONGE	TORN	145.00	145.00
2	REAR BUMPER SIDE RETAINERS @\$68.10	N/S BENT	136.20	68.10
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER SUPPORT BAR	NOT FITTED	1,195.00	-
2	REAR BUMPER SUPPORT BAR BRACKETS @\$165.00	NOT FITTED	330.00	-
2	REAR BUMPER SIDE HOLDERS @\$75.50	NOT NECESSARY	151.00	-
1	REAR END PANEL	BADLY DENTED	831.60	803.10
1	REAR END PANEL TOP GARNISH	TWISTED	360.89	360.89
2	TAILLAMPS @\$541.10	NOT NECESSARY	1,082.20	-
1	REAR FLOOR PANEL TOP BOARD	SERVICEABLE	820.10	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,166.50	-
2	REAR FENDERS @\$1021.10	NOT NECESSARY	2,042.20	-
2	REAR FENDER INNER TRIM BOARDS @\$645.20	N/S DEFORMED / TORN	1,290.40	645.20
1	REAR EXHAUST	NOT NECESSARY	1,185.00	-
4	REAR BUMPER PDC SENSORS @\$361.10	NOT NECESSARY	1,444.40	-
1	REAR SMART KEYLESS ANTENNE	NOT NECESSARY	199.20	-
1	SET REAR BUMPER REVERSE SENSOR	SHORTED	250.00	250.00

Report Ref No. CS/SMO19022854/Uqd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-	-1,914.98
			19,523.86	5,744.94
	<b>SPECIAL NETT ITEMS</b>			
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	180.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR LICENCE PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
			330.00	90.00
	<b>LABOUR</b>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		150.00	80.00
	TO SPRAY RUST PROOFING.		120.00	60.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO TRANSFER TAILGATE MECHANISM.		120.00	80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		2,200.00	880.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
			4,880.00	2,300.00
	<b>GRAND TOTAL</b>		<b>24,733.86</b>	<b>8,134.94</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>6,500.00</b>

Report Ref No. CS/SMO19022854/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.