

22/05/2001

ASS. REC. BY:

REF: CS / MSG 19022888/UVF3/

Special Instruction:

Survivor: Marcus

ASSIGNMENT (Office)

From (Person): Chhin Myuk Ri

of

MSG

Date/Time: 30.12.19 15.53 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLF 1598 L

Insured: SL 8984 C

at Workshop m/s Sreanika Motor

Tel: 67472112

of BIK 3018 A Ubi Rd / 101-201 26/12

Policy No: 29114756

Claim No: 615716

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23.12.2019

CA / REV / REP. / REV 24 HRS

mp"

2-Jan-2020

Date/Time: 30.12.19 4.52 p.m

Person Contacted:

Hui Ung

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLF 1598 L - X

SL 8984 C - X

31/03/20

Send preli revised via meriman

ASSIGNMENT

From: Date:

Estimated Cost:

OD / *FP* / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

L7A 43 696

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Type: *M* / Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/1/20 *\$ 1855.28*
Confirmed final ty \$ 1855.28 w/h hulin (Red 4520.31, 719)
(No LS)

RECEIVED 16 JAN 2020

16/1/2020

Date/Time, File Pass to?



Prel. Report

Days Of Repair:

4

1)



Final Report

Resurvey No. of Trip:

2

Survey Fee:

Date/Time, File Return to?

2)

16/1 - typist

Add Fee:



Site Insp (\$

Transportation:



Interview (\$

Photos



Tech. Invs (\$

Others



Weekend (\$

Report Format:

Merimen

Lump Sum / I.B.I. (\$

1855.28

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Dec 2019		30 Dec 2019 15:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	TAN MENG SIANG, ID: S1302468E								
Vehicle Reg. No.:	SLF1598L	Date of Loss:	22/12/2019 20:00 - :59 [40 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 615716	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLL8984C	Policy No. (Claimant):							
		Excess:							
Repairer:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26, 408711 Ubi - Tel: 6747 2112								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd, (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/12/2019]								
Driver/Custodian (Insured):	LYE DER SIAN (), NRIC: S1685824B Email:								
Adj Asg. Remarks:	on WP, Liab: unclear. Choose Marcus Chua - Formteam, Hui Lin 6747 2112								
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date:	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Chhia Nyuk Pui	Date: 03 Jan 2020
<u>Preliminary Advice</u>	

Insured Vehicle No	: SLL8984C	Accident Date	: 22/12/2019
TP Vehicle No	: SLF1598L	Assignment Date	: 30/12/2019
Make	: SUZUKI SWIFT	Est. Duration of Repair	: 4.00
Date of Inspection	: 02/01/2020		
Inspection At	: SPECIALISTS MOTOR PTE LTD (HQ) BLK 3018A UBI ROAD 1, #01-24/25/26 SINGAPORE 408711		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,335.79
Revised Amount	:S\$	2,022.68
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,022.68
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

()	The vehicle is economical/not economical for repair.
(X)	The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	468E
Vehicle Details	
Vehicle No.:	SLF1598L
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2020
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT GLX 1.4 AT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	K14B1131030
Chassis No.:	JSAFZC82S00330891
Maximum Power Output:	70.0 kW (93 bhp)
Open Market Value:	\$11,932.00
Original Registration Date:	16 Aug 2016
First Registration Date:	16 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$11,932.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Aug 2026
PARF Rebate Amount:	\$8,949.00
Intended COE Rebate Details	
COE Expiry Date:	15 Aug 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,503.00
COE Rebate Amount:	\$34,747.00
Total Rebate Amount:	\$43,696.00

The information contained herein is correct as at 02 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/12/2019 11:41
Date Of Accident	22/12/2019 18:30
Exact Location Of Accident	ROUNDAABOUT STADIUM BLVD,STADIUM DR,STADIUM WALK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF1598L
Insured/Policyholder	
Name Of Registered Owner	TAN MENG SIANG
NRIC No	SXXXX468E
Email Address	HEARTSFREEDOM@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97671097
Alternative Phone No	OFFICE-97671097

Vehicle Particulars

Manufacturer	SUZUKI
Model	SWIFT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D-19093882MVPC
Cover Note Number	

Driver

Name of Driver	WONG WEN JIE DOUGLAS
NRIC No	SXXXX858G
Date Of Birth	06/07/1990
Occupation	INDOOR
Date Of Driving Pass	13/06/2011
Driving Experience	8 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96633788
Fax Number	
Contact Number	
Email Address	HEARTSFREEDOM@HOTMAIL.COM

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLF1598L/1912164

26th December 2019

The Manager
Motor Claim Department
MSIG Insurance (Singapore) Pte Ltd
No. 4 Shenton Way #21-01
SGX Centre 2
Singapore 068807

Date Of Accident : 22nd December 2019
Location : Roundabout Stadium Blvd, Stadium Dr, Stadium Walk
Third Party Claim Vehicle No : SLL 8984 C
Repair Cost for Vehicle No : SLF 1598 L Suzuki Swift

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front door assy RH <i>no/Beut</i>	1	690.95	\$ 690.95 ✓
2	Front door weather strip <i>512</i>	1	83.80	\$ 83.80 X
3	Front door lock <i>11</i>	1	195.80	\$ 195.80 X
4	Front door striker <i>11</i>	1	35.90	\$ 35.90 X
5	Front door window regulator gear with motor <i>11</i>	1	384.75	\$ 384.75 X
6	Front door sticker <i>11</i>	1	63.70	\$ 63.70 ✓
7	Front door window moulding <i>11</i>	1	48.55	\$ 48.55 X
8	Rear door RH <i>11</i>	1	659.55	\$ 659.55 X
9	Rear door window stripe <i>11</i>	1	98.45	\$ 98.45 X
10	Rear door hinge upper <i>11</i>	1	39.80	\$ 39.80 X
11	Rear door hinge lower <i>11</i>	1	39.80	\$ 39.80 X
12	Rear door checker <i>11</i>	1	45.99	\$ 45.99 X
13	Rear door sticker <i>11</i>	1	58.35	\$ 58.35 X
14	Rear door window moulding <i>11</i>	1	44.45	\$ 44.45 X
15	Running board panel <i>11</i>	1	300.95	\$ 300.95 X
				\$ 2,790.79

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLF1598L/1912164

26th December 2019

Balance b/f

\$ 2,790.79

Labour Charges :-

Amounts

Cut out, renew, knocking & welding front & rear fender RH, running board panel, front & rear fender RH B pillar RH, remove & install all damage parts, straighten & re-align body

\$ 1,200.00

450

Tuff-kote on damage parts

\$ 120.00

30

Spray painting on damage parts

\$ 1,500.00

600

Remove & refix front & rear door board, front & rear window regulator gear, power window motor, audio speaker

\$ 480.00

80

Check all lighting after repairs

\$ 65.00

20

Initialise power window regulator

\$ 180.00

X

Labour Charge

\$ 3,545.00

Total Amount

6375.59

\$ 6,335.79

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

1. I/We hereby acknowledge receipt of the above bill for repairs.

2. I/We agree to pay the amount of the bill to the repairer within 14 days of the date of this letter.

3. I/We agree to pay the amount of the bill to the repairer within 14 days of the date of this letter.

4. I/We agree to pay the amount of the bill to the repairer within 14 days of the date of this letter.

5. I/We agree to pay the amount of the bill to the repairer within 14 days of the date of this letter.

6. I/We agree to pay the amount of the bill to the repairer within 14 days of the date of this letter.

7. I/We agree to pay the amount of the bill to the repairer within 14 days of the date of this letter.

8. I/We agree to pay the amount of the bill to the repairer within 14 days of the date of this letter.

9. I/We agree to pay the amount of the bill to the repairer within 14 days of the date of this letter.

10. I/We agree to pay the amount of the bill to the repairer within 14 days of the date of this letter.

Acknowledged by Repairer

Signature

Date

p-794.48
152
p-675.28
1-1180.00
1855.28

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472113 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLF1598L/1912164

02nd January 2020

The Manager
Motor Claim Department
MSIG Insurance (Singapore) Pte Ltd
No. 4 Shenton Way #21-01
SGX Centre 2
Singapore 068807

Date Of Accident : 22nd December 2019
Location : Roundabout Stadium Blvd, Stadium Dr, Stadium Walk
Third Party Claim Vehicle No : SLL 8984 C
Repair Cost for Vehicle No : SLF 1598 L Suzuki Swift

Supplementary of Parts

No.	Particulars	Qty	Price	Amounts
1	Front door sticker (from) <i>from AOD</i>	<i>1</i>	39.80	\$ 39.80
				\$ 39.80

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Dec 2019		30 Dec 2019 15:53 Edit Adj Rpt	\$S1,855.28 Edit Estimates	\$S1,855.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	TAN MENG SIANG, ID: S1302468E								
Vehicle Reg. No.:	SLF1598L	Date of Loss:	22/12/2019 20:00 - :59 [40 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 615716	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLL8984C	Policy No. (Claimant):							
		Excess:							
Repairer:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26, 408711 Ubi - Tel: 6747 2112								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 29/01/2020]								
Driver/Customer (Insured):	LYE DER SIANG (), NRIC: S1685824B Email:								
Adj Asg. Remarks:	on WP. Liab: unclear. Choose Marcus Chua - Formteam. Hui Lin 6747 2112								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLF1598L (615716)

[SLL8984C]

TP

TAN MENG SIANG

Dec 22 2019 8:00PM

[GRAB RENTALS PTE LTD]

Specialists Motor Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/01/20 10:58	Video - Accident (TP)	1 Load AVI	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/01/20 11:37	Adjuster Immediate Advice	1 Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/01/20 14:31	Chassis Number	1 Load JPG	
2	02/01/20 14:31	Odometer Reading	1 Load JPG	
3	02/01/20 14:31	General View	1 Load JPG	
4	02/01/20 14:31	General View	1 Load JPG	
5	02/01/20 14:31	General View	1 Load JPG	
6	02/01/20 14:31	General View	1 Load JPG	
7	02/01/20 14:31	General View	1 Load JPG	
8	02/01/20 14:31	General View	1 Load JPG	
9	02/01/20 14:31	General View	1 Load JPG	
10	02/01/20 14:31	General View	1 Load JPG	
11	02/01/20 14:31	General View	1 Load JPG	
12	02/01/20 14:31	General View	1 Load JPG	
13	02/01/20 14:31	General View	1 Load JPG	
14	02/01/20 14:31	General View	1 Load JPG	
15	02/01/20 14:31	General View	1 Load JPG	
16	02/01/20 14:31	General View	1 Load JPG	
17	02/01/20 14:31	General View	1 Load JPG	
18	02/01/20 14:31	General View	1 Load JPG	
19	02/01/20 14:32	General View	1 Load JPG	
20	02/01/20 14:32	General View	1 Load JPG	
21	02/01/20 14:32	General View	1 Load JPG	
22	02/01/20 14:32	General View	1 Load JPG	
23	02/01/20 14:32	General View	1 Load JPG	
24	02/01/20 14:32	General View	1 Load JPG	
25	02/01/20 14:32	General View	1 Load JPG	
26	02/01/20 14:32	General View	1 Load JPG	
27	02/01/20 14:32	General View	1 Load JPG	
28	02/01/20 14:32	General View	1 Load JPG	
29	02/01/20 14:32	General View	1 Load JPG	
30	10/01/20 20:48	Reinspection Photo	1 Load JPG	
31	10/01/20 20:48	Reinspection Photo	1 Load JPG	
32	10/01/20 20:48	Reinspection Photo	1 Load JPG	
33	10/01/20 20:48	Reinspection Photo	1 Load JPG	
34	10/01/20 20:48	Reinspection Photo	1 Load JPG	
35	10/01/20 20:48	After Repair Photo	1 Load JPG	
36	10/01/20 20:48	After Repair Photo	1 Load JPG	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
37	10/01/20 20:48	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
38	10/01/20 20:48	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
39	10/01/20 20:48	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/12/19 10:00	OI Accident Report		Load PDF
2	26/12/19 10:00	TP SLF1598L E-REPORT		Load PDF
3	27/12/19 09:44	IMG_2483		Load JPG <input checked="" type="checkbox"/>
4	27/12/19 09:44	IMG_2489		Load JPG <input checked="" type="checkbox"/>
5	27/12/19 09:44	IMG_2494		Load JPG <input checked="" type="checkbox"/>
6	30/12/19 12:36	email to workshop		Load PDF
7	30/12/19 14:16	email to workshop		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/20 08:41	SUPPLEMENTARY PART		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19022888/UVF3Q2

Date: 17/01/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29114756

Claimant Vehicle No : SLF1598L

Insured Vehicle No : SLL8984C

Date of Loss: 22/12/2019

Nature of Claim: TP Claim No: 615716

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLF1598L

Make & Model: SUZUKI SWIFT, 1.2 (A)

Engine No: K14B1131030

Reg. Date: 16/08/2016 (Man. Year: 2016)

Chassis No: JSAFZC82S00330891

Colour: White

Odometer: 24752 km

Engine Capacity: 1372 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16

Rear Tyre Size: 185/55 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,830.59	675.28	2,155.31	76.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,545.00	1,180.00	2,365.00	66.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,375.59	1,855.28	4,520.31	70.90
+ GST 7.00/7.00% (S\$)	446.29	129.87	316.42	70.90
Nett Amount (S\$)	6,821.88	1,985.15	4,836.73	70.90

INSPECTION

Date of Assignment: 30/12/2019

Date Inspected: 02/01/2020 Inspected At:

Specialists Motor Pte Ltd (HQ)
Blk 3018A Ubi Road 1, #01-24/25/26
Singapore 408711

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2020)
Parts:	144	SUZUKI SWIFT 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF1598L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR ASSY RH	Dented / Bent	690.95 F	*690.95 FL
2	1		*FRONT DOOR WEATHER STRIP	Serviceable	83.80 F	*- FL
3	1		*FRONT DOOR LOCK	Not Necessary	195.80 F	*- FL
4	1		*FRONT DOOR STRIKER	Not Necessary	35.90 F	*- FL
5	1		*FRONT DOOR WINDOW REGULATOR GEAR WITH MOTOR	Not Necessary	384.75 F	*- FL
6	1		*FRONT DOOR STICKER	Necessary	63.70 F	*63.70 FL
7	1		*FRONT DOOR WINDOW MOULDING	Not Necessary	48.55 F	*- FL
8	1		*REAR DOOR RH	Repair	659.55 F	*- FL
9	1		*REAR DOOR WINDOW STRIPE	Not Necessary	98.45 F	*- FL
10	1		*REAR DOOR HINGE UPPER	Not Necessary	39.80 F	*- FL
11	1		*REAR DOOR HINGE LOWER	Not Necessary	39.80 F	*- FL
12	1		*REAR DOOR CHECKER	Not Necessary	45.99 F	*- FL
13	1		*REAR DOOR STICKER	Not Necessary	58.35 F	*- FL
14	1		*REAR DOOR WINDOW MOULDING	Not Necessary	44.45 F	*- FL
15	1		*RUNNING BOARD PANEL	Repair	300.95 F	*- FL
16	1		*FRONT DOOR STICKER (FRONT)	Necessary	39.80 F	*39.80 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,830.59	794.45
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	119.17
Total Parts (\$\$)	2,830.59	675.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT ,RENEW ,KNOCKING & WELDING FRONT & REAR FENDER RH ,RUNNING BOARD PANEL ,FRONT & REAR FENDER RH B PILLAR RH ,REMOVE & INSTALL ALL DAMAGE PARTS ,STRAIGHTEN & REALIGN BODY	New	1,200.00	450.00
2	TUFF-KOTE ON DAMAGE PARTS	New	120.00	30.00
3	SPRAY PAINTING ON DAMAGE PARTS	New	1,500.00	600.00
4	REMOVE & REFIX FRONT & REAR DOOR BOARD ,FRONT & REAR WINDOW REGULATOR GEAR ,POWER WINDOW MOTOR ,AUDIO SPEAKER }	New	480.00	80.00
5	INITIALISE POWER WINDOW REGULATOR)	New	180.00	0.00
6	CHECK ALL LIGHTING AFTER REPAIRS	New	65.00	20.00
Gross Labour Cost (\$\$)			3,545.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >