

简福星摩哆工廠
 KAN FOOK SING MOTOR WORKSHOP
 61 DEFU LANE 12
 SINGAPORE 539147
 TEL: 67479560, 68582126, 68584361
 FAX: 67481006, 62818428

SPF ACCIDENTS CLAIMS SECTION
 AUTOMOTIVE ENGG & MGNT DIV
 POLICE LOGISTICS DEPARTMENT
 NO:1 MOUNT PLEASANT ROAD
 VEHICLE NO POLICE ACADEMY #02-12 SINGAPORE 298333
 ACCIDENT DATE : 27-12-2019 09:15
 THIRD PARTY REF. : QX1634L

INVOICE NO : TEST
 DATE : 17-01-2020

ATTN: SPF ACCIDENTS CLAIMS SECTION

INVOICE COST OF REPAIRS TO VEHICLE SLW6598P CITROEN GC4 PICASSO 1.2 PURETECH

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	REAR BUMPER	980.00
10	REAR BUMPER CLIP @\$5.00	50.00
1	REAR BUMPER REINFORCEMENT	350.00
1	REAR BUMPER REINFORCEMENT PLASTIC	170.00
		<u>1,550.00</u>
	LESS 10 %	155.00
	TOTAL (A)	<u>1,395.00</u>

LABOUR CHARGES

1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	200.00
1	SPRAYPAINTING CHARGES	300.00
	TOTAL (D)	<u>500.00</u>
	TOTAL REPAIR COST :	<u>1,895.00</u>
	G S T % :	132.65
	INVOICE AMOUNT :	<u>2,027.65</u>



簡福星噴多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
 E-mail: ryan@kanfs.net/ patricia@kanfs.net
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

SPF ACCIDENTS CLAIMS SECTION

DATE : 27-12-2019

AUTOMOTIVE ENGG & MGNT DIV
 POLICE LOGISTICS DEPARTMENT
 NO:1 MOUNT PLEASANT ROAD

VEHICLE NO SLW6598P #02-12 SINGAPORE 298333

ACCIDENT DATE : 27-12-2019 09:15

THIRD PARTY REF. : QX1634L

ATTN: SPF ACCIDENTS CLAIMS SECTION

ESTIMATE COST OF REPAIR TO VEICLE SLW6598P CITROEN GC4 PICASSO 1.2 PURETECH

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1 REAR BUMPER / CBA	980.00
2	10 REAR BUMPER CLIP@\$5.00 / MCL.	50.00
		<hr/>
		1,030.00
		LESS 10 %
		<hr/>
		103.00
		<hr/>
		TOTAL (A)
		<hr/>
		927.00
		<hr/>
LABOUR CHARGES		
1	1 TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	480.00
2	1 SPRAYPAINTING CHARGES	480.00
		<hr/>
		TOTAL (D)
		<hr/>
		960.00
		<hr/>
		ESTIMATE TOTAL
		<hr/>
		1,887.00
		<hr/>

2 Days.

ump sum repair.

After repair photos.

Guo Qiang - 82880282

13/01/2020.



簡福星嘍嘍工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
 E-mail: ryan@kanfs.net/ patricia@kanfs.net
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

SPF ACCIDENTS CLAIMS SECTION

DATE : 13-01-2020

AUTOMOTIVE ENGG & MGNT DIV
 POLICE LOGISTICS DEPARTMENT
 NO:1 MOUNT PLEASANT ROAD
 VEHICLE NO POLICE ACADEMY #02-12 SINGAPORE 298333
 ACCIDENT DATE : 27-12-2019 09:15
 THIRD PARTY REF. : QX1634L

ATTN: SPF ACCIDENTS CLAIMS SECTION

SUPPLEMENTARY COST OF REPAIR TO VEICLE SLW6598P CITROEN GC4 PICASSO 1.2 PURETECH

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	REAR BUMPER REINFORCEMENT	350.00 —
1	REAR BUMPER REINFORCEMENT PLASTIC	170.00 —
		<hr/> 520.00
	LESS 10 %	52.00
	TOTAL (A)	<hr/> 468.00
	SUPPLEMENTARY TOTAL	<hr/> 468.00