

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67

AUTOBAY, SINGAPORE 417883

HP: 96709191 FAX: 66840767

AXA Insurance Pte Ltd
8 Shenton Way
#26-01 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Date: 2 January 2020

Accident on 16/12/2019 involving vehicles SMM3672T & SBK8383K
at 496 Geylang Road

Estimate cost of repair to vehicle SMM3672T Mazda 3

1 pc. front bumper
1 pc. front bumper side retainer lh
1 set front bumper clips
1 pc. front fender lh
1 pc. headlamp lh

Deepcut \$ 971.40
u1 \$ 45.80 X
u1 \$ 50.00
u1 \$ 415.00 X
Scr \$ 812.00
\$ 2,294.20
Less 20% \$ 458.84
\$ 1,835.36

Labour Charges:

To check wiring
To spray rust-proofing
To spray ceramic coating
Labour for panel beating, welding & renew parts
Spray painting

\$ 50.00 20
\$ u1 80.00 X
\$ 380.00 200
\$ 350.00 200
\$ 550.00 400

Total: \$ 3,245.36

p-1833-4
202
1466.72
2286.72
203
1829.37

Not Allowed
Lhr
2/5 \$1800/
2/1/20
3dy