



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19022937/Hvd3e2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 08-04-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 9793R	Veh. Inspected	YP 3768T	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1906029/SYH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	30/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FUSO	c.c	7545	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	FM65FMA30132	Colour	BLUE	
Odometer	101059	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	11 R22.5	FALKEN	6 mm	
L/H Front Tyre	11 R22.5	FALKEN	6 mm	
R/H Rear Tyre	11 R22.5 (D)	FALKEN	6/6 mm	
L/H Rear Tyre	11 R22.5 (D)	FALKEN	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/12/2019	Inspection Date	04/02/2020	
Survey held at	TRIPLE-T AUTOMOBILE BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		