



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19022938/Ksf3e2

73 BRAS BASAH ROAD

Date: 14-05-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : AZHARI

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 236Y	Veh. Inspected	SLU 7303C
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1077789-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	31/12/2019

#### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA C-HR (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZYX102087158	Colour	METALLIC BLUE
Odometer	214084 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	APLUS	9 mm
L/H Front Tyre	215/60 R17	APLUS	9 mm
R/H Rear Tyre	215/60 R17	KAPSEN	7 mm
L/H Rear Tyre	215/60 R17	KAPSEN	7 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.  DAMAGES SEE DETAILS.
--

#### 5. General Information

Accident Date	29/12/2019	Inspect Date / Time	31/12/2019 ( 12:59 PM )
Survey held at	385 SIN MING DRIVE		
Repairer	ESTEEM PERFORMANCE PTE LTD		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------