

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX3119E
MOHAMMED ASHRAF BIN MAJID ZINNA
BLK 664 WOODLANDS RING ROAD
10-198
SINGAPORE 730664
TEL : FAX :
PH : 98215784
ATTN :

ESTIMATE BILL

Number : EB00005373
Date : 30/12/2019
Case No : AD00010885
Vehicle No : SKE1071G
Chassis : WVWZZZ13ZCV01785
Year of Mfr : 2011
Policy No :
Model : VOLKSWAGEN
SCIROCCO 1.4L AT

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT BUMPER RETAINER LH	1.0	32.55	0	32.55
2	HEADLAMP LH	1.0	741.95	0	741.95
3	FRONT FENDER LH	1.0	643.15	0	643.15
4	FRONT LOWER ARM LH	1.0	357.25	0	357.25
5	FRONT KNUCKLE ARM LH	1.0	631.60	0	631.60
6	FRONT SHOCK ABSORBER LH	1.0	325.50	0	325.50
7	FRONT WHEEL BEARING LH	1.0	491.60	0	491.60
8	FRONT WHEEL RIM LH	1.0	1,404.10	0	1,404.10
List Price - Parts Sub Total					4,627.70
9	FRONT BUMPER - REPAIR	1.0			
10	BONNET - REPAIR	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					4,627.70
11	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	500.00	0	500.00
12	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00
13	ANTI-RUST COATING	1.0	100.00	0	100.00
14	TO REMOVE & REFIT UNDERCARRIAGE	1.0	350.00	0	350.00
15	TWO WHEEL ALIGNMENT	1.0	80.00	0	80.00
16	WIRING	1.0	40.00	0	40.00
Labour 1 Sub Total					1,870.00
SINGAPORE DOLLARS : SIX THOUSAND NINE HUNDRED FIFTY-TWO AND CENTS FIFTY-FOUR ONLY					0.00
Less Excess					
SUBTOTAL					6,497.70
GST 7.00%					454.84
TOTAL					6,952.54

Date of accident : 24/12/2019 01:00 PM. Place : ARAB STREET TWDS BEACH ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE