



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Ang Ching Sze		Cust No/Name	/ANG CHING SZE
BLK 476 SEMBAWANG DR		Reg No/Reg Date	SLQ2487J / 30/06/2017
#13-301		Date In/Mileage	/ 56583
SINGAPORE 750476		Chassis No	VF7NXXBZTGY541058
Contact No Mobile: 98246045		Engine No	10JBHX3006928
		Make/Model	CIT/DS4 1.6 BLUEHDI 120 EAT6 CROSSBACK S
		Colour/Trim	VLM GRIS PLATINIUM / 3PF BLACK LEATHER

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	27/12/2019/ 18:48	QUD	247 / DonBong	15045

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S SPECIALISTJOB				180.00
WO: 1228696 ACCIDENT TOWED BY KINGDOLLEY FROM FLYOVER LENTOR TO CNC PG				
E PNT88000				2400 3600.00
RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER, REAR TAILGATE, CUT/WELD REAR FLOOR PANEL, REAR END PANEL, REPAIR BOTH REAR FENDER				2100
E PNT88000				300.00
REMOVE AND REPLACE REAR WINDSCREEN GLASS				
M SUNDRY				80 100.00
SUPPLY REAR WINDSCREEN SEALANT				
E PNT88000				80 100.00
REMOVE AND INSTALL PARKING ASSIST				
E PNT88000				300 600.00
REMOVE AND TRANSFER REAR TAILGATE TRIM MECHANISM TO NEW PANEL				1260
E PNT98000				2940.00
PAINT WORK SPRAY REAR FLOOR PANEL, REAR END PANEL, REAR TAILGATE, REAR BUMPER, RH REAR FENDER, LH REAR FENDER AND AFFECTED PORTION				
M SUNDRY				80 320.00
SUPPLY BODY SEALANT				
A 54900099				50 80.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				
A 10028901				300.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				
M SUNDRY				80 180.00
PERFORM RUST PREVENTION				
A 30000001				300 600.00
RENEW FRONT BOTH SEALT BELT AND BUCKLE AND OTHERS ATTACHMENT				
A 30000001				300 600.00
REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIR WORK				

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Ang Ching Size	Cust No/Name /ANG CHING SIZE
BLK 476 SEMBAWANG DR	Reg No/Reg Date SLQ2487J / 30/06/2017
#13-301	Date In/Mileage / 56583
SINGAPORE 750476	Chassis No VF7NXXBHZTG541058
Contact No Mobile: 98246045	Engine No 10JBHX3006928
	Make/Model CIT/DS4 1.6 BLUEHDI 120 EAT6 CROSSBACK S
	Colour/Trim VLM GRIS PLATINIUM / 3PF BLACK LEATHER

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	27/12/2019/ 18:48	QUD	247 / DonBong	15045

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A 30000001				300 600.00
REMOVE AND REPLACE REAR EXHASUT SYSTEM				50.00
M SUNDRY				50.00
SUPPLY REAR NUMBER PLATE WITH FRAME				50.00
M SUNDRY				50.00
SUPPLY C&C LOGO				50.00
M SUNDRY				50.00
SUNDRIES				
M REAR BUMPER de	1.00	843.00	0.00	843.00
M RECESS DOOR de	1.00	59.00	0.00	59.00
M RR SKIRT PANEL de	1.00	562.00	0.00	562.00
M BUMPER MOULDING de	1.00	305.00	0.00	305.00
M SET REINFORFORC de	1.00	64.00	0.00	64.00
M BRACKET SET rec	1.00	120.00	0.00	120.00
M BUMPER BRACKET rec	1.00	131.00	0.00	131.00
M STIFFENER rec	1.00	24.00	0.00	24.00
M RIVET 4,8X20 rec	10.00	8.00	0.00	80.00
M LOW RR PAN FIX rec	1.00	80.00	0.00	80.00
M LOAD FLOOR ASS ? X 500	1.00	687.00	0.00	687.00
M BULKHEAD ? de	1.00	467.00	0.00	467.00
M REAR PANEL ASS ? X 500	1.00	559.00	0.00	559.00
M BADGE AV rec	1.00	52.00	0.00	52.00
M BADGE rec	1.00	65.00	0.00	65.00
M BADGE DS4 rec	1.00	61.00	0.00	61.00
M BADGE CROSSBACK rec	1.00	126.00	0.00	126.00
M TAILGATE ASS de	1.00	1240.00	0.00	1240.00
M TLGT EXT PANEL ? X 500	1.00	641.00	0.00	641.00
M TAILGATE HINGE ? X 500	2.00	87.00	0.00	174.00
M WEATHERSTRIP ? X 500	1.00	147.00	0.00	147.00
M TAILGATE GLASS ? X 500	1.00	523.00	0.00	523.00
M TAILGATE PROP LH X 500	1.00	104.00	0.00	104.00
M TAILGATE PROP RH X 500	1.00	104.00	0.00	104.00
M MOULDING de	1.00	345.00	0.00	345.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

Company Reg No. 200609327M
GST Reg No. MR-6500111-X

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Ang Ching Sze	Cust No/Name /ANG CHING SZE
BLK 476 SEMBAWANG DR	Reg No/Reg Date SLQ2487J / 30/06/2017
#13-301	Date In/Mileage / 56583
SINGAPORE 750476	Chassis No VF7NXBHZTGY541058
Contact No Mobile: 98246045	Engine No 10JBHX3006928
	Make/Model CIT/DS4 1.6 BLUEHDI 120 EAT6 CROSSBACK S
	Colour/Trim VLM GRIS PLATINIUM / 3PF BLACK LEATHER

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	27/12/2019/ 18:48	QUD	247 / DonBong	15045

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SPOILER FLAP <i>X sue</i>	1.00	816.00	0.00	816.00
M SPOILER SEAL <i>X sue</i>	1.00	38.00	0.00	38.00
M TAILGATE FIX <i>nu</i>	1.00	85.00	0.00	85.00
M WING REAR LIGHT RH <i>? 0m</i>	1.00	354.00	0.00	354.00
M WING REAR LIGHT LH <i>? X sue</i>	1.00	354.00	0.00	354.00
M TAILGATE LIGHT RH <i>bo</i>	1.00	165.00	0.00	165.00
M TAILGATE LIGHT LH <i>bo</i>	1.00	165.00	0.00	165.00
M REAR FOG LIGHT RH <i>? X sue</i>	1.00	124.00	0.00	124.00
M REAR FOG LIGHT LH <i>? 1m</i>	1.00	117.00	0.00	117.00
M WDW WIPER MOTOR <i>? X sue</i>	1.00	256.00	0.00	256.00
M MOTOR SPACER <i>? X sue</i>	1.00	10.00	0.00	10.00
M SENSOR <i>nu</i>	1.00	231.00	0.00	231.00
M SENSOR <i>nu</i>	1.00	231.00	0.00	231.00
M SENSOR <i>nu</i>	1.00	231.00	0.00	231.00
M SENSOR <i>? X sue</i>	1.00	231.00	0.00	231.00
M SENSOR SUPPORT <i>nu</i>	4.00	137.00	0.00	548.00
M ASSIST. CAMERA ASS <i>? X sue</i>	1.00	473.00	0.00	473.00
M ASSIST. CAMERA <i>? X sue</i>	1.00	384.00	0.00	384.00
M EXHAUST PIPE <i>bo</i>	1.00	323.00	0.00	323.00
M REAR SILENCER PSA 3382 <i>st</i>	1.00	356.00	0.00	356.00
M FIXING CLAMP DIAM 61 <i>nu</i>	1.00	13.00	0.00	13.00
M FRT PIPE SLEEVE DIAM 50 <i>nu</i>	1.00	139.00	0.00	139.00
M FR RETRACK STAL LH <i>nu</i>	1.00	502.00	0.00	502.00
M FR RETRACK STAL RH <i>nu</i>	1.00	502.00	0.00	502.00
M BELT BUCKLE <i>nu</i>	2.00	143.00	0.00	286.00
M ADJUSTMENT <i>? de</i>	2.00	130.00	0.00	260.00
M TRUNK MAT <i>? de</i>	1.00	290.00	0.00	290.00
M LINING <i>? de</i>	1.00	322.00	0.00	322.00
M ELECTRO UNIT <i>X sue</i>	1.00	392.00	0.00	392.00

Estimate

SURVEYOR NAME: *Rasul - 4p 9000068*SURVEYOR SIGNATURE: *Rasul*DATE: *02/01/19 @ 1640*REMARKS: *2 days*

Confirm & accepted by

Authorized signatory and company stamp

Parts	15,761.00
Labour	9,720.00
Standard Menu	0.00
Specialist Job	180.00
Diagnostics Job	0.00
Sundry/Others	750.00
Total (w/o GST)	26,411.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 30% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

INSURANCE CO.: INDIA

Supplementary Parts For Registration No.: SLQ 2487 J

	<u>Materials</u>	<u>Cost</u>
1	Bumper Moulding RH <i>ne</i> ✓	258.00 ✓
2	Box CDE S/G <i>nw</i> ✓	756.00 ✓
3	Air Puller <i>ne</i> ✓	50.00 ✓
4	Bumper Harness <i>cut</i> ✓	507.00 ✓
5	Jack Box <i>de</i> ✓	170.00 ✓
		<u>1,741.00</u>
	<u>Labour</u>	
1	Spray Paint LH Rear Fender <i>ne</i> ✓	420.00 ✓
		<u>2,161.00</u>
	7% GST	151.27
	Total	<u>2,312.27</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE FRANCE PTE LTD


LARRY SONGCUAN
CUSTOMER SERVICE OFFICER
TEL: 6568 4554
FAX : 6567 5258



TP CLAIM
INDIA
LKK - PASUL

VEHICLE NO : SLQ2847J

MODEL : CIT/DS4 1.6 BLUEHDI

WIP : 15045

Material	:	\$	<u>11,758.00</u>
Labour	:	\$	<u>6,200.00</u>
Sub-Total	:	\$	<u>17,958.00</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>17,958.00</u>
GST 7%	:	\$	<u>1,257.06</u>
Grand Total	:	\$	<u>19,215.06</u>

Finalise By/Date : Ummu ON 25/03/20

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 09 WORKING DAYS + 4 days (2 wk. ends)

* TP VEHICLE NO : GBJ5799U

* LTA search fee \$ 7.45

* claim loss of RENTAL.

PRO-FORMA INVOICE

Company Reg No. 200009327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ang Ching Sze	Cust No/Name /ANG CHING SZE
BLK 476 SEMBAWANG DR	Reg No/Reg Date SLQ2487J / 30/06/2017
#13-301	Date In/Mileage 09/01/2020/ 56583
SINGAPORE 750476	Chassis/Package VF7NXBHZTGY541058 /CC17S5
Contact No Mobile: 98246045	Engine No 10JBHX3006928
	Make/Model CIT/DS4 1.6 BLUEHD1 120 EAT6 CROSSBACK S
	Colour/Trim VLM GRIS PLATINIUM / 3PF BLACK LEATHER



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CTP00073	Cash	25/03/2020/ 11:47	TLD	884 / Lauro Songcuan	15045	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S SPECIALISTJOB ACCIDENT TOWED BY KINGDOLLEY FROM FLYOVER LENTOR TO CNC PG WO: 1228696				180.00 ✓
E PNT88000 RENEW DAMAGED PARTS ON REAR BUMPER, REAR TAILGATE, REPAIR REAR FLOOR PANEL & REPLACE REAR END PANEL				2100.00 ✓
E PNT88000 REMOVE AND REPLACE REAR WINDSCREEN GLASS				300.00 ✓
M SUNDRY SUPPLY REAR WINDSCREEN SEALANT				80.00 ✓
E PNT88000 REMOVE AND INSTALL PARKING ASSIST				80.00 ✓
E PNT88000 REMOVE & TRANSFER REAR TAILGATE TRIM, MECHANISM TO NEW PANEL				300.00 ✓
E PNT98000 SPRAY PAINT REAR FLOOR PANEL, REAR END PANEL, REAR TAILGATE, REAR BUMPER AND AFFECTED PORTIONS				1260.00 ✓
M SUNDRY SUPPLY BODY SEALANT ON AFFECTED AREAS				80.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				50.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				300.00 ✓
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED PORTIONS				80.00 ✓
A 30000001 RENEW FRONT BOTH SEALT BELT AND BUCKLE AND OTHER ATTACHMENT				300.00 ✓
A 30000001 REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIR				300.00 ?
A 30000001 REMOVE AND REPLACE REAR EXHASUT SYSTEM				300.00 ✓
M SUNDRY				50.00 ✓

Payment should be made strictly by cash, NETS or credit cards. Thank you.
 Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Company Reg No. 200809327M
 GST Reg No. MR-0500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ang Ching Sze BLK 476 SEMBAWANG DR #13-301 SINGAPORE 750476 Contact No Mobile: 98246045	Cust No/Name /ANG CHING SZE Reg No/Reg Date SLQ2487J / 30/06/2017 Date In/Mileage 09/01/2020/ 56583 Chassis/Package VF7NXBHZTG541058 /CC17S5 Engine No 10JBHX3006928 Make/Model CIT/DS4 1.6 BLUEHDI 120 EAT6 CROSSBACK S Colour/Trim VLM GRIS PLATINIUM / 3PF BLACK LEATHER

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CTP00073	Cash	25/03/2020/ 11:47	TLD	884 / Lauro Songcuan	15045	0 6200

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
SUPPLY C&C LOGO				20.00 ✓
M SUNDRY				
SUNDRIES				
E PNT98000				420.00 X
SPRAY PAINT LH REAR FENDER → Supp2				
X REAR BUMPER ✓	1.00	843.00	0.00	843.00 ✓
X RECESS DOOR ✓	1.00	59.00	0.00	59.00 ✓
X RR SKIRT PANEL ✓	1.00	562.00	0.00	562.00 ✓
X BUMPER MOULDING ✓	1.00	305.00	0.00	305.00 ✓
X SET REINFORFORC ✓	1.00	64.00	0.00	64.00 ✓
X BRACKET SET ✓	1.00	120.00	0.00	120.00 ✓
X BUMPER BRACKET ?	1.00	131.00	0.00	131.00 ?
X STIFFENER ✓	1.00	24.00	0.00	24.00 ✓
X RIVET 4,8X20 ✓	10.00	8.00	0.00	80.00 ✓
X LOW RR PAN FIX ✓	1.00	80.00	0.00	80.00 ✓
X BADGE AV ✓	1.00	52.00	0.00	52.00 ✓
X BADGE ✓	1.00	65.00	0.00	65.00 ✓
X BADGE DS4 ✓	1.00	61.00	0.00	61.00 ✓
X BADGE CROSSBACK ✓	1.00	126.00	0.00	126.00 ✓
X TAILGATE ASS ✓	1.00	1240.00	0.00	1240.00 ✓
X MOULDING ✓	1.00	345.00	0.00	345.00 ✓
X TAILGATE FIX ✓	1.00	85.00	0.00	85.00 ✓
X TAILGATE LIGHT RH ✓	1.00	165.00	0.00	165.00 ✓
X TAILGATE LIGHT LH ✓	1.00	165.00	0.00	165.00 ✓
X SENSOR ✓	1.00	231.00	0.00	231.00 ✓
X SENSOR ✓	1.00	231.00	0.00	231.00 ✓
X SENSOR ✓	1.00	231.00	0.00	231.00 ✓
X SENSOR SUPPORT ✓	4.00	137.00	0.00	548.00 ✓
X EXHAUST PIPE ✓	1.00	323.00	0.00	323.00 ✓
X REAR SILENCER PSA 3382 ✓	1.00	356.00	0.00	356.00 ✓
X FIXING CLAMP DIAM 61 ✓	1.00	13.00	0.00	13.00 ✓
X FRT PIPE SLEEVE DIAM 50 ✓	1.00	139.00	0.00	139.00 ✓
X FR RETRACK STAL LH ✓	1.00	502.00	0.00	502.00 ✓

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ang Ching Sze BLK 476 SEMBAWANG DR #13-301 SINGAPORE 750476 Contact No Mobile: 98246045	Cust No/Name /ANG CHING SZE Reg No/Reg Date SLQ2487J / 30/06/2017 Date In/Mileage 09/01/2020/ 56583 Chassis/Package VF7NXXBH2TGY541058 /CC17S5 Engine No 10JBHX3006928 Make/Model CIT/DS4 1.6 BLUEHDI 120 EAT6 CROSSBACK S Colour/Trim VLM GRIS PLATINIUM / 3PF BLACK LEATHER

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No		
CTP00073	Cash	25/03/2020/ 11:47	TLD	884 / Lauro Songcuan	15045	0 4612		
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	FR RETRACK STAL RH				1.00	502.00	0.00	502.00 ✓
X	BUMPER MOULDING RH	→	supp.		1.00	258.00	0.00	258.00 X
X	REAR PANEL ASS ?				1.00	559.00	0.00	559.00 ?
X	BULKHEAD ?				1.00	467.00	0.00	467.00 ?
X	REAR FOG LIGHT LH ?				1.00	117.00	0.00	117.00 ?
X	TRUNK MAT ?				1.00	290.00	0.00	290.00 ?
X	LINING ?				1.00	322.00	0.00	322.00 ?
X	BOX CDE S/G				1.00	756.00	0.00	756.00 X
X	AIR PULLER				1.00	50.00	0.00	50.00 X
X	BUMPER HARNESS				1.00	507.00	0.00	507.00 X
X	ADJUSTMENT ?				2.00	130.00	0.00	260.00 ?
X	JACK BOX	→	supp.		1.00	170.00	0.00	170.00 X
X	WING REAR LIGHT LH ?				1.00	354.00	0.00	354.00 ?
Z TEXT								
TP CLAIM INDIA - GBJ5799U								
DOA: 26.12.2019								
SURVEY: RASUL 02.01.20								
09 DAYS								

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	11,758.00		Nett	17,958.00
Labour	5,710.00	7% GST on	17958.00	1257.06
Standard Menu	0.00			
Specialist Job	180.00		Total Payable	19,215.06
Diagnostics Job	0.00		Paid	0.00
Sundry/Others	310.00		Total Due	19,215.06
Total(w/o GST)	17,958.00			

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.