# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

3 Anson Road

51 Ubi Ave 1 #01-25 #16-00 Springleaf Tower Paya Ubi Industrial Park Singapore 079909 Singapore 408933

Attn: Ben Tang Date: 06 Jan 2020

## **Preliminary Advice**

Vehicle No : SLX55Z Accident Date : 18/12/2019

: PORSCHE PANAMERA Make Policy No. : DMPCSN30123919011

**Assignment Date** : 02/01/2020 Excess : S\$2,000.00 Date of Inspection : 03/01/2020 Est. Duration of Repair : 7 days

Inspection At : Etalia Autoworkz Pte Ltd (HQ)

53 UBI AVENUE 1, #01-16 PÁYA UBI IND. PARK

Singapore 408934

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,060.00
Revised Amount	:S\$	18,310.00
Check Items (Estimated)	:S\$	13,090.00
Total	:S\$	31,400.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 85,000.00 COE / PARF Rebate 63,941.00 :S\$

Salvage Value :S\$

Other comments: We are still pending repair cost from repairer.

Margin for Repair :S\$ 21,059.00

### Remarks

( X )

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.