

Exclusive Enterprise Pte Ltd

8 Kaki Bukit Ave 4, #03-50, Premier @ KB, Singapore 415875

Tel : 62459655 / 8653 6483 (Xiang) Fax : 6245 9678

Email : exclusiveenterprise50@gmail.com

TP INS : First Capital

Veh No. : YQ 1543 H

Veh Model : Mits FEB21ER4SDEN

No. List items	QTY	Amount
1 Front Windscreen Moulding ✓ <i>new</i>	1	\$ 464.21 398.80 ✓
2 Front Wiper Garnish X (R)	1	\$ 362.24
3 Front Panel X (R)	1	\$ 2,298.62
4 Front Panel EMBLEM FUSO ✓ <i>new</i>	1	\$ 146.19 76.80 ✓
5 Front Grille ✓ <i>CR4</i>	1	\$ 1,043.04 718.32 ✓
6 Front Grille Emblem CANTER X (SVC)	1	\$ 73.97
7 Front Grille Logo X (SVC)	1	\$ 77.85
8 Front Grille Bracket X (SVC)	1	\$ 24.66
9 Front Corner Panel LH ✓ <i>CR4</i>	1	\$ 478.07 400.70 ✓
10 Front Corner Panel Cap LH X (SVC)	1	\$ 38.20
11 Front Corner Panel Seal LH X (SVC)	1	\$ 34.63
12 Head Lamp LH ✓ <i>CR4</i>	1	\$ 768.21 672.70 ✓
13 Signal Lamp LH ✓ <i>CR4</i>	1	\$ 266.36 197.70 ✓
14 Head Lamp Panel LH ✓ <i>B+</i>	1	\$ 209.96 150.70 ✓
15 Front Step Ganish LH ✓ <i>CR4</i>	1	\$ 595.35 415.40 ✓
16 Front Bumper ✓ <i>cut</i>	1	\$ 1,689.00 948.60 ✓
17 Front Bumper Stay L/R @ \$185.14 4H only ✓ (B+)	2	\$ 370.28 150.20 ✓
18 Front Bumper Cover L/R @ \$322.37 4H only ✓ (CR4)	2	\$ 644.74 280.70 ✓
19 Front Bumper Bracket L/R @ \$154.29 4H only ✓ (B+)	2	\$ 308.58 144.70 ✓
20 Front Door LH ✓ <i>cut</i>	1	\$ 2,652.00 1800.70 ✓
21 Front Door Outer Moulding LH X (SVC)	1	\$ 288.00
22 Front Door Inner Moulding LH ✓ <i>new</i>	1	\$ 288.00 ✓
23 Front Door Inner Trimboard LH ✓ <i>CR4</i>	1	\$ 413.00 ✓
24 Front Door Lock LH ✓ <i>new</i>	1	\$ 305.00 250.20 ✓
25 Front Door Hinge Top & Bottom @ \$199 ✓ (B+) ✓	2	\$ 398.00 210.80 ✓
26 Front Pillar Inner & Outer ✓ <i>B+</i>	1	\$ 1,533.00 1150.50 ✓
27 Front Pillar Inner Trim X	1	\$ 233.00
28 Front Floor Panel ✓ <i>B+</i>	1	\$ 1,879.30 1300.70 ✓
Sub-Total : \$17883.46		
Less 25%		
Total : \$13412.59		

S/N

Exclusive Enterprise Pte Ltd

8 Kaki Bukit Ave 4 , #03-50 , Premier @ KB , Singapore 415875

Tel : 62459655 / 8653 6483 (Xiang) Fax : 6245 9678

Email : exclusiveenterprise50@gmail.com

TP INS : First Capital

Veh No. : YQ1543H

Veh Model : Mits FEB21ER4SDEN

Supplementary

No. List items

1 Front Side Lamp LH ✓ m/s

QTY

1

Amount

\$ 160.00 120.50 ✓

Sub-Total : \$160

Less 25%

Total : \$120

S/N item.

Sealant ✓
 Front Grille Clips ✓
 Front Headlamp Clips ✓
 Front Door Inner Trimboard Clips ✓

1	\$	120.00	60	✓
1Set	\$	50.00	20	✓
1Set	\$	50.00	15	✓
1Set	\$	50.00	40	✓

S/N Total : \$270

Labour

Wire Check ✓
 R&R Front Windscreen ✓
 Transfer Front Door Component From Old To New ✓
 R&R Front DashBoard to Facilitate Repairs ✓
 R&R Front Carpet & Seats to Facilitate Repairs ✓
 Tuff Coat X
 Labour
 Painting

\$	50.00	30	✓
\$	250.00	150	✓
\$	100.00	60	✓
\$	400.00	250	✓
\$	200.00	60	✓
\$	200.00	X	
\$	3,000.00	1400	✓
\$	2,500.00	1400	✓

Labour Total : \$6700

L/S repair
 without problem
 Resurvey after paint

8 day
 Hock ANN
 8531483
 Hock ANN @ Hock Auto.com
 14/1/10
 3.40pm

Resurvey taken
 known after paint
 H. ANN
 15/1/10
 12.15pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Parts	10089.72
Parts less	25%
	7567.29
S/W	135
labour	3350
	11052.29
L/s less	20%
	8841.83
total	↓
L/s →	\$ 8850 #