

Surveyor:

MARCUS

DOI: 03/01/2020

Date / Time : 03/01/2020

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SHB 2588C
 Name of Insured : CITYCAB PTE LTD
 Insured Tel No. : HP: _____
 Excess Sec II : \$\$ D.O.A : 02/01/2020
 Is driver the owner? (YES / ☒ NO) Nature of Accident : _____

Claim No. : _____
 Policy No. : _____
 Make / Model : _____
 Place of Accident : _____

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability : % Final ? Yes / No

GBD 9388C



INSRS:
WSP: JIN AUTO
Tel : _____
Liability : _____
RMKS: _____



INSRS:
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS:
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS:
WSP: _____
Tel : _____
Liability : _____
RMKS: _____

Date/ Time	STAGE	DATE / PIC
GBD 9388C - X	Non-Reporting ltr (1st):	
SHB 2588C - CC3/EQI15015771/H1hv3v2; DOA : 15.09.15	Non-Reporting ltr (2nd):	
<i>Please verify on's v.l.</i>	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>
PRELIMINARY ADVICE Date/Time: _____ Sent By: _____		
FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____		
Repair Cost: \$S (days) Reduction: % Email <input type="checkbox"/> Call <input type="checkbox"/>		
FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email <input type="checkbox"/> Call <input type="checkbox"/>		
Final Liability: % <input checked="" type="checkbox"/> 100 (Agreed / Assessed) BOLA S/N No. : 11(a)		
Repair Cost: \$S		
Loss of Rental (LOR): \$S (days)		
Loss of Use (LOU): \$S (\$ x days)		
Loss of Income (LOI): \$S (\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search: \$S		
Medical: \$S		
Disbursement: \$S (e.g. Tow/ Independent)		
Legal Cost: \$S		
Total: \$S Global Sum \$S:		
FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email <input type="checkbox"/> Call <input type="checkbox"/>		
Payee 1: \$S Name 1: _____		
Payee 2: (Strike if N.A.) \$S Name 2: _____		
Payee 3: (Strike if N.A.) \$S Name 3: _____		

COPY SENT
21/2/2020

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: G3D 9388
 at Workshop m/s: J. n Ave
 of: SH B 2588 C
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 38/1
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time _____ Action / Instruction Left 2008
LA 17915 Sys. 7m.

4/5 - \$5300 (Red \$2113.73/291)

Veh No: G3D 9388 Yr Regn: 7.15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Dyna c.c. 2982
 Colour: silver A/C: Insured / Std / NI / NA
 Sp. Reading: 203075 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KD42318017287
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195-R15 35
 R: 155-R13
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: 6 mm Rear: 6/6 mm
 R/Bal. 6 mm L/Bal. 6/6 mm
 D.O.A. 2/1/20 D.O.I. 3/1/20
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S R.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prel. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) \$ - RS. \$

) Photos: _____

) Others: _____

TOTAL

Report Format: _____

Lump Sum / I.B.I.: (\$ _____)

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

\$150

\$50 + \$50

\$69

\$80

\$399

319

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

not Authorised
N/A

2/545300

7dy.

8/1/2020

First Capital Insurance Limited

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR GBD9388C(TOYOTA DYNA)

1 1 PC	FRONT BUMPER	Dis	\$	685.90	✓
2 1 PC	FRONT BUMPER RH BRACKET	Seal	\$	211.60	✓
3 1 PC	FRONT GRILLE	One	\$	501.20	✓
4 1 PC	FRONT GRILLE SEAL	rel	\$	27.40	✓
5 1 PC	RH FRONT HEADLAMP	Sno	\$	995.70	✓
6 1 PC	FRONT RH CORNER PANEL	Seal	\$	265.50	✓
7 1 PC	FRONT RH DOOR	Dis	\$	1,349.30	✓
8 1 PC	FRONT RH DOOR HINGE	Seal	\$	85.20	✓
9 1 PC	FRONT RH DOOR PILLAR	Bodging	\$	392.70	✓
10 1 PC	FRONT RH STP GARNISH	Sno	\$	318.40	✓
11 1 PC	RH SIGNAL LAMP	AA	\$	43.30	X
12 1 PC	DOOR CHECKER	Tru	\$	127.80	✓
13 1 PC	DOOR LOWER RUBBER	Torn	\$	185.30	✓
14 1 PC	DOOR RUBBER	Torn	\$	186.30	✓
15 1 PC	RH DOOR TRIMBOARD	AA	\$	560.30	X
			\$	5935.90	
less 25%			\$		
16 1 PC	DOOR STICKER	Rel	\$	10.00	✓
17 1 PC	NUMBER PLATE	AA	\$	40.00	X
18	ALIGNMENT		\$	80.00	60
19	TUFF KOTE		\$	120.00	60
20	TO REMOVE & REFIX WINDSCREEN TO RENEW DOOR PILLAR		\$	100.00	80
21	TO REMOVE & REFIX DASHBOARD		\$	380.00	200
22	SPRAY PAINTING		\$	1,250.00	1000
23	LABOUR CHARGE		\$	1,650.00	1200
24	WIRING CHECK		\$	35.00	20
			Total	\$ 7,413.73	

Jin Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To replace damaged parts using warranty
- To replace parts subject to construction
- To replace parts using only "Jalisco Premium" parts
- To replace parts using only "Jalisco Premium" parts
- To replace parts using only "Jalisco Premium" parts

Page 1 of 2

Acknowledged by Repairer

Signature:

Date:

7-5332-30

25%

399922

6629.22

5303



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

The Only 740 Individual Model. Highest Option Model!



Plus We Includes 3 Years
Exclusive Warranty On Engine &
Gearbox. Price Nego.
Jin Heng Locomotive [Starline](#)

HIN LUNG AUTO
 Ho Bee Group
One Stop Car Hub
 Finance, Insurance, Workshop
 New and Used Cars

[Browse by Category](#)
[Sort by Date Posted](#)

15 vehicles

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	Toyota Dyna		Any	Any	2015	Any	Any	Any
	Toyota Dyna	150 3.0M	\$36,800	\$7,050 /yr	26-Mar-2015	2,982 cc	80,172 km	Truck
Fuel Type: Diesel 100% Loan Available! 3 Months Warranty! Free Servicing! 1 Owner, Genuine Low Mileage Done. Smooth & Reliable Engine Gearbox. Guaranteed The Best Workhorse In Town, Highest Resale Value. One Stop Service Provider - Canopy, Box, Tailgate, Chequered Plate Et... Car (S) Pte Ltd Posted: 04-Jan-2020 Tags: 2015 Toyota Dyna, 2015 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna	150 3.0M	\$41,800	\$6,980 /yr	31-Dec-2015	2,982 cc	-	Truck
Fuel Type: Diesel Monthly \$688 Only, 3 Day Delivery, Super Low Mileage, No Need Repair. \$0 Drive Away, Cash Rebate, High Loan With Lowest Interest Available. Super High Trade In. What Are You Waiting For ? Call Now. ABWIN Bus Pte Ltd Posted: 03-Jan-2020 Tags: 2015 Toyota Dyna, 2015 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna	150 3.0M	\$41,800	\$6,990 /yr	29-Dec-2015	2,982 cc	-	Truck
Fuel Type: Diesel 3 Months Warranty! Free Servicing! Low Mileage! 1 Owner Only, Well Maintained Unit. Drive Feels Like A New, Test To Believe! Arrangements Of Canopy, Chequered Plate, Box, Tailgate Accessories Can Be Done! Genuine Low Mileage! High Trade In Quotation Give... Car (S) Pte Ltd Posted: 03-Jan-2020 Tags: 2015 Toyota Dyna, 2015 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna	150 3.0M	\$38,800	\$7,070 /yr	03-Jul-2015	2,982 cc	-	Truck
Fuel Type: Diesel Good Condition. New Paint. Servicing Done. No Repairs Needed, High Trade In Welcome. Price Negotiable. Call Now For More Info And Test Drive! ABWIN (1994) Pte Ltd Posted: 02-Jan-2020 Tags: 2015 Toyota Dyna, 2015 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	10FT Toyota Dyna with Box (For Lease) \$1,400/mth 10FT BOX LORRY FOR RENT / LEASE More info about this vehicle							

[Compare](#)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 303H

Vehicle Details

Vehicle No.: GBD9388C

Vehicle to be Exported: No

Intended Deregistration Date: 06 Jan 2020

Vehicle Make: TOYOTA

Vehicle Model: DYNA 3.0 DIESEL TURBO M/T 2WD LORRY

Primary Colour: Silver

Manufacturing Year: 2014

Engine No.: 1KD2445907

Chassis No.: KDY2318017287

Maximum Power Output: -

Open Market Value: \$27,747.00

Original Registration Date: 20 Jul 2015

First Registration Date: 20 Jul 2015

Transfer Count: 1

Actual ARF Paid: \$1,388.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 19 Jul 2025

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$32,476.00

COE Rebate Amount: \$17,975.00

Total Rebate Amount: \$17,975.00

The information contained herein is correct as at 06 Jan 2020

OK

MOTOR SURVEY ASSIGNMENT

Date 3/1/2020

Our Ref No. SHB2588C

Accident Date 2/1/2020

Claim Type. TP

Insured Vehicle SHB2588C

Third Party Vehicle. GBD 9388C

Survey Location JIN AUTO SERVICES PTE LTD
Contact Person. Blk 14, #01-412, DEFU LANE 10, S(539195)Contact No. JOUIS SEOW
62898126

Fax No. 62870590

Survey Type Without Prejudice

Appointed
Surveyor LKK

Contact Person

Fax No. 68416315

Contact Number. 62863561

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Cc: Workshop JIN AUTO
Cc: TP SolicitorAttention. JOUIS SEOW
TP Solicitor Fax No.

Officer Incharge MERIWA CHIA 03/01/2020

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Nivitha (LKK Auto)

From: Aini Binte <Aini@msfirstcapital.com.sg>
Sent: Friday, 3 January 2020 2:58 PM
To: 'assignments@lkkauto.com'
Cc: 'jouis@jinauto.com.sg'; Merina Chia
Subject: NEW ASSIGNMENT (SHB2588C)
Attachments: FW: PRI REQUEST : FC REF: SHB2588C & GBD9388C ACCIDENT ON 02/01/2020 (626 KB); MOTOR SURVEY ASSIGNMENT.pdf

3.42am @ 3/1/2020

P: Jouis
✓: IN
S: Maring

Dear Sirs

New survey assignment for your handling.

Thanks & Regards

Aini
Motor Claims Department

MS First Capital Insurance Ltd | 36 Robinson Road, City House, #16-01 Singapore 068877 | TEL: 6507 3848
Fax: 6507 3849 | Company Reg. No. 195000106C

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

Nivitha (LKK Auto)

From: IL Process Centre <ilprocesscentre@icicilombard.com>
Sent: Friday, 3 January 2020 12:34 PM
To: Motor Claims
Subject: FW: PRI REQUEST : FC REF: SHB2588C & GBD9388C ACCIDENT ON 02/01/2020
Attachments: SP (7).jpg; SP (21).jpg

From: jouis [mailto:jouis@jinauto.com.sg]
Sent: Friday, January 03, 2020 8:43 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Subject: PRI REQUEST : FC REF: SHB2588C & GBD9388C ACCIDENT ON 02/01/2020

[External Email Warning: Do not click on any attachment or links/URL in this email unless sender is reliable]

Without Prejudice

Dear Sir/Madam

SHB2588C & GBD9388C ACCIDENT ON 02/01/2020

We are assisting owner of GBD9388C handling their third party claim

recovery against SHB2588C Please arrange M/S LKK Auto Consultants Pte Ltd to conduct the third party survey at our workshop.

Kindly establish liability for this case.

Thank you & Best Regards,
Jouis Seow
Jin Auto Services Pte Ltd
Blk 14 #01-412 Defu Lane 10
Singapore 539195.

Tel : (65) 62898126
Fax : (65) 62870590
Email : jouis@jinauto.com.sg

"Please note that this email, including any attachments, is intended solely for the individual (s) or entity (ies) to whom they are addressed and may contain information that is private, confidential and privileged. In

case you are not the intended recipient, request you to notify the sender by reply mail and delete this email, including any copies or attachments from your system. Any unauthorized dissemination, disclosure and/or use of the contents of this communication to anyone is strictly prohibited and punishable by law.

Opinions, conclusions and statements of intent expressed in this e-mail are of the sender and ICICI Lombard General Insurance Company Limited (Company) does not accept liability for the views expressed in this email unless confirmed by an authorized representative of the Company independently of this communication or for the consequences of any viruses that may be transmitted with this email."

Mei Kwan (LKKAuto)

From: Merina Chia <MerinaChia@msfirstcapital.com.sg>
Sent: Wednesday, 8 January, 2020 10:04 AM
To: Mei Kwan (LKKAuto)
Cc: Admin A; Jia Le (LKK Auto)
Subject: RE: NEW ASSIGNMENT (SHB2588C) // EXPRESS SETTLEMENT
Attachments: SAS2730557-NEW1.pdf

Categories: HMK

Dear Mei Kwan,

Please refer to the attached SAS report for your perusal.

Thank you.

Best Regards,
Merina Chia (Ms)
Motor Claims Department

MS First Capital Insurance Ltd | 36 Robinson Road, City House #16-01 Singapore 068877 | Tel: 6507 3848 | DID : 6507 3856 | Fax No. : 6507 3849 | Email: merinachia@msfirstcapital.com.sg | Company Regn. No. 195000106C A Member of Insurance Group

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to <http://www.msfirstcapital.com.sg> for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

-----Original Message-----

From: Merina Chia
Sent: Monday, 6 January 2020 3:15 PM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Jia Le (LKK Auto) <JiaLe@lkkauto.com>
Subject: RE: NEW ASSIGNMENT (SHB2588C) // EXPRESS SETTLEMENT

Dear Mei Kwan,

GIA report reported by our insured was incomplete.

I will forward the GIA report to you once our insured done the addendum.

Thank you.

Best Regards,
Merina Chia (Ms)
Motor Claims Department

"Wishing you a Happiness and Prosperity New Year"

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Aini Binte [mailto:Aini@msfirstcapital.com.sg]

Sent: Friday, 3 January 2020 2:58 PM

To: 'assignments@lkkauto.com' <assignments@lkkauto.com>

Cc: 'jouis@jinauto.com.sg' <jouis@jinauto.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>

Subject: NEW ASSIGNMENT (SHB2588C)

Dear Sirs

New survey assignment for your handling.

Thanks & Regards

Aini

Motor Claims Department

MS First Capital Insurance Ltd | 36 Robinson Road, City House, #16-01 Singapore 068877 | TEL: 6507 3848

Fax: 6507 3849 | Company Reg. No. 195000106C

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

This email has been checked for viruses by AVG.

<https://www.avg.com>

Jin Auto Services Pte Ltd

**Blk 14 Defu Lane 10 #01-412 Singapore
539195**

Tel:62898126 Fax :62870590

Business Registration No:200704370C GST Registration No:200704370C

Date: 14/01/2020

Your Ref : SHB2588C

First Capital Insurance Ltd

36 Robinson Road,
#16-01 City House
Singapore 068877
Motor Claims Department

WITHOUT PREJUDICE

Dear Sir/Madam

SHB2588C & GBD9388C ACCIDENT ON 02/01/2020

We are instructed by the owner : GBD9388C to write, negotiate and settle claim on his behalf for the above mentioned accident. We are now seeking the total amount of claim as follow:

1) Repair cost	\$	5671.00
2) RENTAL		963.00

	SS	6634.00
		=====

The following documents are enclosed to support our claims:

GBD9388C rental bill and repair bill

Yours faithfully

Jouis Seow

jouis@jinauto.com.sg

HUI WANG ENTERPRISE PTE LTD

BLK 5, DEFU LANE 10, #01-570 / 576, SINGAPORE 539186

TEL: 6286 4541, 6283 0717 FAX: 6281 0647

EMAIL: Huiwang576@Gmail.com

REG. NO. 201426468N GST No. 201426468N

TAX INVOICE

To :

Jin Auto

Invoice No. : 00018151

Date : 14/01/2020

Reference :

Vehicle Number :

Repair Date :

Attn : Jin Auto

DESCRIPTION	AMOUNT
Rental of GBF4207P From 03/1/2020 to 09/1/2020	\$900.00
INTEREST AT THE RATE 1.5% PER MONTH WILL BE CHARGE ON OVERDUE ACCOUNTS	
Sub-Total	\$900.00
GST 7%	\$63.00
Total Payable	\$963.00

Payment Options

Please note that if you wish to make payment via Bank Transfer or Cheque, indicate the Bank, Amount Transfer & Invoice Number in the email so we are able to confirm that the funds came through. The email can be sent to Accounts@HuiWangEnterprise.com

OCBC SGD Account

Bank Name: Oversea-Chinese Banking Corporation Limited

Account Number: 689 021 568 001

Account Name: Hui Wang Enterprise Private Limited

Received By _____

Issued By _____

E. & O. E.



輝皇企業私人有限公司

HUI WANG ENTERPRISE PTE LTD

BLK 5, DEFU LANE 10, # 01-576, SINGAPORE 539186
TEL: 6286 4541, 6283 0717 FAX: 6281 0647

No 22301

Co. Reg. No. 201426468N

噸度, 貨車出租, 車輛檢查, 修理, 噴漆, 打嗎呷等
LORRY, VAN RENTAL, VEHICLES INSPECTION, REPAIRING, SPRAY PAINTING, PANEL BEATING, INSURANCE CLAIM, ETC.

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULARS

I/We

Yu Yu Interior Design P/L

I/C No:

If Different From Section 1

of

Tel No:

hereby confirm having agreed to hire this day from Messrs Hui Wang Enterprise Pte Ltd the undermentioned NEW/USED Vehicles at the rental fees as shown below and I agree that I shall be responsible for the first payment of \$2,000.00 / \$3,000.00 for any loss and/or damaged caused to the said vehicle and I shall be responsible to pay Messrs Hui Wang Enterprise Pte Ltd the value of the vehicle in the event of the Vehicle being CONFISCATED or any loss resulting from THEFT or DESTRUCTION of the said vehicle whether or not such damage or loss is caused by negligence or by any breach by me of the terms and conditions of hire, hereinafter mentioned and printed.

Vehicle Regd. No. 車號 GBF4207P		(Diesel / Petrol)	
Section 1 Hirer's And / Or Driver's Particulars 租車者 / 駕駛員個人記錄		日期及取車時間 Date & Time Out: 3/1/20 4pm.	
Name 名 Wan Yin Wai		日期及還車時間 Date & Time In: 9/1/20 3pm.	
Address 地址 Blk 655 Senja Road #09-280		天數 Days @ \$	
SE. 670655		星期 Weeks @ \$	
駕駛執照 Dr/Licence No: I/C No: 81225321 B Tel No:		月 Months @ \$	
截止日期 Expiry Date	Date Of Birth	總數 Nett-Total	
Replacement Veh. Regd. No. (Diesel / Petrol)		按櫃金 Deposit	
日期及取車時間 Date & Time Out:		Refund	
日期及還車時間 Date & Time In:		Balance To Pay	
* Note: A repossession fee of S\$100.00 will be charged on repossess vehicles		Cash / Cheque	
NOTICES: ACCIDENT EXCESS: \$ 2500 22 69. NO INSURANCE COVERAGE FOR YOUNG (BELOW 22), OLD (ABOVE 69). AND IN EXPERIENCED DRIVERS. 請注意水箱及引擎油每日檢查。 Please check Radiator Water & Engine Oil daily. 半途汽油不足, 遺失鑰匙等, 若須服務者另付額外費用。 Extra charges are required for those vehicle that run out of petrol, lost of key and etc. Interest rate of 1.5% will be charged on overdue payments		出車油箱 Fuel Tank OUT E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F 加額費用 Total Additional Charges	

IMPORTANT!

I / We declare that the usage of renting the above mention Vehicle are not to be used for illegal purpose, including offences in connection with thefts, uncustomed goods, drugs dealings or trafficking or smuggling.

Signature of Hirer

I/We hereby accept the terms and conditions herein and overleaf which I have read and understood or have been read over and explain to me and understood by me. I/We hereby declare that the particulars of the Hirer and license given above are correct and that the vehicle is not disqualified from driving.

Remarks:

Signature of Hirer

承租者簽名

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20000170/Uda3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 03-03-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2588C	Veh. Inspected	GBD 9388C
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D20000168MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	03/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KDY2318017287	Colour	SILVER
Odometer	203075	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	155 R13 (D)	YOKOHAMA	6/6 mm
L/H Rear Tyre	155 R13 (D)	YOKOHAMA	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/01/2020	Inspection Date	03/01/2020
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 9388C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DISTORTED	685.90	685.90
1	FRONT BUMPER RH BRACKET	BENT	211.60	211.60
1	FRONT GRILLE	CRACKED	501.20	501.20
1	FRONT GRILLE SEAL	NECESSARY	27.40	27.40
1	RH FRONT HEADLAMP	BROKEN	995.70	995.70
1	FRONT RH CORNER PANEL	BUCKLED	265.50	265.50
1	FRONT RH DOOR	DISTORTED	1,349.30	1,349.30
1	FRONT RH DOOR HINGE	BENT	85.20	85.20
1	FRONT RH DOOR PILLAR	BADLY DENTED	392.70	392.70
1	FRONT RH STEP GARNISH	BROKEN	318.40	318.40
1	RH SIGNAL LAMP	NOT NECESSARY	43.30	-
1	DOOR CHECKER	TWISTED	127.80	127.80
1	DOOR LOWER RUBBER	TORN	185.30	185.30
1	DOOR RUBBER	TORN	186.30	186.30
1	RH DOOR TRIMBOARD	NOT NECESSARY	560.30	-
	LESS 25% DISCOUNT		-1,483.98	-1,333.08
			4,451.92	3,999.22
<u>SPECIAL NETT ITEMS</u>				
1	DOOR STICKER (SN)	NECESSARY	10.00	10.00
1	NUMBER PLATE (SN)	NOT NECESSARY	40.00	-
			50.00	10.00
<u>LABOUR</u>				
	ALIGNMENT.		80.00	60.00
	TUFF KOTE.		120.00	60.00
	TO REMOVE & REFIX WINDSCREEN TO RENEW DOOR PILLAR.		100.00	80.00
	TO REMOVE & REFIX DASHBOARD.		380.00	200.00
	SPRAY PAINTING.		1,250.00	1,000.00
	LABOUR CHARGE.		1,650.00	1,200.00

Report Ref No. CC4/FCI20000170/Uda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING CHECK.		35.00	20.00
			3,615.00	2,620.00
GRAND TOTAL			8,116.92	6,629.22
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,300.00

Report Ref No. CC4/FCI20000170/Uda3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.