

ZENITH

ZENITH ENGINEERING PTE LTD

34 Joo Koon Circle, Singapore 629060
Tel: (65) 6861 1100 Fax: (65) 6862 1948
Email: info@ze.com.sg Website: www.ze.com.sg
CO No: 197904024Z GST Reg No: M2-0037093-7

QUOTATION
NO: QU19-L1592-R00

Customer : SembWaste Pte Ltd
4543 Jalan Bukit Merah
Singapore 159470

Attn : Mr Mohamad Azman

Tel : 62723821 Fax : 62271443

Date : 30/12/19
Validity : 29/01/20
Account No : SE04
Currency : Singapore Dollar
Page : Page 1 of 1

No.	Description	Qty	UOM	Unit Price S\$	Amount S\$
1	Replacement of new binlifter Assy for RCV XD9303L , caused by accident .	1	EA	13,500.00	13,500.00 ? 11,400 .
2	Supply labour and material for the repair of RCV XD9303L as follows. removing of damaged binlifter Assy , forming & welding , fabrication of sub assembly , retrofitting new bin lifter onto the RCV and testing and painting of Binlifter assembly of affected area of repair.				

TERMS & CONDITIONS

Payment: Cash on Delivery

Validity : 30 days from the date of this quotation


LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer


Signature:

Date:



Ong Poh Kiat
Head of Service Department
68611100

bizSAFE
ST & R



Net Amount	:	13,500.00
Add 7% GST	:	945.00
Total Amount	:	14,445.00

Confirmed & Accepted By:
SembWaste Pte Ltd
Name:
Title:
Date:
Company Stamp:

Rasul
Hp 95010068
14 days ?
06/01/2020
@1650

Resurvey after
repair