

Third Party Insurer: AIG
Third Party Veh No: SKC5599K
Date of Accident: 16.12.2019

NO.	DESCRIPTION	QTY	UNIT \$	AMOUNT \$
1	REAR BUMPER	1		<i>R</i> \$608.31
2	REAR BUMPER CLIPS	8	\$5.50	<i>rw</i> \$44.00
3	REAR BUMPER REINFORCEMENT			REPAIR
			SUB TOTAL	\$652.31
			LESS 25%	-\$163.08
			PARTS TOTAL	\$489.23

12 \$250.00 X

\$250.00 2001

~ \$80.00 X

LABOUR TOTAL	\$580.00
--------------	----------

ONG	TOTAL	\$1,069.23
-----	-------	------------

Not noticed
Pain after Pain
1 day

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date:

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

