

First capital.

LKK

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE**

VEHICLE NO : SHC 1645 Y

DATE: 31/12/2019

MAKE :

TEL : 6483 6016

MODEL : HYUNDAI IONIQ

FAX : 6483 6015

Parts Description/Labour	Qty	Unit Price	Amount
FRONT BUMPER GRILLE AIR DUCT <i>Crack</i>			\$ 80.50
FRONT BUMPER COVER <i>ton</i>			\$ 418.30
FRONT BUMPER REINFORCEMENT <i>NH</i>			\$ 1,075.10
FRONT BUMPER SPONGE <i>NH</i>			\$ 86.90
FRONT BUMPER CENTRE MOULDING <i>NH</i>			\$ 188.00
FRONT BUMPER GRILLE LH <i>NH</i>			\$ 186.90
FRONT BUMPER LIP <i>NH</i>			\$ 35.10
FRONT BUMPER BRACKET TOP <i>Crack</i>			\$ 35.00
FRONT BUMPER CLIPS 10 PCS <i>NH</i>			\$ 22.00
FRONT BUMPER BRACKET LH <i>NH</i>			\$ 28.00
FRONT BUMPER SIDE BRACKET SUPPORT <i>NH</i>			\$ 12.00
FRONT FENDER LH <i>Distort</i>			\$ 490.70
FRONT FENDER SHIELD <i>NH</i>			\$ 114.70
FRONT HEADLAMP SUPPORT PANEL <i>Crack</i>			\$ 949.30
FRONT HEADLAMP LH <i>Crack</i>			\$ 1,198.80
FRONT HEADLAMP RH <i>NH</i>			\$ 1,198.80
FRONT HEADLAMP SUPPORT TOP COVER <i>NH</i>			\$ 398.00
DAY LIGHT <i>Crack mounting</i>			\$ 642.50
FRONT ENGINE UNDER COVER <i>NH</i>			\$ 469.40
FRONT WHEEL RIM LH <i>NH</i>			\$ 1,124.20
FRONT WHEEL HUB CAP LH <i>cut</i>			\$ 346.40
FRONT WHEEL BEARING <i>2 Distort</i>			\$ 454.00
FRONT SHOCK ABSORBER ASSY <i>2 Distort</i>			\$ 372.50
FRONT SHOCK ABSORBER MOUNTING <i>NH</i>			\$ 206.90
FRONT SUSPENSION LOWER ARM <i>2 Distort</i>			\$ 296.80
KNUCKLE ARM <i>2 Distort</i>			\$ 363.60
SUB-TOTAL			\$ 10,794.40
LESS 20%			\$ 2,158.88
DISCOUNTED TOTAL			\$ 8,635.52
			100.00
FRONT FENDER ADVERTISEMENT LOGO RH/LH <i>2/3 New</i>			\$ 200.00
FRONT TYRE <i>NH</i> <i>0/2 NH</i>			\$ 216.00
			\$ 416.00

NETT ✓

NETT X

Parts Description/Labour	Qty	Unit Price	Amount
LABOUR CHARGE			
PANEL BEATING			\$ 900.00 500/-
SPRAY PAINTING CHARGE			\$ 800.00 400/-
TUFF KOTE			\$ 60.00 30/-
TOWING CHARGE			\$ 80.00 40/-
REMOVE/REFIX AIRCON & REFILL GAS			\$ 120.00 40/-
FRONT WHEEL ALIGNMENT			\$ 420.00 60/-
REMOVE/REFIX UNDERCARRIAGE (FRT)			\$ 280.00 150/-
DIAGNOSE & RESETING TO ERASE FAULT CODE			\$ 480.00 180/-
TOTAL LABOUR			\$ 2,840.00
ESTIMATE TOTAL			\$ 11,891.52

06/01/2020 @ 1700hrs
 N/A Arthur
 2/5 hrs 4 days.

J Ryan

LKK Auto

8

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.